



A054FZT

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5 STR
Colour	Silver
Year of manufacture	-
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg





MOT history

MOT #22	2021-07-20 12:12
MOT test number	772621990335
Result	✓ Passed
Next expiry date	2022-07-19
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear Direction indicator slightly discoloured both sides (4.4.3 (a))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Offside Windscreen damaged but not adversely affecting driver's view crack near pillar (3.2 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

MOT #21	2021-07-19 10:58
MOT test number	322315665159
Result	✗ Failed
Fail	Offside Front Stop lamp(s) not working (4.3.1 (a) (ii))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Minor	Offside Windscreen damaged but not adversely affecting driver's view crack near pillar (3.2 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Direction indicator slightly discoloured both sides (4.4.3 (a))

**MOT #20**

2020-05-21 14:44

MOT test number

700952595521

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Child Seat fitted not allowing full inspection of adult belt To all 3 rear seats.
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #19

2019-03-20 13:48

MOT test number

524858305952

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm and wear to inner edge (5.2.3 (e))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush on arm (5.3.4 (a) (i))
- Advice** Nearside Rear Brake dirt protector is corroded.
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush on arm (5.3.4 (a) (i))
- Advice** Offside Rear Brake dirt protector is missing.



MOT #18

2019-03-20 13:48

MOT test number

653749359889

Result

✗ Failed

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush on arm (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm and wear to inner edge (5.2.3 (e))

Advice Nearside Rear Brake dirt protector is corroded.

Pass with rectification Nearside Front Headlamp aim too low and too far to the left. (4.1.2 (a))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush on arm (5.3.4 (a) (i))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Offside Rear Brake dirt protector is missing.

Pass with rectification Offside Front Headlamp aim too high and too far to the right. (4.1.2 (a))

MOT #17

2018-03-14 10:37

MOT test number

317496848141

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

Advice Items removed from driver's view prior to test Recording dash cam

Advice Front Suspension arm has slight play in a pin/bush Nearside and offside rearmost bushes (2.4.G.2)

Advice Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

**MOT #16**

2018-03-14 10:37

MOT test number

220199494527

Result**✗ Failed**

- Advice** Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
- Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)
- Pass with rectification** Headlamp aim too high nearside and offside (1.8)
- Advice** Items removed from driver's view prior to test Recording dash cam
- Advice** Front Suspension arm has slight play in a pin/bush Nearside and offside rearmost bushes (2.4.G.2)

MOT #15

2017-03-17 11:56

MOT test number

800938337311

Result**✓ Passed**

- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement REAR BUSH (2.4.G.2)
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Engine management light on

**MOT #14** 2017-03-17 11:56**MOT test number** 726760680066**Result** ✗ Failed**Advice** Engine management light on**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
REAR BUSH (2.4.G.2)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #13** 2016-03-17 15:11**MOT test number** 557492341989**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #12** 2016-03-17 15:11**MOT test number** 604545179630**Result** ✗ Failed

Advice Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #11** 2015-03-24 07:58**MOT test number** 228343585053**Result** ✓ Passed**MOT #10** 2014-10-14 15:20**MOT test number** 369397484494**Result** ✓ Passed

Notice Both front tyres worn to nothing on inside edges advise to change but boarderline for MOT so advise and pass.

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #9 2014-10-02 11:56**MOT test number** 406795674235**Result** ✗ Failed

Fail Brakes imbalanced across an axle (3.7.B.5b)

Notice Front tyres worn on edges

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

Fail Offside Rear rear parking (secondary) brake grabbing severely (3.7.B.6b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Rear rear brake recording little or no effort (3.7.B.5a)

MOT #8 2013-10-10 14:24**MOT test number** 995713183208**Result** ✓ Passed

Notice Brake pad wear indicator wire hanging down on nearside broken.

**MOT #7** 2012-10-11 10:23**MOT test number** 439515682230**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #6 2011-09-29 11:52**MOT test number** 986332471238**Result** ✓ Passed**MOT #5** 2010-10-14 15:45**MOT test number** 764197680257**Result** ✓ Passed

- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Note offside rear brake been binding/hot.

MOT #4 2010-10-07 12:09**MOT test number** 800320480267**Result** ✗ Failed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Note offside rear brake been binding/hot.
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #3	2009-10-13 16:26
MOT test number	332156889229
Result	✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear brake disc slightly pitted (3.5.1h)
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear brake disc slightly pitted (3.5.1h)

MOT #2	2008-10-01 10:28
MOT test number	442835078250
Result	✓ Passed

MOT #1	2007-10-04 12:46
MOT test number	122747077221
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<div><div></div><div>*****</div></div>
Plate since	2024-03-29
Current registration	<div><div></div><div>*****</div></div>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-10-01
Last registration	2021-07-20
Complete history	See info



Registration #1	2004-10-01	13 mi
Registration #2	2007-10-04	33.886 mi
Registration #3	2008-10-01	42.500 mi
Registration #4	2009-10-13	50.873 mi
Registration #5	2010-10-07	58.383 mi
Registration #6	2010-10-14	58.502 mi
Registration #7	2011-09-29	67.483 mi
Registration #8	2012-10-11	76.890 mi
Registration #9	2013-10-10	85.369 mi
Registration #10	2014-10-02	94.373 mi
Registration #11	2014-10-14	94.582 mi
Registration #12	2015-03-24	94.632 mi
Registration #13	2015-05-20	95.277 mi
Registration #14	2015-05-20	95.277 mi
Registration #15	2015-05-20	95.277 mi
Registration #16	2015-05-20	95.277 mi
Registration #17	2015-05-20	95.277 mi
Registration #18	2015-05-20	95.277 mi
Registration #19	2015-05-20	95.277 mi
Registration #20	2015-05-20	95.277 mi
Registration #21	2015-05-20	95.277 mi
Registration #22	2015-05-20	95.277 mi
Registration #23	2015-05-20	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	AVQ 050944