



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Grey
Year of manufacture	2011
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-29
Pictures	24
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-27
MOT pass rate	52 %
MOT passed	12
Failed MOT tests	11
Total advice items	90
Total items failed	43

MOT #23	2023-10-28 12:38
---------	------------------

MOT test number	752015805038
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-27
------------------	------------

- Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Brake pedal wearing smooth (1.1.2 (c))
- Minor

Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #22**

2023-10-10 11:36

MOT test number

693013600745

Result**✗ Failed**

Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Bald on edges (5.2.3 (e))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Rear Registration plate deteriorated but not likely to be misread Badly deteriorated (0.1 (b))

Fail Nearside Headlamp levelling device inoperative (4.1.5 (a))

Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Brake pedal wearing smooth (1.1.2 (c))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #21**

2022-10-03 12:32

MOT test number

631161779247

Result

✓ Passed

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Brake pedal wearing smooth (1.1.2 (c))

Advice

Rear coolant pipes badly corroded

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor

Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #20

2022-09-21 14:42

MOT test number

129659141125

Result

✗ Failed

Fail

Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Advice

Rear coolant pipes badly corroded

Fail

Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice

Brake pedal wearing smooth (1.1.2 (c))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail

Nearside Headlamp aim too high (4.1.2 (a))

Fail

Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor

Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail

Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #19**

2021-09-10 13:42

MOT test number

382374287727

Result

✓ Passed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** N/s/f sunvisor missing**Minor** Nearside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Corrsion on rear water**MOT #18**

2020-09-10 08:55

MOT test number

265692617266

Result

✓ Passed

Advice Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #17**

2020-09-08 14:36

MOT test number

415236508222

Result

✗ Failed

Advice Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Windscreen washer not working (3.5 (a))



MOT #162019-09-20 13:25

MOT test number508683515847

Result

✓ Passed

- Advice

Brake pedal rubber split on one corner
- Advice

Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Both rear shock absorber lower bushes deteriorated - no movement
- Advice

Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice

Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Engine oil leak from bottom of intercooler

**MOT #15**

2019-09-18 10:11

MOT test number

933093519899

Result**✗ Failed**

- Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Fail** Offside Other passenger door cannot be opened from outside the vehicle sliding (6.2.3 (a))
- Fail** Nearside Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Rear Brake pad(s) wearing thin 2-3mm approx. (1.1.13 (a) (ii))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Brake pedal rubber split on one corner
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords also worn on very outer edge - rest of tread 3mm (5.2.3 (d) (i))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively smearing (3.4 (b) (ii))
- Advice** Both rear shock absorber lower bushes deteriorated - no movement
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords also 3mm (5.2.3 (d) (i))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively smearing (3.4 (b) (ii))
- Advice** Engine oil leak from bottom of intercooler
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))



MOT #14	2018-09-19 15:06
MOT test number	922718920321
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt second row
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge smooth on very inner edge - rest of tread 5mm (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin 3-4mm approx. (1.1.13 (a) (ii))
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Slight lip to rear brake discs
Advice	Nearside Front Tyre worn close to legal limit/worn on edge smooth on very edges - rest of tread 5mm (5.2.3 (e))

**MOT #13**

2018-09-18 16:38

MOT test number

254285389583

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge smooth on very edges - rest of tread 5mm (5.2.3 (e))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively smearing (3.4 (b) (ii))
- Advice** Slight lip to rear brake discs
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge smooth on very inner edge - rest of tread 5mm (5.2.3 (e))
- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view glass shattered (3.3 (b) (ii))
- Advice** Parking brake has little reserve travel
- Advice** Rear Brake pad(s) wearing thin 3-4mm approx. (1.1.13 (a) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively smearing (3.4 (b) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt second row
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #12

2017-09-15 13:52

MOT test number

979396188262

Result**✓ Passed**

- Advice** Front brake discs lipped
- Advice** Both front wipers smearing slightly
- Advice** Child seat fitted to centre seat, middle row
- Advice** Front brake pad wear uneven - inners 3mm, outers 5mm approx.
- Advice** Brake pedal rubber starting to wear through

**MOT #11**

2017-09-15 13:52

MOT test number

600320924585

Result**✗ Failed**

- Advice** Brake pedal rubber starting to wear through
- Advice** Front brake discs lipped
- Advice** Both front wipers smearing slightly
- Advice** Child seat fitted to centre seat, middle row
- Advice** Front brake pad wear uneven - inners 3mm, outers 5mm approx.

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #10

2016-08-10 15:32

MOT test number

424913079920

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Oil leak heavy
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9** 2016-08-10 15:32**MOT test number** 735815470000**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Oil leak heavy**MOT #8** 2015-07-27 11:38**MOT test number** 158048105235**Result** ✓ Passed**Notice** Front brake discs wearing thin**MOT #7** 2015-07-27 08:48**MOT test number** 127068905237**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Front brake discs wearing thin**Fail** Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2015-04-20 11:28**MOT test number** 489810715175**Result** ✓ Passed

**MOT #5** 2015-04-04 11:58**MOT test number** 488644095097**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Engine oil level low**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-07-11 08:28**MOT test number** 986392894181**Result** ✓ Passed**MOT #3** 2014-07-11 08:28**MOT test number** 275282894191**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #2** 2014-03-26 12:25**MOT test number** 196645684054**Result** ✓ Passed**MOT #1** 2014-03-26 08:50**MOT test number** 179335584461**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)



Tax & MOT check

X

Untaxed

Tax expired:
1 January 2024

✓

MOT

Expires:
27 October 2024

Tax status	Expired at 1 January 2024
Days left	120 days too late
MOT expiry date	27 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	OV11FVF
Plate since	2019-03-29
Current registration	OV11FVF
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2011-03-30
Last registration	2023-10-28
Complete history	See info



Registration #1	2011-03-30	7 mi
Registration #2	2014-03-26	26.932 mi
Registration #3	2014-03-26	26.933 mi
Registration #4	2014-07-11	33.774 mi
Registration #5	2015-04-04	45.025 mi
Registration #6	2015-04-20	45.060 mi
Registration #7	2015-07-27	47.845 mi
Registration #8	2015-07-27	47.845 mi
Registration #9	2016-08-10	57.429 mi
Registration #10	2016-08-10	57.429 mi
Registration #11	2017-09-15	68.089 mi
Registration #12	2017-09-15	68.089 mi
Registration #13	2018-09-20	75.277 mi
Registration #14	2018-09-20	75.277 mi
Registration #15	2019-09-20	75.277 mi
Registration #16	2019-09-20	75.277 mi
Registration #17	2019-09-20	75.277 mi
Registration #18	2019-09-20	75.277 mi
Registration #19	2019-09-20	75.277 mi
Registration #20	2019-09-20	75.277 mi
Registration #21	2019-09-20	75.277 mi
Registration #22	2019-09-20	75.277 mi
Registration #23	2019-09-20	75.277 mi
Registration #24	2019-09-20	75.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Number of axles	2
Engine number	D4CBA743034