



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 2.300 rpm
Engine capacity	1.686 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-29
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-06-20
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	30
Total items failed	7

MOT #14 2021-06-09 15:20

MOT test number 762070380892

Result ✓ Passed

Next expiry date 2022-06-20

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))

Minor Front Drive shaft joint constant velocity boot severely deteriorated both (6.1.7 (g) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13 2020-06-21 12:56

MOT test number 397884936690

Result ✓ Passed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2020-06-21 12:56

MOT test number

377095587470

Result**✗ Failed**

- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Pass with rectification** Front Windscreen washer not working (3.5 (a))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #11

2019-06-18 14:55

MOT test number

693540716140

Result**✓ Passed**

- Advice** Offside body panel damage not effecting any structure or sharp edge
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #10

2018-06-27 17:15

MOT test number

100158236644

Result**✓ Passed**

- Advice** Both wing mirrors secured with tape
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #9** 2017-06-14 16:19**MOT test number** 508535839660**Result** Passed**MOT #8** 2017-06-14 14:09**MOT test number** 552261838772**Result** Failed**Fail** Rear Lower engine mounting deteriorated resulting in excessive movement (6.1.D.1a)**Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Fail** Rear Lower engine mounting bracket insecure and likely to fail (6.1.D.1b)**MOT #7** 2016-07-12 15:14**MOT test number** 620284315142**Result** Passed**Advice** Offside Front Lower Tie bar/rod has slight play in a ball joint (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #6** 2015-07-14 16:10**MOT test number** 927175095166**Result** Passed

**MOT #5** 2014-07-03 16:46**MOT test number** 809234184175**Result** ✗ Failed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #4** 2014-07-03 16:46**MOT test number** 226024084431**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #3** 2013-07-12 15:21**MOT test number** 249623293110**Result** ✓ Passed**Notice** Brake pedal rubber slightly worn**MOT #2** 2012-07-03 14:16**MOT test number** 216625482453**Result** ✓ Passed



MOT #1	2012-07-02 16:35
MOT test number	306594282184
Result	✗ Failed
Fail	Offside Rear Rear position lamp(s) incorrect colour (1.1.A.3e)



Tax & MOT check

✕
Untaxed

Tax expired:
4 September 2022

✕
MOT

Expired:
20 June 2022

Tax status	Expired at 4 September
Days left	604 days too late
MOT expiry date	20 June 2022
Full MOT history	See MOT history




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	BD09WXJ
Plate since	2024-03-29
Current registration	BD09WXJ
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-07-20
Last registration	2021-06-09
Complete history	See info



Registration #1	2009-07-20	25 mi
Registration #2	2012-07-02	92.516 mi
Registration #3	2012-07-03	92.693 mi
Registration #4	2013-07-12	105.639 mi
Registration #5	2014-07-03	113.018 mi
Registration #6	2015-07-14	121.044 mi
Registration #7	2016-07-12	130.063 mi
Registration #8	2017-06-14	135.761 mi
Registration #9	2019-06-09	25,000 (approx.)
Registration #10	2019-06-09	25,000 (approx.)
Registration #11	2019-06-09	25,000 (approx.)
Registration #12	2019-06-09	25,000 (approx.)
Registration #13	2019-06-09	25,000 (approx.)
Registration #14	2019-06-09	25,000 (approx.)
Registration #15	2019-06-09	25,000 (approx.)

More info >



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1453 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	1953149