



Mercedes-Benz



BT6IAUN

report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	SPRINTER 313 CDI
Colour	White
Year of manufacture	2011
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-03-12
Pictures	3
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



MOT history

MOT expiry date	2024-05-10
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	62
Total items failed	31

MOT #17	2023-05-11 13:15
MOT test number	718364336605
Result	✓ Passed
Next expiry date	2024-05-10
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #16**

2023-05-10 09:07

**MOT test number**

302786721235

**Result****✗ Failed**

- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Offside Rear fog lamp lens defective such that emitted light is adversely affected showing white light (4.5.1 (b) (ii))
- Advice** Offside marker lamp not working
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
- Advice** Nearside marker lamp not working
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15**

2022-05-07 12:27

**MOT test number**

823058026046

**Result**

✓ Passed

- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front shock absorber dust covers missing both
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Wipers smearing
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear shock absorber dust cover corroded and broken

**MOT #14**

2022-05-06 13:14

**MOT test number**

843395521767

**Result****✗ Failed**

- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Wipers smearing
- Fail** Nearside Side repeater incorrect colour (4.4.3 (a))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear shock absorber dust cover corroded and broken
- Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))
- Advice** Nearside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Front Body component damaged and likely to cause injury grille (6.2.1 (a) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Rear fog lamp not working (4.5.1 (a) (ii))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front shock absorber dust covers missing both
- Fail** Offside Side repeater incorrect colour (4.4.3 (a))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #13** 2021-04-20 15:37**MOT test number** 817499861300**Result** ✓ Passed**MOT #12** 2021-04-19 13:43**MOT test number** 479347387415**Result** ✗ Failed**Advice** Front to rear brake pipes corroding**Advice** Front Play in steering rack inner joint(s) nearside and offside**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Front Inner Tyre worn close to legal limit/worn on edge nearside and offside (5.2.3 (e))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #11** 2020-11-05 13:26**MOT test number** 911914570036**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Play in steering rack inner joint(s)

**MOT #10**

2020-11-04 12:57

**MOT test number**

924686452444

**Result****✗ Failed****Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Rear Tyre tread depth below requirements of 1.6mm Both (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Play in steering rack inner joint(s)**MOT #9**

2019-07-04 15:10

**MOT test number**

479188045613

**Result****✓ Passed****MOT #8**

2018-09-11 15:30

**MOT test number**

683655974210

**Result****✓ Passed****MOT #7**

2018-09-07 09:25

**MOT test number**

964352477045

**Result****✗ Failed****Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Fail** Offside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))**Fail** Nearside Side repeater missing (4.4.1 (a) (ii))**Fail** Central Outline marker lamp not working (4.2.1 (a))





<b>MOT #6</b>	2017-09-08 13:00
<b>MOT test number</b>	678323609860
<b>Result</b>	✓ Passed
<b>Advice</b>	Parking brake lever has little reserve travel (3.1.6b)

<b>MOT #5</b>	2017-09-06 08:10
<b>MOT test number</b>	160917631567
<b>Result</b>	✗ Failed
<b>Fail</b>	Supplementary Restraint System warning lamp indicates a fault (5.4.2)
<b>Fail</b>	Offside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
<b>Fail</b>	Offside Rear Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)
<b>Fail</b>	Nearside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
<b>Fail</b>	Nearside Rear Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)
<b>Advice</b>	Parking brake lever has little reserve travel (3.1.6b)

<b>MOT #4</b>	2016-09-07 08:10
<b>MOT test number</b>	278590836123
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
<b>Advice</b>	Parking brake lever has little reserve travel (3.1.6b)
<b>Advice</b>	Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)



MOT #3	2016-09-07 08:10
MOT test number	885965991666
Result	✗ Failed
Advice	Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
Pass with rectification	Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)

MOT #2	2015-09-22 15:21
MOT test number	832054921343
Result	✓ Passed

MOT #1	2014-11-20 07:43
MOT test number	647814224396
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
10 May 2024

Tax status	Valid until 1 April
------------	---------------------

Days left	336
-----------	-----

MOT expiry date	10 May 2024
-----------------	-------------

Full MOT history	<a href="#">See MOT history</a>
------------------	---------------------------------



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	<b>BT61AUN</b>
Plate since	2019-03-29
Current registration	<b>BT61AUN</b>
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-12-14
Last registration	2023-05-11
Complete history	<a href="#">See info</a>



Registration #1	2011-12-14	21 mi
Registration #2	2014-11-20	62.361 mi
Registration #3	2015-09-22	70.504 mi
Registration #4	2016-09-07	85.956 mi
Registration #5	2016-09-07	85.956 mi
Registration #6	2017-09-06	101.104 mi
Registration #7	2017-09-08	101.104 mi
Registration #8	2018-09-07	113.755 mi
Registration #9	2018-09-11	113.882 mi
Registration #10	2019-07-04	125.664 mi
Registration #11	2019-09-20	137.517 mi
Registration #12	2019-09-20	137.517 mi
Registration #13	2019-09-20	137.517 mi
Registration #14	2019-09-20	137.517 mi
Registration #15	2019-09-20	137.517 mi
Registration #16	2019-09-20	137.517 mi
Registration #17	2019-09-20	137.517 mi
Registration #18	2019-09-20	137.517 mi
Registration #19	2019-09-20	137.517 mi

More info >





Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	65195530724960