



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	ACCENT GSI LIMITED EDITION
Colour	Blue
Year of manufacture	-
Top speed	110 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg






Internet history

Entry 1

Date	2021-09-08
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #20	2022-09-20 16:36
MOT test number	671521670142
Result	✓ Passed
Next expiry date	2023-09-19
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Offside Windscreen wiper blade defective ends split (3.4 (b) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #19	2022-09-16 13:52
MOT test number	272591334134
Result	✗ Failed
MAJOR	Front Bumper insecure (6.1.4 (a) (i))
Minor	Offside Windscreen wiper blade defective ends split (3.4 (b) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
MAJOR	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #18**

2021-09-06 12:17

MOT test number

140183659582

Result

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive Sump corroded (8.4.1 (a) (i))
- Minor** Headlamp lens slightly defective Both lenses cloudy, starting to affect beam pattern (4.1.1 (b) (i))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Stop lamp(s) non-obligatory stop lamp not working Hi-Level (4.3.1 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Obligatory mirror slightly loose Both outer mirrors (3.3 (b) (i))

MOT #17

2021-08-31 11:52

MOT test number

855921805522

Result

✗ Failed

- Advice** Oil leak, but not excessive Sump corroded (8.4.1 (a) (i))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Headlamp lens slightly defective Both lenses cloudy, starting to affect beam pattern (4.1.1 (b) (i))
- Advice** Stop lamp(s) non-obligatory stop lamp not working Hi-Level (4.3.1 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Power steering malfunctioning Pump drive belt slipping badly (2.1.5 (a))
- Minor** Obligatory mirror slightly loose Both outer mirrors (3.3 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #16**

2020-08-25 08:09

MOT test number

734039703255

Result

✓ Passed

- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive Sump corroded / leaking (8.4.1 (a) (i))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Stop lamp(s) non-obligatory stop lamp not working High-Level (4.3.1 (a) (ii))

MOT #15

2019-08-30 08:54

MOT test number

996223633748

Result

✓ Passed

- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm front bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Stop lamp(s) non-obligatory stop lamp not working High - Level (4.3.1 (a) (ii))

MOT #14

2019-08-30 08:54

MOT test number

584066384851

Result

✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Stop lamp(s) non-obligatory stop lamp not working High - Level (4.3.1 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm front bush (5.3.4 (a) (i))

**MOT #13** 2018-09-08 18:10**MOT test number** 592453041887**Result** ✓ Passed**MOT #12** 2018-09-08 18:10**MOT test number** 835407772357**Result** ✗ Failed**Pass with rectification** Stop lamp(s) all not working (4.3.1 (a) (iii))**MOT #11** 2017-09-07 16:32**MOT test number** 587318386809**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #10** 2016-08-27 15:21**MOT test number** 381365472474**Result** ✓ Passed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #9** 2016-08-27 14:40**MOT test number** 220810829703**Result** ✗ Failed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #8** 2015-08-29 16:54**MOT test number** 549171945212**Result** ✓ Passed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #7** 2015-08-29 16:54**MOT test number** 358101145488**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Driver's seat fore and aft adjustment mechanism not functioning as intended.
(6.2.A.3)**MOT #6** 2014-08-18 11:14**MOT test number** 466510234201**Result** ✓ Passed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #5** 2013-07-29 09:26**MOT test number** 697550613279**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2012-07-30 11:19**MOT test number** 716162712258**Result** ✓ Passed**Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Offside rear light outer lense cracked but not affecting light output**MOT #3** 2011-08-01 14:49**MOT test number** 375073311475**Result** ✓ Passed**MOT #2** 2010-07-31 13:50**MOT test number** 344912110270**Result** ✓ Passed**Notice** Damage to o/s/r light unit**MOT #1** 2009-07-28 14:12**MOT test number** 524099809226**Result** ✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-07-31
Last registration	2022-09-20
Complete history	See info



Registration #1	2006-07-31	21 mi
Registration #2	2009-07-28	11.559 mi
Registration #3	2010-07-31	22.282 mi
Registration #4	2011-08-01	32.909 mi
Registration #5	2012-07-30	43.104 mi
Registration #6	2013-07-29	53.753 mi
Registration #7	2014-08-18	63.740 mi
Registration #8	2015-08-29	70.287 mi
Registration #9	2016-08-27	76.685 mi
Registration #10	2016-08-27	76.685 mi
Registration #11	2017-09-07	83.310 mi
Registration #12	2018-09-20	91.377 mi
Registration #13	2019-09-20	99.377 mi
Registration #14	2020-09-20	107.377 mi
Registration #15	2021-09-20	115.377 mi
Registration #16	2022-09-20	123.377 mi
Registration #17	2023-09-20	131.377 mi
Registration #18	2024-09-20	139.377 mi
Registration #19	2025-09-20	147.377 mi
Registration #20	2026-09-20	155.377 mi
Registration #21	2027-09-20	163.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	4045 mm
Wheel base	2500 mm
Kerb weight	1246 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	G4EE6528417