



Mercedes-Benz

HU03MPO

report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	SPRINTER 313 CDI
Colour	White
Year of manufacture	2011
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-04
Pictures	2
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-12-16
-----------------	------------

MOT pass rate	82 %
---------------	------

MOT passed	9
------------	---

Failed MOT tests	2
------------------	---

Total advice items	29
--------------------	----

Total items failed	29
--------------------	----

MOT #11	2022-11-28 15:52
---------	------------------

MOT test number	111444112849
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-12-16
------------------	------------

Advice	Rear Side repeater rear of vehicle intermittent
--------	---

Minor	Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
-------	--

Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
--------	--

MOT #10	2021-12-17 16:33
---------	------------------

MOT test number	715502167178
-----------------	--------------

Result	✓ Passed
--------	----------

Advice	Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
--------	--

Advice	Front flexi exhaust deteriorated
--------	----------------------------------

Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
-------	--

Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
--------	--

Advice	Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
--------	---

**MOT #9**

2021-12-13 15:16

MOT test number

147151007987

Result**✗ Failed**

- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Nearside Headlamp light intensity severely reduced (4.1.4 (a))
- Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Nearside Windscreen wiper blade missing (3.4 (b) (ii))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Drag link end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Prop shaft bearing excessively worn centre (6.1.7 (b) (i))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Shock absorbers damaged to the extent that it does not function (5.3.2 (b))
- Fail** Nearside Upper Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Fail** Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Nearside Rear Reversing lamp inoperative (4.6.1 (a))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))
- Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Drag link end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

Fail Offside Headlamp aim too high (4.1.2 (a))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front flexi exhaust deteriorated

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8** 2020-11-28 12:53**MOT test number** 375285109819**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Inner Suspension rod ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Inner Suspension rod ball joint has slight play (5.3.4 (a) (i))**MOT #7** 2019-11-15 14:12**MOT test number** 571896061960**Result** ✓ Passed**MOT #6** 2018-12-07 17:21**MOT test number** 932364268852**Result** ✓ Passed**MOT #5** 2018-12-07 17:21**MOT test number** 617752272575**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #4** 2017-12-08 18:02**MOT test number** 869072993809**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3**

2016-12-10 11:46

MOT test number

828376231048

Result

✓ Passed

Advice Nearside Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Damage to screen but does not effect view of the road

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2

2015-11-17 17:21

MOT test number

823082399426

Result

✓ Passed

Advice Nearside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1

2014-09-03 16:25

MOT test number

949466144290

Result

✓ Passed

Notice Vehicle's internal headlight adjuster altered to recheck lights

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✕
Untaxed

Tax expired:
1 October 2022

✕
MOT

Expired:
16 December 2023

Tax status

Expired at 1 October 2022

Days left

577 days too late

MOT expiry date

16 December 2023

Full MOT history

[See MOT history](#)



Damage history


Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-05-20
Last registration	2022-11-28
Complete history	See info



Registration #1	2011-05-20	25 mi
Registration #2	2014-09-03	134.537 mi
Registration #3	2015-11-17	155.812 mi
Registration #4	2016-12-10	162.880 mi
Registration #5	2017-12-08	188.567 mi
Registration #6	2018-12-07	188.882 mi
Registration #7	2018-12-07	188.882 mi
Registration #8	2019-05-20	201.277 mi
Registration #9	2019-05-20	201.277 mi
Registration #10	2019-05-20	201.277 mi
Registration #11	2019-05-20	201.277 mi
Registration #12	2019-05-20	201.277 mi
Registration #13	2019-05-20	201.277 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	65195530724960