





General information

Make	AUDI
Model	A3 TDI SPORT SPECIAL EDITION
Colour	Silver
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С







2021-01-27
1
View report



source: autoonline.co.uk



MOT history

MOT expiry date	2023-12-16	
MOT pass rate	75 %	
MOT passed	12	
Failed MOT tests	4	
Total advice items	57	
Total items failed	13	

MOT #16	2022-12-16 15:40
MOT test number	898257566275
Result	✓ Passed
Next expiry date	2023-12-16
Advice Nearside Front Tyre worn close to legal limit/worn on edge Tyre startin (5.2.3 (e))	ng to wear on outer edge
Advice Chip in front screen	

MOT #15	2021-12-17 09:56
MOT test number	778102772414
Result	✓ Passed
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #14		2021-02-11 17:07
MOT test	number	346655657465
Result		✓ Passed
Advice	Offside Rear shock absorber dirt shield is insecure	
Advice	Nearside Rear shock absorber dirt shield is insecure	



MOT #13	2021-02-09 12:48
MOT test number	816141500428
Result	🗙 Failed
Advice Offside Rear shock absorber dirt shield is insecure	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
FailNearside Front Suspension arm ball joint dust cover no longer prevents the ing(ii))	gress of dirt (5.3.4 (b)
Minor Offside Rear Tyre obviously under inflated (5.2.3 (I))	
Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Nearside Rear shock absorber dirt shield is insecure	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3	3.4 (b) (i))

MOT #12		2020-01-09 17:04
MOT test	number	267304075677
Result		✓ Passed
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice (5.3.4 (a)	Offside Front Suspension arm pin or bush worn but not resulting in exce (i))	essive movement rear bush
Advice	Offside Rear shock absorber dirt shield is partially insecure	
Advice (d) (ii))	Offside Rear Tyre slightly damaged/cracking or perishing perishing alon	g the tread grooves (5.2.3
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))	
Advice bush (5.3	Nearside Front Suspension arm pin or bush worn but not resulting in exe .4 (a) (i))	cessive movement rear
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice (5.2.3 (d)	Nearside Rear Tyre slightly damaged/cracking or perishing perishing alc (ii))	ong the tread grooves



MOT #11 2020-01-09 16:00
MOT test number 988677812204
Result × Failed
Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Fail Offside Headlamp aim too far to the left (4.1.2 (a))
Advice Oil leak, but not excessive engine (8.4.1 (a) (i))
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice Offside Rear Tyre slightly damaged/cracking or perishing perishing along the tread grooves (5.2.3 (d) (ii))
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Fail Nearside Headlamp aim too far to the right (4.1.2 (a))
Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Advice Nearside Rear Tyre slightly damaged/cracking or perishing perishing along the tread grooves (5.2.3 (d) (ii))
Advice Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice Offside Rear shock absorber dirt shield is partially insecure
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))



MOT #10		2019-01-02 12:59
MOT test	number	313831352283
Result		✓ Passed
Advice	Offside Play in steering rack inner joint(s)	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear shock absorber dirt shield is partially insecure	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive	e movement (5.3.4 (a)
Advice	Nearside Play in steering rack inner joint(s)	
Minor	Central Windscreen damaged but not adversely affecting driver's view (3.2 (a	a) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside headlamp lens full of moisture	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excession	ve movement (5.3.4

WR58OUF

report date: 2024-03-28



MOT #9 2018-	12-20 11:40
MOT test number 217	642059765
Result	🗙 Failed
Advice Offside Play in steering rack inner joint(s)	
Fail (ii))Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt	(5.3.4 (b)
Minor Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Fail Offside Rear Service brake excessively binding (1.2.1 (f))	
Advice Offside Rear shock absorber dirt shield is partially insecure	
Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Play in steering rack inner joint(s)	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movemen (i))	t (5.3.4 (a)
Fail Nearside Rear Service brake excessively binding (1.2.1 (f))	
Advice Offside headlamp lens full of moisture	
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movemer (a) (i))	ent (5.3.4

MOT #8	2018-02-23 16:	06
MOT test	number 7255843362	07
Result	✓ Pass	ed
Advice	O/s/r shock absorber top dust gard insecure.	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' $(8.3.1d)$	



W	R580UI	
r	eport date: 2024-03-	28

MOT #7		2018-02-23 11:02
MOT test I	number	724503924101
Result		🗙 Failed
Advice	O/s/r shock absorber top dust gard insecure.	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		
Fail Of	fside Headlamp aim beam image obviously incorrect (1.8.A.1b)	

MOT #6		2017-02-27 16:35
MOT test	number	325598080152
Result		✓ Passed
Advice	Tyre worn close to the legal limit both front tyres worn on outer edges $\&$ (4.1.E.1)	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1	Ld)

MOT #5		2016-03-01 10:13
MOT test	number	760862651050
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8	.3.1d)
Advice	Front tyres worn slightly on outer edges	

MOT #4	2015-02-27 10:12
MOT test number	275608255075
Result	✓ Passed
MOT #3	2014-03-01 09:57

MOT test number	997020264038
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	





MOT #2	2013-02-01 14:35
MOT test number	485142733038
Result	✓ Passed
MOT #1	2011-11-25 11:09
MOT test number	206849321335
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 6 June 2022	X MOT Expired: 16 December 2023
Tax status	Expired at 6 June 2022
Days left	692 days too late
MOT expiry date	16 December 2023
Full MOT history	See MOT history
Tax calculation	
Vehicle class	49

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT D
Date	*
Category	AMP
Туре	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	UK (





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-12-02
Last registration	2022-12-16
Complete history	See info



Registration #1	2008-12-02	18 mi
Registration #2	2011-11-25	43.639 mi
Registration #3	2013-02-01	49.151 mi
Registration #4	2014-03-01	58.064 mi
Registration #5	2015-02-27	69.618 mi
Registration #6	2016-03-01	82.979 mi
Registration #7	2017-02-27	93.854 mi
Registration #8	2018-02-23	100.457 mi
Registration #9	2018-02-23	100.457 mi
Registration #10		11.117 est
Registration #11		11.777 esi
Registration #12		11.777 est
Registration #13		11.707 est
Registration #14		11.777 esi
Registration #15		11.707 esi
Registration #16		11.117 esi
Registration #17		11.777 esi
Registration #18		10.317 mil





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
S0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1957 mm
Height	1423 mm
Length	4286 mm
Wheel base	2578 mm
Max. allowed weight	1880 kg
Additional information	
Fuel tank capacity	55
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 16/1

Engine number

BLS 673127