



Mercedes-Benz

YH59JKE

report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	SPRINTER 313 CDI LWB C/C
Colour	Yellow
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2021-10-17
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	47
Total items failed	12

MOT #11 2020-10-15 16:41

MOT test number 365545870308

Result ✓ Passed

Next expiry date 2021-10-17

- Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement n/s & o/s (5.3.4 (a) (i))

MOT #10 2019-10-18 09:39

MOT test number 261063141545

Result ✓ Passed

- Advice** Front Play in steering rack inner joint(s) n/s & o/s
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement n/s & o/s (5.3.4 (a) (i))



MOT #9	2018-10-18 10:18
MOT test number	908780536891
Result	✓ Passed
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement n/s & o/s (5.3.4 (a) (i))

MOT #8	2017-12-13 16:29
MOT test number	976710898175
Result	✓ Passed
Advice	Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
Advice	Slight play noticed in o/s/f steering rack arm
Advice	Slight play noticed in n/s/f shock absorber

MOT #7	2016-12-16 09:32
MOT test number	997054226297
Result	✓ Passed
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
Advice	Play in steering rack inner joint(s)
Advice	Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. n/s & o/s (3.7.B.6b)
Advice	Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #6	2015-11-09 16:44
MOT test number	423480550760
Result	✓ Passed
Advice	Nearside Front steering rack end has slight play
Advice	Offside Front steering rack end has slight play

**MOT #5**

2015-11-07 10:02

MOT test number

335203428105

Result**✗ Failed**

- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside Front steering rack end has slight play
- Fail** Offside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Fail** Nearside Front Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Rear Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Advice** Offside Front steering rack end has slight play
- Fail** Offside Front Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Rear Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

MOT #4

2014-11-17 14:20

MOT test number

828311324307

Result**✓ Passed**

- Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Steering system has slight free play detected at steering wheel (2.2.A.1b)
- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #3

2013-11-02 12:24

MOT test number

438846703412

Result

✓ Passed

- Advice

Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice

Items removed from driver's view prior to test
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Front brake fluctuating, but not excessively (3.7.B.3)
- Advice

Brake pad(s) wearing thin (3.5.1g)
- Notice

Slight knocking when working steering,possible universal joint advise further inspection
- Advice

Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Notice

Nail in nearside rear tyre
- Advice

Parking brake lever has little reserve travel (3.1.6b)

**MOT #2**

2013-11-02 09:01

MOT test number

225446003392

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Items removed from driver's view prior to test
- Fail** Offside Rear Direction indicator not working (1.4.A.2c)
- Advice** Front brake fluctuating, but not excessively (3.7.B.3)
- Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Brake pad(s) wearing thin (3.5.1g)
- Advice** Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Notice** Slight knocking when working steering, possible universal joint advise further inspection
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Notice** Nail in nearside rear tyre
- Fail** Offside Front Direction indicator incorrect colour (1.4.A.2f)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #1

2012-11-10 11:18

MOT test number

808535712308

Result**✓ Passed**

- Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✕
Untaxed

Tax expired:
10 February 2021

✕
MOT

Expired:
17 October 2021

Tax status

Expired at 10 February 2021

Days left

1174 days too late

MOT expiry date

17 October 2021

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	YH59JKE
Plate since	2019-03-28
Current registration	YH59JKE
Plate since	2019-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-11-24
Last registration	2020-10-15
Complete history	See info



Registration #1	2009-11-24	20 mi
Registration #2	2012-11-10	76.489 mi
Registration #3	2013-11-02	108.161 mi
Registration #4	2013-11-02	108.162 mi
Registration #5	2014-11-17	163.139 mi
Registration #6	2015-11-07	202.514 mi
Registration #7	2016-11-02	251.277 mi
Registration #8	2017-11-02	251.277 mi
Registration #9	2018-11-02	251.277 mi
Registration #10	2019-11-02	251.277 mi
Registration #11	2020-10-15	251.277 mi
Registration #12	2020-10-15	251.277 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	7
Engine number	65195530126535