



Mercedes-Benz

VI9SSK

report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	ML ML430
Colour	Silver
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	400 Nm at 3.000 rpm
Cylinders	8
Fuel type	Petrol
Consumption city	18.6 mpg
Consumption extra urban	25.2 mpg
Consumption combined	20.6 mpg





Internet history

Entry 1

Date	2021-07-27
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #27	2020-09-29 13:20
MOT test number	323261800391
Result	✓ Passed
Next expiry date	2021-10-28
Advice	Brake servo damaged but function not impaired (1.1.3 (e))

MOT #26	2019-10-29 14:44
MOT test number	506281738327
Result	✓ Passed

MOT #25	2019-10-26 12:32
MOT test number	926146074915
Result	✗ Failed
Fail	Brake servo defective or ineffective (1.1.10 (a) (i))
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #24**

2019-10-23 10:06

MOT test number

714965135434

Result**✗ Failed**

- Fail** Nearside Headlamp aim too high and too far to the right. (4.1.2 (a))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Steering system excessively rough (2.1.1 (a))
- Fail** Brake servo defective or ineffective (1.1.10 (a) (i))
- Fail** Offside Headlamp aim too high and too far to the right. (4.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #23

2018-10-16 14:48

MOT test number

626017596394

Result**✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Side repeater insecure (4.4.1 (c) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #22**

2018-10-11 10:57

MOT test number

372354694674

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Side repeater incorrect colour (4.4.3 (a))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Side repeater incorrect colour (4.4.3 (a))
- Minor** Nearside Side repeater insecure (4.4.1 (c) (i))
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Non obligatory mirror damaged
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #21

2017-10-16 10:41

MOT test number

131025407887

Result**✓ Passed**

- Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**MOT #20** 2016-10-13 14:44**MOT test number** 771456674179**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Centre Rear Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**MOT #19** 2016-10-13 14:44**MOT test number** 105758988951**Result** ✗ Failed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Centre Rear Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**MOT #18** 2015-10-22 13:13**MOT test number** 570886626848**Result** ✓ Passed**Advice** N/s/front tyre low tread on inner edge

**MOT #17**

2015-10-14 12:11

MOT test number

342452025979

Result**✗ Failed****Fail** Nearside Rear coil spring broken (2.4.C.1a)**Advice** Rear parking brake test just passed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** N/s/front tyre low tread on inner edge**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Fail** Nearside Front Anti-roll bar rubber bush bonding deteriorated resulting in excessive movement anti roll bar to body bracket bush (2.4.G.2)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Offside Rear Lower Suspension arm has excessive play in a ball joint wishbone to rear hub ball joint (2.4.G.2)**Advice** ETS light illuminated**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Advice** N/s/rear tyre low tread on inner edge and on wear bars.**MOT #16**

2014-10-03 11:18

MOT test number

219666974233

Result**✓ Passed****Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre

**MOT #15**

2013-10-18 12:53

MOT test number

698551493268

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Oil leak

MOT #14

2013-10-12 11:33

MOT test number

977085583293

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** N/s/ kat rattle ,,,,oil leak auto fluid
- Fail** Offside Headlamp aim too low (1.8)
- Fail** Offside Upper Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)
- Notice** O/s/ steering rack arm movement in joint
- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)

**MOT #13**

2012-09-15 12:06

MOT test number

246689452222

Result

✓ Passed

- Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Offside Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #12

2012-09-15 12:06

MOT test number

917929752285

Result

✗ Failed

- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Offside Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11**

2011-09-26 14:31

MOT test number

689539061272

Result

✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Suspension joint offside upper dust cover split/missing**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #10**

2011-09-17 10:04

MOT test number

475170761275

Result

✗ Failed

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Suspension joint offside upper dust cover split/missing**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #9**

2010-11-10 15:48

MOT test number

261664010301

Result

✓ Passed

**MOT #8** 2010-11-10 10:47**MOT test number** 860834310379**Result** ✗ Failed

- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Front Brake hose excessively chafed (3.6.B.4d)
- Fail** All position lamps adversely affected by the operation of another lamp (1.1.A.3f)
- Fail** Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #7 2010-11-06 11:37**MOT test number** 544930410318**Result** ✗ Failed

- Fail** Nearside Front Brake pipe inadequately supported (3.6.B.1)
- Notice** Slight movement in os front wheel
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Front position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Front position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

MOT #6 2009-11-11 12:08**MOT test number** 561775419300**Result** ✓ Passed

**MOT #5** 2009-11-11 12:08**MOT test number** 791825619367**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Registration plate lamp not working (1.1.5c)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2008-07-09 13:05**MOT test number** 313441398127**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Heavey damage to nearside rear tyre side wall**MOT #3** 2008-07-08 16:54**MOT test number** 252480298413**Result** ✗ Failed**Notice** Heavy damage to offside front tyre side wall**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Heavey damage to nearside rear tyre side wall**MOT #2** 2007-09-14 15:38**MOT test number** 321277557463**Result** ✓ Passed



MOT #1

2007-09-11 15:49

MOT test number

833494057290

Result

✗ Failed

Advice

Front Direction indicator slightly discoloured (1.4.A.2f)

Fail

Rear Direction indicator incorrect colour (1.4.A.2f)

Fail

Nearside Front Body has a sharp edge caused by damage (6.1.C.1)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Fail

Nearside Headlamp aim too low (1.8)

Fail

Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 V19SSK
Plate since	2019-03-28
Current registration	 V19SSK
Plate since	2019-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2000-01-01
Last registration	2020-09-29
Complete history	See info



Registration #1	2000-01-01	19 mi
Registration #2	2007-09-11	42.331 mi
Registration #3	2007-09-14	42.331 mi
Registration #4	2008-07-08	44.116 mi
Registration #5	2008-07-09	44.126 mi
Registration #6	2009-11-11	44.980 mi
Registration #7	2010-11-06	54.481 mi
Registration #8	2010-11-10	54.635 mi
Registration #9	2010-11-10	54.635 mi
Registration #10	2011-09-17	62.302 mi
Registration #11	2011-09-26	62.581 mi
Registration #12	2012-09-15	71.529 mi
Registration #13	2013-10-12	80.511 mi
Registration #14	2013-10-18	80.658 mi
Registration #15	2014-01-01	81.000 mi
Registration #16	2014-01-01	81.000 mi
Registration #17	2014-01-01	81.000 mi
Registration #18	2014-01-01	81.000 mi
Registration #19	2014-01-01	81.000 mi
Registration #20	2014-01-01	81.000 mi
Registration #21	2014-01-01	81.000 mi
Registration #22	2014-01-01	81.000 mi
Registration #23	2014-01-01	81.000 mi
Registration #24	2014-01-01	81.000 mi
Registration #25	2014-01-01	81.000 mi
Registration #26	2014-01-01	81.000 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	11394230109433