



Mercedes-Benz

YD58GME

report date: 2024-03-29

General information

Make	MERCEDES
Model	SPRINTER 311 CDI LWB CC
Colour	White
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.600 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-03-02
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	72
Total items failed	29

MOT #16 2023-03-03 14:26

MOT test number 905912610940

Result ✓ Passed

Next expiry date 2024-03-02

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Underbody general corrosion

MOT #15 2023-02-15 14:11

MOT test number 754093916062

Result ✗ Failed

- Advice** Front Brake pipe corroded, covered in grease or other material To rear (1.1.11 (c))
- Advice** Underbody general corrosion
- Fail** Front Prop shaft bearing excessively worn (6.1.7 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Central Prop shaft bearing excessively worn (6.1.7 (b) (i))

**MOT #14**

2019-10-31 16:56

MOT test number

159096839044

Result

✓ Passed

- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both sides (n/s and o/s) (5.3.4 (a) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced general corrosion under vehicle (6.1.1 (c) (i))
- Advice** 3 x prop shaft universal joints have slight play
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** 2 x prop shaft mounting bearings are worn
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

2018-10-29 14:03

MOT test number

262585742173

Result

✓ Passed

**MOT #12** 2018-10-27 15:36**MOT test number** 451438936454**Result** ✗ Failed

- Fail** Emissions not tested (8.2.1.2 (d))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a))

MOT #11 2017-10-12 14:38**MOT test number** 208517113680**Result** ✓ Passed**MOT #10** 2016-10-14 14:10**MOT test number** 651781303961**Result** ✓ Passed

- Advice** Steering rack slight knocking
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Rear Anti-roll bar has slight play in a pin/bush D bush (2.4.G.2)
- Advice** Engine oil leak
- Advice** Nearside Front steering rack end slight play
- Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush D bush (2.4.G.2)

**MOT #9**

2016-10-10 09:33

MOT test number

624440182070

Result**✗ Failed**

- Advice** Nearside Front steering rack end slight play
- Advice** Offside Rear Anti-roll bar has slight play in a pin/bush D bush (2.4.G.2)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Power steering component(s) leaking (2.3.3b)
- Advice** Steering rack slight knocking
- Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush D bush (2.4.G.2)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Engine oil leak
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #8

2015-10-05 09:31

MOT test number

627882617773

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear exhaust hanger missing
- Advice** Steering rack ends have slight play
- Advice** Front Suspension arm has slight play in a ball joint both front (2.4.G.2)
- Advice** Windscreen has slight damage
- Advice** Coolant leak

**MOT #7**

2015-10-02 09:28

MOT test number

731546545930

Result**✗ Failed**

- Advice** Steering rack ends have slight play
- Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Offside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Fail** Front Brakes imbalanced across an axle (3.7.B.5b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear exhaust hanger missing
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Advice** Front Suspension arm has slight play in a ball joint both front (2.4.G.2)
- Advice** Front brakes slight bind
- Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)
- Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Advice** Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Windscreen has slight damage
- Fail** Front Anti-roll bar has excessive play in a pin/bush both front D bush (2.4.G.2)
- Advice** Coolant leak
- Fail** Centre Brake cable has wires broken and is significantly weakened at yoke (3.5.1b)



MOT #6	2014-10-01 10:01
MOT test number	467164674229
Result	✓ Passed
Advice	Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
Advice	Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
Advice	Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Notice	Oil leak
Advice	Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
Advice	Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #5	2013-10-03 16:10
MOT test number	769536473244
Result	✓ Passed
Advice	Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
Advice	Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
Advice	Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #4**

2013-10-03 10:18

MOT test number

806216773202

Result**✗ Failed**

- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Notice** Nearside rear tyre worn to limit
- Advice** Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)

MOT #3

2012-10-02 13:38

MOT test number

959306072285

Result**✓ Passed**

- Notice** Nearside handbrake effort low

MOT #2

2011-09-15 13:45

MOT test number

289648051296

Result**✓ Passed**

- Notice** Both door mirrors damaged
- Advice** Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)



MOT #1

2011-09-14 11:53

MOT test number

468047951251

Result

✗ Failed

Fail

Parking brake: efficiency below requirements (3.7.B.7)

Advice

Nearside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

Fail

Offside Stop lamp not working (1.2.1b)

Fail

Nearside rear parking brake recording little or no effort (3.7.B.6a)

Advice

Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Notice

Both door mirrors damaged

Fail

Nearside Front position lamp(s) not working (1.1.A.3b)



Tax & MOT check

✕
Untaxed

Tax expired:
1 September 2023

✕
MOT

Expired:
2 March 2024

Tax status	Expired at 1 September
Days left	242 days too late
MOT expiry date	2 March 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 YD58GME
Plate since	2019-03-29
Current registration	 YD58GME
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-09-12
Last registration	2023-03-03
Complete history	See info



Registration #1	2008-09-12	14 mi
Registration #2	2011-09-14	83.781 mi
Registration #3	2011-09-15	83.794 mi
Registration #4	2012-10-02	102.365 mi
Registration #5	2013-10-03	120.258 mi
Registration #6	2013-10-03	120.261 mi
Registration #7	2014-10-01	136.530 mi
Registration #8	2015-10-02	153.171 mi
Registration #9	2016-10-02	169.812 mi
Registration #10	2017-10-02	186.453 mi
Registration #11	2018-10-02	203.094 mi
Registration #12	2019-10-02	219.735 mi
Registration #13	2020-10-02	236.376 mi
Registration #14	2021-10-02	253.017 mi
Registration #15	2022-10-02	269.658 mi
Registration #16	2023-10-02	286.299 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2426 mm
Height	2420 mm
Length	6845 mm
Kerb weight	2005 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	64698551611803