



SM54LXW

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 16V
Colour	Black
Year of manufacture	-
Top speed	100 mph
0 - 60 mph	14.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	126 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg





Internet history

Entry 1

Date	2021-07-15
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #23	2021-02-17 15:19
MOT test number	259996630258
Result	✓ Passed
Next expiry date	2022-02-16
Advice	Offside Sill damaged
Advice	Exhaust has a minor leak of exhaust gases Mid/rear join (6.1.2 (a))
Minor	Offside Front Windscreen wiper blade defective Split and smearing screen slightly (3.4 (b) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #22	2021-02-17 15:19
MOT test number	574764600405
Result	✗ Failed
Minor	Offside Front Windscreen wiper blade defective Split and smearing screen slightly (3.4 (b) (i))
Advice	Offside Sill damaged
Advice	Exhaust has a minor leak of exhaust gases Mid/rear join (6.1.2 (a))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #21	2020-01-22 11:00
MOT test number	385717270639
Result	✓ Passed

**MOT #20**

2020-01-21 12:21

MOT test number

839042238566

Result**✗ Failed****Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Pass with rectification** Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))**MOT #19**

2019-03-15 10:33

MOT test number

873829608568

Result**✓ Passed****Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Minor chips to windscreen**Minor** Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Play in steering rack inner joint(s)**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension rod pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**MOT #18**

2018-03-09 15:42

MOT test number

578611495305

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Nail in tyre
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Rear bush (2.4.G.2)
- Advice** Exhaust has a minor leak of exhaust gases Centre clamp corroding (7.1.2)

MOT #17

2018-03-09 13:01

MOT test number

359523179259

Result

✗ Failed

- Advice** Exhaust has a minor leak of exhaust gases Centre clamp corroding (7.1.2)
- Fail** Nearside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Nail in tyre
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Rear bush (2.4.G.2)

**MOT #16**

2017-03-17 11:58

MOT test number

466200174989

Result

✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Rear bush (2.4.G.2)

Advice Offside Play in steering rack inner joint(s)

Advice Minor chips to windscreen

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #15

2017-03-16 09:59

MOT test number

282655167723

Result

✗ Failed

Fail Offside Stop lamp not working (1.2.1b)

Fail Nearside Rear coil spring broken (2.4.C.1a)

Advice Minor chips to windscreen

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Brake servo vacuum pipe split (3.6.C.1b)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Rear bush (2.4.G.2)

Advice Offside Play in steering rack inner joint(s)

MOT #14

2016-03-01 14:07

MOT test number

113674126388

Result

✓ Passed

Advice O/S steering rack inner joint has play

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Minor chips to windscreen

Advice Nearside Front Tyre worn close to the legal limit Outer edge (4.1.E.1)

**MOT #13**

2016-02-29 16:16

MOT test number

539579333005

Result**✗ Failed**

- Fail** Hazard warning switch faulty (1.4.B.1d)
- Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure Inner sidewall (4.1.D.1b)
- Advice** Nail in N/S/R Tyre
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Minor chips to windscreen
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Headlamp aim too high (1.8)
- Advice** Nearside Front Tyre worn close to the legal limit Outer edge (4.1.E.1)
- Advice** O/S steering rack inner joint has play

MOT #12

2015-03-06 15:09

MOT test number

205245365062

Result**✓ Passed**

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Play in steering rack inner joint(s)
- Notice** Minor chips to windscreen

**MOT #11** 2015-03-06 10:35**MOT test number** 216415465000**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Play in steering rack inner joint(s)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Minor chips to windscreen**MOT #10** 2014-03-08 14:23**MOT test number** 628247364028**Result** ✓ Passed**Advice** Power steering pump has slight seepage from a component (2.3.3b)**Notice** Play in steering rack inner joint(s)**MOT #9** 2014-03-08 14:23**MOT test number** 278687464093**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Power steering pump has slight seepage from a component (2.3.3b)**Notice** Play in steering rack inner joint(s)**Pass with rectification** Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**MOT #8** 2013-03-02 13:26**MOT test number** 116181863034**Result** ✓ Passed

**MOT #7** 2012-03-24 15:45**MOT test number** 259434282009**Result** ✓ Passed**MOT #6** 2011-03-18 14:12**MOT test number** 498127371006**Result** ✓ Passed**MOT #5** 2010-03-15 14:55**MOT test number** 844004470089**Result** ✓ Passed**MOT #4** 2009-03-20 13:18**MOT test number** 824869279087**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2008-03-25 13:07**MOT test number** 803305488092**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)



MOT #2	2008-03-25 13:07
MOT test number	783495388096
Result	✓ Passed
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #1	2007-09-24 13:17
MOT test number	921727667274
Result	✓ Passed
Notice	Tyre wear starting on both fronts
Notice	O/s/f bumper eye cover missing



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SM54LXW
Plate since	2024-03-29
Current registration	 SM54LXW
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-12-02
Last registration	2021-02-17
Complete history	See info



Registration #1	2004-12-02	6 mi
Registration #2	2007-09-24	14.288 mi
Registration #3	2008-03-25	18.726 mi
Registration #4	2009-03-20	26.921 mi
Registration #5	2010-03-15	34.577 mi
Registration #6	2011-03-18	42.853 mi
Registration #7	2012-03-24	51.436 mi
Registration #8	2013-03-02	60.335 mi
Registration #9	2014-03-08	70.062 mi
Registration #10	2015-03-06	79.836 mi
Registration #11	2015-03-06	79.836 mi
Registration #12	2016-02-29	89.436 mi
Registration #13	2016-03-01	90.000 mi
Registration #14	2016-03-01	90.000 mi
Registration #15	2016-03-01	90.000 mi
Registration #16	2016-03-01	90.000 mi
Registration #17	2016-03-01	90.000 mi
Registration #18	2016-03-01	90.000 mi
Registration #19	2016-03-01	90.000 mi
Registration #20	2016-03-01	90.000 mi
Registration #21	2016-03-01	90.000 mi
Registration #22	2016-03-01	90.000 mi
Registration #23	2016-03-01	90.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1259 kg
Max. allowed weight	1641 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BCA 323204