



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	PREVIA D-4D T2 8STR
Colour	Silver
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.2 mpg





Internet history

Entry 1

Date	2022-06-30
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT #26

2024-01-23 15:04

MOT test number

623578786215

Result

✗ Failed

MAJOR Offside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice Rear Coil spring corroded (5.3.1 (b) (i))

Advice Near side front fog lamp pushed into bumper

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front lower arm rear bushes perished (5.3.4 (a) (i))

Advice Tyre worn close to legal limit/worn on edge both front tyres worn low and worn inner edges advise replacement ASAP (5.2.3 (e))

Advice Suspension arm pin or bush worn but not resulting in excessive movement both rear trailing arm bushes perished and worn (5.3.4 (a) (i))

MAJOR Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Steering system slightly rough top mounts (2.1.1 (a))

DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Minor Headlamp lens slightly defective both front lamp lens cloudy (4.1.1 (b) (i))

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #25	2023-12-22 11:31
MOT test number	771996261693
Result	✗ Failed
MAJOR	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
MAJOR	Offside Rear Parking brake inoperative on one side (1.4.1 (a))
MAJOR	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #24	2022-12-28 13:49
MOT test number	263342190008
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material both front to rear and offside rear (1.1.11 (c))
Advice	Central Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside headlamp image poor
Advice	Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))



MOT #23	2022-12-15 17:05
MOT test number	938396755683
Result	✗ Failed
Advice	Brake pipe corroded, covered in grease or other material both front to rear and offside rear (1.1.11 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Central Front Shock absorbers has light misting of oil (5.3.2 (b))
MAJOR	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
MAJOR	Exhaust has a major leak of exhaust gases (6.1.2 (a))
MAJOR	Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))
Advice	Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Front Service brake excessively fluctuating (1.2.1 (e))

MOT #22	2021-12-30 11:00
MOT test number	724509460456
Result	✓ Passed
Advice	Slight play steering rack mounting bushes
Advice	Coil spring corroded both rear (5.3.1 (b) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Central Rear stop lamp inop
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner (5.3.4 (a) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner (5.3.4 (a) (i))



MOT #21	2021-12-30 11:00
MOT test number	647214168740
Result	✗ Failed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner (5.3.4 (a) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Central Rear stop lamp inop
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner (5.3.4 (a) (i))
Advice	Coil spring corroded both rear (5.3.1 (b) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Slight play steering rack mounting bushes

MOT #20	2020-12-17 16:09
MOT test number	681894310785
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Non obligatory mirror damaged casing
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear both o/s & n/s (5.3.4 (a) (i))
Advice	3rd row seat belts not checked seats not present
Advice	Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle beam front bush (5.3.4 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #19 2020-12-09 16:12

MOT test number 900386552107

Result ✗ Failed

- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement axle beam front bush (5.3.4 (a) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge o/s & n/s (5.2.3 (e))
- Minor** Headlamp lens slightly defective o/s & n/s (4.1.1 (b) (i))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear both o/s & n/s (5.3.4 (a) (i))
- Advice** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- MAJOR** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Non obligatory mirror damaged casing
- MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** 3rd row seat belts not checked seats not present

MOT #18 2019-12-04 14:23

MOT test number 450100570071

Result ✓ Passed

- Minor** Front Headlamp lens slightly defective (4.1.1 (b) (i))



MOT #17	2019-12-04 11:09
MOT test number	356067284430
Result	✗ Failed
MAJOR	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor	Front Headlamp lens slightly defective (4.1.1 (b) (i))
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #16	2018-09-17 10:42
MOT test number	939598978780
Result	✓ Passed

MOT #15	2017-09-23 12:19
MOT test number	949143306227
Result	✓ Passed

MOT #14	2017-09-21 13:31
MOT test number	853604169147
Result	✗ Failed
Fail	Nearside Stop lamp not working (1.2.1b)
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Front Shock absorber has a serious fluid leak (2.7.3)
Fail	Offside Front position lamp(s) not working (1.1.A.3b)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Rear Statutory seat belt missing (5.1.1)



MOT #13 2016-09-03 12:21

MOT test number 586787082717

Result ✔ Passed

- Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Rear Brake pipe slightly corroded both sides (3.6.B.2c)

MOT #12 2016-08-24 11:02

MOT test number 294606704356

Result ✘ Failed

- Advice** Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)
- Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Rear Trailing arm has excessive play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)
- Fail** Nearside Rear Trailing arm has excessive play in a pin/bush (2.4.G.2)

MOT #11 2015-09-23 13:25

MOT test number 379956421347

Result ✔ Passed

- Advice** Offside Front tyre worn on inside edge
- Advice** Nearside Front tyre worn on inside edge



MOT #10 2015-09-23 09:25

MOT test number 249919746807

Result ✗ Failed

Advice Offside Front tyre worn on inside edge

Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Front tyre worn on inside edge

Fail Nearside Rear Stop lamp not working (1.2.1b)

MOT #9 2014-10-28 13:41

MOT test number 415581404406

Result ✓ Passed

MOT #8 2012-11-30 16:32

MOT test number 497145332477

Result ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #7 2012-11-30 11:03

MOT test number 848295532383

Result ✗ Failed

- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Rear brake application uneven (3.7.B.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #6 2011-11-21 16:26

MOT test number 137475221396

Result ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Under covers fitted

MOT #5 2010-12-14 09:48

MOT test number 332258240393

Result ✓ Passed

- Notice** Unable to fully inspect brake pipes due to covers and tank
- Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Notice** Offside rear tyre starting to perish
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2009-11-06 13:16
MOT test number	192740119378
Result	✓ Passed
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
Notice	Child seats fitted to both rear benches therefore unable to test rear adult belts

MOT #3	2008-10-20 15:03
MOT test number	473004398251
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2008-10-14 11:06
MOT test number	691698688250
Result	✗ Failed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Rear Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Rear Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #1	2006-11-20 13:17
MOT test number	602604926335
Result	✓ Passed




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	PK53RZN
Plate since	2019-09-29
Current registration	PK53RZN
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2003-11-19
Last registration	2024-01-23
Complete history	See info



Registration #1	2003-11-19	17 mi
Registration #2	2006-11-20	28.708 mi
Registration #3	2008-10-14	54.868 mi
Registration #4	2008-10-20	55.128 mi
Registration #5	2009-11-06	65.136 mi
Registration #6	2010-12-14	76.657 mi
Registration #7	2011-11-21	84.347 mi
Registration #8	2012-11-30	95.021 mi
Registration #9	2012-11-30	95.021 mi
Registration #10	2014-10-28	115.726 mi
Registration #11	2015-09-23	124.940 mi
Registration #12	2015-09-23	124.940 mi
Registration #13	2016-08-24	133.177 mi
Registration #14	2016-09-03	133.214 mi
Registration #15	2016-09-03	133.214 mi
Registration #16	2016-09-03	133.214 mi
Registration #17	2016-09-03	133.214 mi
Registration #18	2016-09-03	133.214 mi
Registration #19	2016-09-03	133.214 mi
Registration #20	2016-09-03	133.214 mi
Registration #21	2016-09-03	133.214 mi
Registration #22	2016-09-03	133.214 mi
Registration #23	2016-09-03	133.214 mi
Registration #24	2016-09-03	133.214 mi
Registration #25	2016-09-03	133.214 mi
Registration #26	2016-09-03	133.214 mi

Registration #27

2025-25-25

25 257 462

Registration #28

2025-25-25

25 257 462

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1810 mm
Length	4750 mm
Wheel base	2900 mm
Kerb weight	1740 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2

