





General information

Make	VOLKSWAGEN	
Model	FOX	
Colour	Yellow	
Year of manufacture	2008	
Top speed	92 mph	
0 - 60 mph	17.5 seconds	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry	1
Date	

Pictures

2021-06-24

14

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-06-20	
MOT pass rate	61 %	
MOT passed	11	
Failed MOT tests	7	
Total advice items	60	
Total items failed	10	

MOT #18		2022-06-16 16:05
MOT test	number	360414657578
Result		🗸 Passed
Next expiry date 2023-06		2023-06-20
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.	3.4 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge bald outer edge (5.	2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread $(0.1 (b))$	
Advice	Front flexy section deteriorated	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (i	i))



MOT #17		2022-06-16 14:27
MOT test	number	427218567592
Result		🗙 Failed
Advice	Front flexy section deteriorated	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge bald outer edge (5	5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread $(0.1 (b))$	
MAJOR (8.2.1.2 (a	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's	specified limits
Advice	Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) ((ii))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5	5.3.4 (b) (i))
MAJOR	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
MAJOR	Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))	

MOT #16	2021-06-21 14:04
MOT test number	552677654696
Result	✓ Passed

MOT #15		2021-06-21 08:22
MOT test	number	602326208634
Result		🗙 Failed
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1
MAJOR (8.2.1.2 (a	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer	s specified limits
MAJOR (i))	Nearside Front Lower Suspension arm pin or bush excessively worn Wishbor	ne rear bush (5.3.4 (a)



MOT #14		2020-11-02 10:34
MOT test	t number	919242494352
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or lig	ht sources (4.7.1
Advice	Offside Rear Nail in tyre	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive	movement (5.3.4
MOT #13		2020-10-29 08:52
MOT test	t number	247677538368
Result		🗙 Failed
Advice	Brake fluid close to minimum mark (1.1.10 (d) (ii))	
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or lig	ht sources (4.7.1

Advice Offside Rear Nail in tyre

MAJOR Offside Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt Track Rod End (2.1.3 (g) (ii))

MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
MAJOR	Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Nearside Side repeater not working Water Ingress Into Lamp (4.4.1 (a) (ii))
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Pass wit	th rectification Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



MOT #12	2019-03-22 16:45
MOT test n	number 176953989461
Result	✓ Passed
Advice Bush (5.3.4	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Bald Outer Edge (5.2.3 (e))
Advice	Items removed from driver's view prior to test
Advice	Offside Front Tyre worn close to legal limit/worn on edge Bald On Edges (5.2.3 (e))

MOT #11		2019-03-22 12:05
MOT test	number	220277528911
Result		🗙 Failed
Advice	Items removed from driver's view prior to test	
Advice Bush (5.3.	Nearside Front Suspension arm pin or bush worn but not resulting in excessive 4 (a) (i))	movement Rear
MAJOR	Exhaust has a major leak of exhaust gases Exhaust flexi Pipe (6.1.2 (a))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Bald Outer Edge (5.2	2.3 (e))
Advice	All direction indicators slightly discoloured (4.4.3 (a))	
MAJOR	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (2	1.1.6 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge Bald On Edges (5.2.3	(e))
MAJOR	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #10		2018-03-28 15:45
MOT test	number	702195686666
Result		✓ Passed
Advice	Rear Direction indicator slightly discoloured both showing white (1.4.A.2f)	
Advice	Front Exhaust has a minor leak of exhaust gases flexy pipe (7.1.2)	



MOT #92017-04-12 11:42MOT test number357680219834ResultImage: PassedAdviceWipers poorAdviceParking brake lever has little reserve travel (3.1.6b)AdviceNearside Front Tyre worn close to the legal limit edge (4.1.E.1)

MOT #8	2016-04-22 11:34
MOT test number	311593434526
Result	🗸 Passed
Advice Front registration plate deteriorated but not likely to be misread damage (6.3.1d)	

MOT #7 2	016-04-21 14:01		
MOT test number	914785234889		
Result	🗙 Failed		
Fail Offside Front Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)			
Pass with rectification Offside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)		
Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)			
Advice Front registration plate deteriorated but not likely to be misread damage (6.3.1d)			
Fail Offside Front Suspension arm rubber mounting deteriorated resulting in excessive mo (2.4.G.2)	vement rear		

МОТ #6	2015-04-13 13:22
MOT test number	486333905180
Result	✓ Passed



MOT #5		2013-04-30 13:56
MOT test number		685580023106
Result		✓ Passed
Notice Both rear tyres st	arting to perrish	
MOT #4		2013-04-30 13:56
MOT test number		899720323191
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim aimed so that it dazzles other road user	rs (1.8.A.1a)
Notice Both rear tyres starting to perrish		
Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)		

MOT #3		2012-05-01 15:11
MOT test	number	699952322188
Result		✓ Passed
Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in	excessive movement
Advice (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting i	n excessive movement

MOT #2	2012-04-30 16:18	
MOT test number	446351522158	
Result	🗙 Failed	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)		
Advice Nearside Front Suspension arm rubber bush deteriorated but not res (2.4.G.2)	ulting in excessive movement	
Fail Nearside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)		
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)		
Advice Offside Front Suspension arm rubber bush deteriorated but not resul (2.4.G.2)	ting in excessive movement	





MOT #1	2011-05-23 15:19
MOT test number	575313941101
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 25 July 2022	X MOT Expired: 20 June 2023
Tax status	Expired at 25 July 2022
Days left	644 days too late
MOT expiry date	20 June 2023
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEED ON
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE I
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-20
Last registration	2022-06-16
Complete history	See info



Registration #1	2008-03-20	28 mi
Registration #2	2011-05-23	31.654 mi
Registration #3	2012-04-30	39.229 mi
Registration #4	2012-05-01	39.238 mi
Registration #5	2013-04-30	46.001 mi
Registration #6	2015-04-13	49.627 mi
Registration #7	2016-04-21	55.669 mi
Registration #8	2016-04-22	55.669 mi
Registration #9	2017-04-12	60.118 mi
Registration #10	2018-03-28	64.716 mi
Registration #10 Registration #11	2018-03-28	64.716 mi
-		64.716 mi
Registration #11		64.716 mi
Registration #11 Registration #12		64.716 mi
Registration #11 Registration #12 Registration #13		64.716 mi
Registration #11 Registration #12 Registration #13 Registration #14		64.716 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15		64.716 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16		64.716 mi

More info \rightarrow





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight Width 1660 mm Height 1544 mm Length 3828 mm Wheel base 2465 mm Kerb weight 1069 kg Max. allowed weight 1480 kg Additional information Fuel tank capacity 50 I **Fuel delivery Multi-Point Injection** Number of doors 3

Number of seats	4
Number of axles	2
Engine number	BMD 378141