



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS SPORT TDI
Colour	Black
Year of manufacture	-
Top speed	127 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.6 mpg




LABEL UNKNOWN



Internet history

Entry 2


Date	2022-11-14
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-14
Pictures	22
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #18	2022-02-19 11:01
MOT test number	158454870367
Result	✓ Passed
Next expiry date	2023-02-26
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Corrosion to underside and components
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17	2021-02-04 17:01
MOT test number	549262975870
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #16	2021-02-04 12:31
MOT test number	687029121417
Result	✗ Failed

Advice Offside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

**MOT #15**

2020-02-20 10:08

MOT test number

840976216801

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))

**MOT #14**

2020-02-14 15:22

MOT test number

903494974845

Result**✗ Failed****Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure wall (5.2.3 (d) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13**

2019-02-27 16:56

MOT test number

647038192888

Result**✓ Passed**

**MOT #12**

2019-02-21 12:41

MOT test number

217730505239

Result**✗ Failed****Fail**

Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))

Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #11

2018-02-20 15:14

MOT test number

909257523297

Result**✓ Passed****Advice**

Front Brake lining(s) wearing thin (3.5.1g)

Advice

Under tray fitted

MOT #10

2017-05-10 13:15

MOT test number

316970643694

Result**✓ Passed****Advice**

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #9

2016-05-24 13:44

MOT test number

662529809315

Result**✓ Passed****Advice**

Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

Advice

Engine cover / undertray

Advice

Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

High level stop lamp not working

Advice

Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

**MOT #8**

2016-05-23 16:28

MOT test number

620094279162

Result

✗ Failed

- Advice** Engine cover / undertray
- Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)
- Advice** High level stop lamp not working
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside Side repeater not working door mirror (1.4.A.2c)
- Advice** Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

MOT #7

2015-04-24 15:40

MOT test number

525304215126

Result

✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Notice** Advise high level stop lamp not working

MOT #6

2014-05-23 16:13

MOT test number

277863044131

Result

✓ Passed

**MOT #5**

2014-05-23 09:03

MOT test number

209283244486

Result

✗ Failed

Fail

Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Fail

Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

MOT #4

2013-10-02 08:46

MOT test number

717595573283

Result

✓ Passed

Notice

Engine covers fitted obscuring some components in the engine bay

Advice

Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)

Notice

Under-trays fitted obscuring some underside components

Advice

Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3

2012-10-03 10:17

MOT test number

788407972219

Result

✓ Passed

MOT #2

2011-10-31 11:27

MOT test number

609654901323

Result

✓ Passed

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2010-09-06 15:38
MOT test number	104279340257
Result	✓ Passed



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-14
Last registration	2022-02-19
Complete history	See info



Registration #1	2007-09-14	6 mi
Registration #2	2010-09-06	19.676 mi
Registration #3	2011-10-31	23.181 mi
Registration #4	2012-10-03	32.448 mi
Registration #5	2013-10-02	43.943 mi
Registration #6	2014-05-23	49.208 mi
Registration #7	2014-05-23	49.208 mi
Registration #8	2015-04-24	54.757 mi
Registration #9	2016-05-23	62.302 mi
Registration #10	2016-05-24	62.302 mi
Registration #11	2017-05-10	67.765 mi
Registration #12	2018-05-23	75.217 mi
Registration #13	2019-05-23	82.669 mi
Registration #14	2020-05-23	90.121 mi
Registration #15	2021-05-23	97.573 mi
Registration #16	2022-02-19	105.025 mi
Registration #17	2022-02-19	105.025 mi
Registration #18	2022-02-19	105.025 mi
Registration #19	2022-02-19	105.025 mi
Registration #20	2022-02-19	105.025 mi
Registration #21	2022-02-19	105.025 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1548 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BMM 149953