





### General information

Make	VOLVO
Model	V50 SPORT D V50
Colour	Black
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg





# Internet history

Entry 1

Date Pictures 2021-07-18

16

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT #17	2023-11-03 16:13
MOT test number	377584019451
Result	✓ Passed
Next expiry date	2024-11-02
Advice Offside Front Play in steering rack inner joint(s)	

MOT #16	2022-07-16 13:08
MOT test number	267772385364
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view chip in sceen	(3.2 (a) (i))
Advice Rear rear silencer corroded	
Advice Front Play in steering rack inner joint(s) both sides	

MOT #15	2022-07-09 13:24	
MOT test number	538546661233	
Result	× Failed	
Advice Front Play in steering rack inner joint(s) both sides		
FailOffside Front Inner Tyre has ply or cords exposed cords exposed on inner edge (marked in yellow)(215/45/ZR18) (5.2.3 (d) (ii))		
Minor Windscreen damaged but not adversely affecting driver's view chip in sceen	ı (3.2 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on edge	e (5.2.3 (e))	
Advice Rear rear silencer corroded		

MOT #14	2021-07-23 15:50
MOT test number	893247009332
Result	✓ Passed
Advice Rear Exhaust box corroded and deterioted	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))	





MOT #13	2021-07-19 11:59
MOT test number	233892239382
Result	🗙 Failed
Advice Rear Exhaust box corroded and deterioted	
<b>Fail</b> Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail Offside Rear Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Advice Nearside Front Brake sensor insecure	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive (5.3.4 (a) (i))	movement rear

MOT #12	20	020-09-05 10:59
MOT test	number	293313273618
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Nail in tyre unrepairable	

MOT #11	2020-08-29 14:10
MOT test number	852784184614
Result	🗙 Failed
<b>Fail</b> Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Fail</b> Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
<b>Fail</b> Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (	a) (ii))
Advice Nearside Rear Nail in tyre unrepairable	





MOT #10		2019-04-16 12:35
MOT test	number	124172994759
Result		✓ Passed
Advice	Front brake discs worn	
Advice	Nearside front tyre worn inner+ cut outer sidewall	
Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		effect (5.3.2 (b))
MOT #9		2019-04-06 13:51
<b>MOT test number</b> 31579562100		315795621003

Result	🗙 Failed
Advice Front brake discs worn	
FailNearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
<b>Fail</b> Offside Front Position lamp not working (4.2.1 (a))	
Advice Nearside front tyre worn inner+ cut outer sidewall	
Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (	ɔ))
FailOffside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Nearside Front Position lamp not working (4.2.1 (a))	

MOT #8	2018-04-20 15:57
MOT test number	186828648427
Result	✓ Passed
Advice Under trays fitted.	





MOT #7		2018-04-20 15:57
MOT test number		670590347119
Result		🗙 Failed
Advice Under trays fitte	d.	
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	

MOT #6		2017-04-13 15:10
MOT test	number	312754579304
Result		✓ Passed
Advice	Offside Front front brake fluctuating, but not excessively (3.7.B.3)	
Advice	Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	

MOT #5	2016-03-10 13:22
MOT test number	863852232782
Result	✓ Passed
Advice Nearside Front Suspension arm rubber bush deteriorated but no (2.4.G.2)	ot resulting in excessive movement





MOT #4		2015-02-27 11:20
MOT test	number	729048955049
Result		✓ Passed
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Items removed from driver's view prior to test	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Notice	Nail in offside rear tyre	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #3		2015-02-27 10:51
MOT test	number	927728055070
Result		🗙 Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Notice	Items removed from driver's view prior to test	
Fail N	earside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nail in offside rear tyre	
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #2		2014-02-15 09:45
MOT test	number	896486044029
Result		✓ Passed
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Notice	Under-trays fitted obscuring some underside components	





MOT #1		2013-02-15 15:00
MOT test	number	716156643058
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine covers fitted obscuring some components in the engine bay	





#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	L'ANNPE
Туре	
Damage 2	AMPLE
Damaye 2	C C C C
Date	1. St
Category	AMP
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
**********	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Carrent registration	
Plate since	UK
Plate since Carrent registration	
Plate since Carrent registration Plate since	





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >





# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-12-16
Last registration	2023-11-03
Complete history	See info



Registration #1	2009-12-16	19 mi
Registration #2	2013-02-15	38.699 mi
Registration #3	2014-02-15	46.719 mi
Registration #4	2015-02-27	59.630 mi
Registration #5	2015-02-27	59.630 mi
Registration #6	2016-03-10	78.398 mi
Registration #7	2017-04-13	98.335 mi
Registration #8	2018-04-20	113.102 mi
Registration #9	2018-04-20	113.102 mi
Registration #10	2019-04-06	120.803 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.277 au

More info  $\rightarrow$ 





### Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg
Additional information	
Fuel tank capacity	52 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles	2
Engine number	521737