





General information

Make	VOLKSWAGEN
Model	FOX
Colour	Blue
Year of manufacture	-
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP	0 < 101 A	
Max. torque	108 Nm at 3.000 rpm	101 - 120 ^B _C	
Cylinders	3	121 - 140 E	
Fuel type	Petrol	141 - 165 F	
Consumption city	36.2 mpg	166 - 185 H	
Consumption extra urban	55.4 mpg	186 - 225	J
Consumption combined	46.3 mpg	225+	L





Internet history

Entry 2	
Date	2021-06-11
Pictures	16
Listing price	View report



source: autotrader.co.uk

Date 2021-05-26	
Pictures 16	
Listing price <u>View report</u>	



source: autotrader.co.uk









MOT history

MOT #19	2023-02-02 16:16
MOT test number	776472885310
Result	✓ Passed
Next expiry date	2024-02-21

MOT #18	2023-01-30 12:53
MOT test number	497485758584
Result	🗙 Failed
Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2	2 (b))
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Rear Exhaust has a minor leak of exhaust gases rear box (6.1.2 (a))	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or (4.7.1 (b) (i))	light sources
Fail Nearside Front Prop shaft joint constant velocity boot missing (6.1.7 (g) (ii))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #17	2022-02-11 15:16
MOT test number	790794892364
Result	✓ Passed

MOT #16		2021-02-15 12:54
MOT test	number	967760766688
Result		✓ Passed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorate	ed (6.1.7 (g) (i))
Advice	Nearside Front Inner Play In Steering Arm Inner Ball Joint	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	



AF58ZBU
report date: 2024-03-28

MOT #15		2020-02-05 17:53
MOT test	number	607679512872
Result		✓ Passed
Advice	Central Front Number Plate Cracked	
Advice	Engine Covers / Under Trays Fitted	
Advice	Offside Front Seat Belt Slightly Frayed	
Minor	Offside Front Lower Suspension component ball joint dust cover severely de	teriorated (5.3.4 (b) (i))
Advice	Nearside Front Inner Play In Steering Arm Ball Joint	
Minor	Nearside Front Lower Suspension component ball joint dust cover severely o	deteriorated (5.3.4 (b)
(i)) Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deterio	orated (6.1.7 (g) (i))

MOT #14	2020-02-05 10:52
MOT test number	643087214799
Result	🗙 Failed
Advice Offside Front Seat Belt Slightly Frayed	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriora	ated (6.1.7 (g) (i))
Advice Engine Covers / Under Trays Fitted	
Minor Offside Front Lower Suspension component ball joint dust cover severely deter	iorated (5.3.4 (b) (i))
Fail Nearside Rear Upper Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice Central Front Number Plate Cracked	
Minor Nearside Front Lower Suspension component ball joint dust cover severely det (i))	eriorated (5.3.4 (b)
Advice Nearside Front Inner Play In Steering Arm Ball Joint	



AF58ZBU	
report date: 2024-03-2	28

MOT #13	2019-02-19 13:17
MOT test number	475884337818
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Under Trays Fitted	
Advice Central Front Number Plate Cracked	
Advice Nearside Front Inner Play In Steering Arm Joint	

MOT #12	2019-02-18 11:36
MOT test number	164371365864
Result	🗙 Failed
Fail Offside Front Lower Suspension arm pin or bush excessively worn Rear	ward Bush (5.3.4 (a) (i))
Advice Under Trays Fitted	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Nearside Front Lower Suspension arm pin or bush excessively worn Rea	arward Bush (5.3.4 (a) (i))
Advice Central Front Number Plate Cracked	
Advice Nearside Front Inner Play In Steering Arm Joint	



MOT #11		2018-02-20 11:15
MOT test	number	270138678185
Result		✓ Passed
Advice	Offside Front Tyre Showing Signs Of Ageing	
Advice	Nearside Front Inner Slight Play In Steering Arm	
Advice	Offside Rear Tyre Showing Signs Of Ageing	
Advice	Under Trays Fitted	
Advice	Nearside Rear Tyre Showing Signs Of Ageing	
Advice	Central Front registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #10		2017-02-20 11:53
MOT test	number	229822935907
Result		✓ Passed
Advice	Offside Front Seat Belt Slightly Frayed	
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice	Central Front Exhaust Heat Shield On CAT Loose	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Central Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Under Trays Fitted	
Advice	Nearside Front Play in steering rack inner joint(s)	

AF58ZBU

report date: 2024-03-28



МОТ #9	2017-02-20 11:53
MOT test number	589565926869
Result	🗙 Failed
Advice Under Trays Fitted	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)	
Advice Offside Front Seat Belt Slightly Frayed	
Advice Nearside Front Play in steering rack inner joint(s)	
Advice Central Front Exhaust Heat Shield On CAT Loose	
Advice Central Front registration plate deteriorated but not likely to be misread (6.3.1d)
Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)	

MOT #8		2016-02-22 15:22
MOT test	number	286041196962
Result		✓ Passed
Advice	Centre Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Offside Front Suspension arm has slight play in a pin/bush Rearward (2.4.G.2)	
Advice	Nearside Front Steering pivot point has slight play (2.2.B.1g)	
Advice	Nearside Rear Tyre Showing Signs Of Aging	
Advice	Nearside Front Suspension arm has slight play in a pin/bush Rearward (2.4.G.2)	
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice	Offside Rear Tyre Showing Signs Of Aging	

AF58ZBU

report date: 2024-03-28



MOT #7	2016-02-22 11:50
MOT test number	690592935127
Result	🗙 Failed
Fail Nearside Rear Stop lamp not working (1.2.1b)	
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Advice Nearside Rear Tyre Showing Signs Of Aging	
Advice Offside Front Suspension arm has slight play in a pin/bush Rearward (2.4.G.2)	
Advice Nearside Front Steering pivot point has slight play (2.2.B.1g)	
Advice Centre Front registration plate deteriorated but not likely to be misread (6.3.1d)
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach (4.1.D.1a)	the ply or cords
Advice Nearside Front Suspension arm has slight play in a pin/bush Rearward (2.4.G.2)	1
Advice Offside Rear Tyre Showing Signs Of Aging	
Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)	

MOT #6		2015-02-13 09:24
MOT test	number	878694545068
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Front bumper insecure	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	







MOT #5	2015-02-12 10:15
MOT test number	937303945090
Result	🗙 Failed
Notice Front bumper insecure	
FailOffside rear brake binding (3.7.B.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	
MOT #4	2014-02-12 12:01
MOT test number	198003344497
Result	✓ Passed
Notice Play in steering rack inner joint(s)	
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	
MOT #3	2013-02-20 11:36
MOT test number	495711553006

Result		🗸 Passed
Advice	Offside Front Steering arm damaged but serviceable (2.2.C.1d)	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	





MOT #2	2013-02-19 15:50
MOT test number	689830953098
Result	🗙 Failed
Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its s	structure (4.1.D.1b)
Fail Rear Exhaust emissions Lambda reading after 2nd fast idle outside specified l	limits (7.3.D.3)
Advice Offside Front Steering arm damaged but serviceable (2.2.C.1d)	
Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)	
FailOffside rear brake binding (3.7.B.1)	
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #1		2011-09-09 11:42
MOT test	number	355452251446
Result		✓ Passed
Advice	Suspension arm rubber bush deteriorated but not resulting in excessive	movement (2.4.G.2)





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETO
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CUT D
Date	*
Category	AMPT
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-09-22
Last registration	2023-02-02
Complete history	See info



Registration #1	2008-09-22	20 mi
Registration #2	2011-09-09	84.717 mi
Registration #3	2013-02-19	108.098 mi
Registration #4	2013-02-20	108.098 mi
Registration #5	2014-02-12	113.111 mi
Registration #6	2015-02-12	120.847 mi
Registration #7	2015-02-13	120.847 mi
Registration #8	2016-02-22	121.200 mi
Registration #9	2016-02-22	121.200 mi
Registration #10	2017-02-20	122.433 mi
Registration #11	2017-02-20	122.433 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		10.207 est
Registration #21		11.777 mi
Registration #22		11.227 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight Width 1660 mm Height 1544 mm Length 3828 mm Wheel base 2465 mm Kerb weight 1069 kg Max. allowed weight 1480 kg Additional information Fuel tank capacity 50 I **Fuel delivery Multi-Point Injection** Number of doors 3

CarCheck.co.uk

Number of seats	4
Number of axles	2
Engine number	BMD 388228