



Mercedes-Benz

A008KKT

report date: 2024-03-28

General information

Make	MERCEDES
Model	SPRINTER 318 CDI MWB P/V
Colour	Silver
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	135 BHP
Max. torque	305 Nm at 1.200 rpm
Engine capacity	2.987 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-04-02
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-12-01
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	76
Total items failed	51

MOT #20 2022-12-02 14:06

MOT test number 319410037677

Result ✓ Passed

Next expiry date 2023-12-01

- Advice** Slight play in steering joints
- Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both side rear (5.3.4 (a) (i))
- Advice** Central prop shaft bush worn
- Advice** Brake pipe corroded, covered in grease or other material front & rear (1.1.11 (c))
- Advice** Parking brake weak

MOT #19 2022-12-02 13:22

MOT test number 187444706807

Result ✗ Failed

- Advice** Brake pipe corroded, covered in grease or other material front & rear (1.1.11 (c))
- Advice** Parking brake weak
- Fail** Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Slight play in steering joints
- Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both side rear (5.3.4 (a) (i))
- Advice** Central prop shaft bush worn



MOT #18	2021-11-08 16:33
----------------	------------------

MOT test number	875015861562
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #17	2020-09-01 16:13
----------------	------------------

MOT test number	578832269378
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #16	2019-09-05 14:06
----------------	------------------

MOT test number	524268493489
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Play in steering rack inner joint(s)
---------------	--------------------------------------

MOT #15	2018-09-05 16:35
----------------	------------------

MOT test number	496426604179
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Play in steering rack inner joint(s)
---------------	---

Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
---------------	--

Advice	Offside Front Play in steering rack inner joint(s)
---------------	--

Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	---

**MOT #14**

2018-03-23 15:16

MOT test number

329203778186

Result**✗ Failed**

- Fail** Rear Stop lamp not working x 2 (1.2.1b)
- Fail** Nearside Rear rear brake binding (3.7.B.1)
- Fail** Front front brake excessively fluctuating (3.7.B.3)
- Fail** Front Exhaust has a major leak of exhaust gases flexi (7.1.2)
- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)
- Advice** Eml
- Advice** Oil leak
- Fail** Front Windscreen wiper does not clear the windscreen effectively x 2 (8.2.2)
- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)
- Advice** Offside Front tyre worn inner edge
- Fail** Central Rear Brake pipe excessively corroded x 2 (3.6.B.2c)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Advice** Play in steering rack inner joint(s)



MOT #13

2016-08-05 14:07

MOT test number

800010535316

Result

✓ Passed

- Advice

Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Nearside Front top marker light innop ///
- Advice

Nearside Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice

Nearside Rear Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)
- Advice

Offside side marker light innop ///
- Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Nearside Front Inner Play in steering rack inner joint(s)
- Advice

Front Brake pipe slightly corroded too rear x2 /// (3.6.B.2c)
- Advice

Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice

Offside Rear top marker light innop ///
- Advice

Offside Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice

Offside Front tyre wearing on inner edge ///
- Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Offside Front Inner Play in steering rack inner joint(s)



MOT #12	2016-08-02 12:01
MOT test number	638157529840
Result	✗ Failed

- Advice** Offside Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Offside Front Side repeater missing (1.4.A.2b)
- Advice** Offside Front Inner Play in steering rack inner joint(s)
- Fail** Nearside Rear Inner Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Front Body has a sharp edge caused by damage mirror /// (6.1.C.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear top marker light innop ///
- Advice** Nearside Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Offside Front tyre wearing on inner edge ///
- Fail** Nearside Front Obligatory mirror insecure glass insecure /// (8.1.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Advice** Nearside Front Inner Play in steering rack inner joint(s)
- Fail** Nearside Front Inner Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Direction indicators flashing more than 120 times a minute (1.4.A.2g)
- Advice** Front Brake pipe slightly corroded too rear x2 /// (3.6.B.2c)
- Advice** Nearside Front top marker light innop ///
- Fail** Offside Rear Inner Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Front Headlamp insecure (1.7.3)
- Advice** Offside side marker light innop ///

**MOT #11**

2015-08-28 15:31

MOT test number

552251706726

Result

✓ Passed

- Advice** Nearside Front top marker light innop ///
- Advice** Front steering rack inner joints slight play ///
- Advice** Off side rear marker light innop
- Advice** Near side / off side front brake discs signs of wear ///

MOT #10

2015-08-21 00:00

MOT test number

772535329991

Result

✗ Failed

- Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front top marker light innop ///
- Fail** Brake hydraulic reservoir fluid level below minimum level (3.6.G.1b)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Front steering rack inner joints slight play ///
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Offside Front Side repeater excessively damaged so that it is not visible from a reasonable distance (1.4.A.2e)
- Advice** Off side rear marker light innop
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Near side / off side front brake discs signs of wear ///
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Nearside Front Direction indicators incorrect colour (1.4.A.2f)

**MOT #9**

2014-08-18 16:02

MOT test number

345250634264

Result

✓ Passed

- Notice** Play in steering rack inner joint(s)
- Notice** Near side rear marker light missing ///
- Advice** Nearside Front Direction indicators slightly discoloured (1.4.A.2f)
- Notice** Off side rear side marker light innop ///

MOT #8

2014-08-18 10:07

MOT test number

248170234216

Result

✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Notice** Near side rear marker light missing ///
- Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Body has a sharp edge caused by damage (6.1.C.1)
- Notice** Off side rear side marker light innop ///
- Advice** Nearside Front Direction indicators slightly discoloured (1.4.A.2f)
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Notice** Play in steering rack inner joint(s)
- Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #7** 2013-08-09 15:30**MOT test number** 935341423299**Result** ✓ Passed**Advice** Nearside Inner Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Notice** Play in steering rack inner joint(s)**Notice** Off side rear marker light innop ///**Advice** Offside Inner Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #6** 2013-08-09 12:45**MOT test number** 719951023274**Result** ✗ Failed**Fail** Front registration plate deteriorated (6.3.1d)**Advice** Nearside Inner Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Notice** Play in steering rack inner joint(s)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Inner Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Notice** Off side rear marker light innop ///**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #5** 2012-08-23 16:11**MOT test number** 105706532278**Result** ✓ Passed

**MOT #4** 2012-08-21 14:19**MOT test number** 935384632229**Result** ✗ Failed

- Fail** Offside Front Headlamp aim too high (1.8)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front Headlamp aim too high (1.8)
- Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)
- Notice** Near side / off side side marker lights innop ///
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

MOT #3 2011-08-17 12:55**MOT test number** 598879821216**Result** ✓ Passed

- Notice** Wheel nuts not visible

MOT #2 2011-03-08 11:42**MOT test number** 496687861054**Result** ✓ Passed**MOT #1** 2011-03-08 11:42**MOT test number** 757877161014**Result** ✗ Failed

- Pass with rectification** Offside Upper Front position lamp(s) not working (1.1.A.3b)



Tax & MOT check

X
Untaxed

Tax expired:
1 May 2023

X
MOT

Expired:
1 December 2023

Tax status	Expired at 1 May 2023
Days left	364 days too late
MOT expiry date	1 December 2023
Full MOT history	See MOT history



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-05-13
Last registration	2022-12-02
Complete history	See info



Registration #1	2008-05-13	27 mi
Registration #2	2011-03-08	121.828 mi
Registration #3	2011-08-17	133.007 mi
Registration #4	2012-08-21	149.716 mi
Registration #5	2012-08-23	149.716 mi
Registration #6	2013-08-09	164.003 mi
Registration #7	2013-08-09	164.003 mi
Registration #8	2014-08-18	188.889 mi
Registration #9	2014-08-18	188.899 mi
Registration #10	2015-08-21	205.114 mi
Registration #11	2015-08-28	205.178 mi
Registration #12	2016-08-28	221.393 mi
Registration #13	2016-08-28	221.393 mi
Registration #14	2016-08-28	221.393 mi
Registration #15	2016-08-28	221.393 mi
Registration #16	2016-08-28	221.393 mi
Registration #17	2016-08-28	221.393 mi
Registration #18	2016-08-28	221.393 mi
Registration #19	2016-08-28	221.393 mi
Registration #20	2016-08-28	221.393 mi
Registration #21	2016-08-28	221.393 mi

More info >



Dimensions & weight

Width	1960 mm
Kerb weight	2055 kg
Max. allowed weight	3500 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	64299240770571