



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	LANDCRUISER D-4D LC4 8 SEATS
Colour	Black
Year of manufacture	2004
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	343 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.6 mpg
Consumption extra urban	32.5 mpg
Consumption combined	27.2 mpg
CO2 emission	277 g/km
CO2 label	M





Internet history

Entry 1

Date	2022-02-13
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-07-17
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	137
Total items failed	30

MOT #22	2022-07-18 14:07
MOT test number	659736266633
Result	✓ Passed
Next expiry date	2023-07-17

MOT #21	2022-07-18 14:07
MOT test number	955392369568
Result	✗ Failed
<div>Pass with rectification</div> Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))	
<div>Pass with rectification</div> Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))	

MOT #20	2021-09-01 10:51
MOT test number	580786398684
Result	✓ Passed



MOT #19

2019-07-25 11:44

MOT test number

318695601472

Result

✗ Failed

Advice Multiple stone chips windscreen

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength tie bar mounting - chassis (5.3.6 (a) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Anti-roll bar mounting - chassis (5.3.6 (a) (i))

Advice Offside wiper blade worn

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Advice Offside Rear Suspension component corroded but not seriously weakened tie bar (5.3.3 (b) (i))

Minor Offside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice Nearside & offside rear brakes showing signs of heat. No bind at time of test

Advice Nearside & offside rear chassis corroded

Advice Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Rear fog lamp likely to become detached (4.5.1 (c) (ii))

Advice Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Fuel tank filler pipe & breather pipe excessively corroded

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Anti-roll bar mounting - chassis (5.3.6 (a) (i))

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Anti-roll bar mounting - chassis (5.3.6 (a) (i))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Offside sun visor doesn't stay in the up position

Fail Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Anti-roll bar mounting - chassis (5.3.6 (a) (i))

Fail Oil leaking excessively from engine (8.4.1 (a) (i))

Advice Nearside Rear Suspension component corroded but not seriously weakened tie bar (5.3.3 (b) (i))

Advice Engine oil on minimum level

Advice Rear axle corroded

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

Advice Exhaust excessively corroded and leaking

Advice Rear fuel tank mounting strap corroded

Advice Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Fail Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced inner wheel arch (7.1.1 (a) (i))

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #18

2018-08-07 11:16

MOT test number

613677658269

Result

✓ Passed

- Advice

Nearside Rear Passenger seat(s) missing at time of test
- Advice

Nearside Rear Upper Suspension component mounting prescribed area is corroded but not considered excessive shocker mounting (5.3.6 (a) (i))
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Rear Brake pad(s) wearing thin require inspecting asap (1.1.13 (a) (ii))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Sunvisor faulty
- Advice

Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c))
- Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor

Brake hydraulic reservoir fluid level below minimum level (1.1.10 (d) (i))
- Advice

Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

Various under components/panels corroded

**MOT #17**

2018-08-06 12:05

MOT test number

773290484363

Result**✗ Failed**

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Rear Upper Suspension component mounting prescribed area is corroded but not considered excessive shocker mounting (5.3.6 (a) (i))
- Advice** Sunvisor faulty
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Windscreen washer not working (3.5 (a))
- Advice** Nearside Non obligatory mirror damaged
- Minor** Brake hydraulic reservoir fluid level below minimum level (1.1.10 (d) (i))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Brake pad(s) wearing thin require inspecting asap (1.1.13 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c))
- Advice** Various under components/panels corroded
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Windscreen washer not working (3.5 (a))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Passenger seat(s) missing at time of test



MOT #16

2017-07-27 14:01

MOT test number

979096259655

Result		✓ Passed
Advice	Vehicles internal headlight adjuster altered to recheck lights	
Advice	Offside sunviser not stowed in correct place	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Nearside and offside rear chassis rails corroding	
Advice	Nearside Rear coil spring corroded (2.4.C.1b)	
Advice	Oil leak	
Advice	Rear Passenger seat(s) missing at time of test	
Advice	Screen damaged	
Advice	Nearside Non obligatory mirror damaged	
Advice	Offside wiper blade ends split	
Advice	Front Brake pipe slightly corroded too rear pipes (3.6.B.2c)	
Advice	Offside Rear coil spring corroded (2.4.C.1b)	

**MOT #15**

2017-07-26 09:58

MOT test number

390956555454

Result**✗ Failed**

Fail Nearside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Front Brake pipe slightly corroded too rear pipes (3.6.B.2c)

Advice Offside sunviser not stowed in correct place

Advice Rear Passenger seat(s) missing at time of test

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Offside wiper blade ends split

Advice Nearside Non obligatory mirror damaged

Advice Offside Front Tyre worn close to the legal limit wearing badly on outer edges and blistering (4.1.E.1)

Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Screen damaged

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Oil leak

Advice Nearside Front Tyre worn close to the legal limit wearing badly on outer edges and blistering (4.1.E.1)

Advice Nearside and offside rear chassis rails corroding



MOT #14

2016-08-02 11:53

MOT test number

347902429549

Result

✓ Passed

- Advice

Nearside Front tyre wearing on edges
- Advice

Nearside Front Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice

Temperature gauge not working
- Advice

Nearside Front Brake pipe slightly corroded too rear (3.6.B.2c)
- Advice

Nearside Rear All position lamps damaged, but still visible from a reasonable distance (1.1.A.3d)
- Advice

Nearside Front Nail in tyre
- Advice

Windscreen damaged
- Advice

Offside Rear coil spring corroded (2.4.C.1b)
- Advice

Offside Front tyre wearing on edges
- Advice

Offside Front Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice

Vehicle structure has slight corrosion (6.1.B.2)
- Advice

Nearside Rear Mudguard insecure
- Advice

Nearside Rear coil spring corroded (2.4.C.1b)



MOT #13

2015-07-27 15:38

MOT test number

488738305222

Result

✓ Passed

Advice

Nearside Brake pipe slightly corroded (3.6.B.2c)

Notice

Various stone chips windscreen

Notice

Engine oil on minimum

Advice

Offside Rear coil spring corroded (2.4.C.1b)

Notice

Nearside rear seatbelt lazy to return

Notice

Exhaust corroded

Advice

Offside Brake pipe slightly corroded (3.6.B.2c)

Notice

Rear registration plate deteriorating

Advice

Nearside Rear coil spring corroded (2.4.C.1b)

Notice

Oil leak



MOT #12	2015-07-27 12:17
MOT test number	499738805276
Result	✗ Failed
Advice	Offside Rear coil spring corroded (2.4.C.1b)
Notice	Nearside rear seatbelt lazy to return
Advice	Offside Brake pipe slightly corroded (3.6.B.2c)
Fail	Offside Rear Seat belt retracting mechanism defective (5.2.5b)
Notice	Rear registration plate deteriorating
Fail	Towbar component insecure (6.6.1)
Notice	Oil leak
Advice	Nearside Rear coil spring corroded (2.4.C.1b)
Advice	Nearside Brake pipe slightly corroded (3.6.B.2c)
Notice	Various stone chips windscreen
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Notice	Engine oil on minimum
Fail	Offside Inner Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Notice	Exhaust corroded

MOT #11	2014-08-01 13:23
MOT test number	397843214476
Result	✓ Passed

**MOT #10**

2013-08-13 16:38

MOT test number

397935223403

Result

✓ Passed

Advice Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #9**

2013-08-13 09:32

MOT test number

188655523241

Result

✗ Failed

Pass with rectification Offside Headlamp aim too low (1.8)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Front Wheel stud(s) missing (4.2.A.1e)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)**Notice** Rear wiper split**Fail** Offside Front Wheel nut(s) missing (4.2.A.1e)**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2012-07-05 09:53**MOT test number** 978667782127**Result** ✓ Passed**Notice** Third row offside rear seat removed not allowing full inspection of adult seat belts**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #7** 2011-07-21 15:41**MOT test number** 126772101229**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2011-07-18 10:26**MOT test number** 176619691121**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2010-07-27 09:42**MOT test number** 173528500238**Result** ✓ Passed**Notice** Stone chip on windscreen.**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2009-07-27 11:32**MOT test number** 451428609227**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #3** 2009-07-27 11:32**MOT test number** 633188709234**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2008-08-01 10:25**MOT test number** 821634418256**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear no. plate deteriorating.**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2007-08-13 11:36**MOT test number** 510355527298**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Unable to check fully both outer seat belts as child seats fitted.



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	HY54YCM
Plate since	2019-03-28
Current registration	HY54YCM
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-09-01
Last registration	2022-07-18
Complete history	See info



Registration #1	2004-09-01	8 mi
Registration #2	2007-08-13	32.345 mi
Registration #3	2008-08-01	44.773 mi
Registration #4	2009-07-27	57.547 mi
Registration #5	2010-07-27	70.490 mi
Registration #6	2011-07-18	81.958 mi
Registration #7	2011-07-21	81.958 mi
Registration #8	2012-07-05	90.101 mi
Registration #9	2013-08-13	97.312 mi
Registration #10	2013-08-13	97.312 mi
Registration #11	2014-08-01	105.302 mi
Registration #12	2015-07-27	112.438 mi
Registration #13	2016-07-27	120.575 mi
Registration #14	2017-07-27	128.712 mi
Registration #15	2018-07-27	136.849 mi
Registration #16	2019-07-27	144.986 mi
Registration #17	2020-07-27	153.123 mi
Registration #18	2021-07-27	161.260 mi
Registration #19	2022-07-18	169.397 mi
Registration #20	2023-07-27	177.534 mi
Registration #21	2024-07-27	185.671 mi
Registration #22	2025-07-27	193.808 mi
Registration #23	2026-07-27	201.945 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	1990 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Engine number	1KD1121289