





General information

Make	VOLKSWAGEN
Model	SHARAN CARAT TDI (130BHP)
Colour	Black
Year of manufacture	2004
Top speed	117 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	310 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	173 g/km
CO2 label	Н







Internet history

Entry 1

Date Pictures 2021-09-20

13

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-02-09
MOT pass rate	59 %
MOT passed	16
Failed MOT tests	11
Total advice items	89
Total items failed	19

MOT #27		2023-02-08 08:29
MOT test	number	522714212497
Result		✓ Passed
Next expi	ry date	2024-02-09
Advice	Offside Rear Shock absorbers has slight external damage to the casing (5	5.3.2 (b))
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice (i))	Integral body structure is corroded but structural rigidity is not significant	tly reduced sills (6.1.1 (c)
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Front Shock absorbers has a slightly worn bush (5.3.2 (c))	

MOT #26		2022-02-07 13:49
MOT test	number	315406472105
Result		✓ Passed
Advice (5.3.4 (a)	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessiv (i))	re movement
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4	4 (a) (i))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	





MOT #25		2022-02-07 13:48
MOT test	number	110171527548
Result		🗙 Failed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.	1.11 (c))
Advice	Front Anti-roll bar pin or bush worn but not resulting in excessive movemer	nt (5.3.4 (a) (i))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.	11 (c))
Pass wit	th rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice (5.3.4 (a)	Offside Front Lower Suspension arm pin or bush worn but not resulting in ex (i))	xcessive movement

MOT #24	2021-02-10	09:36
MOT test	number 9668388	317372
Result		Passed
Advice (a) (i))	Offside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5	.3.4
Advice	Brake pad wear warning lamp illuminated	
Advice	Nearside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	
Advice	Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))	





MOT #23		2021-02-04 17:09
MOT test	number	713297538821
Result		🗙 Failed
Advice	Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effe	ct (5.3.2 (b))
Advice	Offside Rear Inner Brake pipe corroded, covered in grease or other material (1	.1.11 (c))
Fail Or of dirt (6.1	ffside Front Drive shaft joint constant velocity boot split or insecure, no longer p .7 (g) (ii))	revents the ingress
Advice	Brake pad wear warning lamp illuminated	
Advice (a) (i))	Offside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive	e movement (5.3.4
Advice	Nearside Rear Inner Brake pipe corroded, covered in grease or other material	(1.1.11 (c))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	

MOT #22		2020-01-13 15:11
MOT test	number	306442077357
Result		✓ Passed
Advice	Os outer cv boot leaking	
Advice	Nsr shock damp	
Advice	Osr brake pipe rusty	
Advice	Osf tyre wearing low	
Advice	Both front anti roll bar D bushes worn	
Advice	Outer sills not checked side skirts fitted	
Advice	Nsr brake pipe rusty	
Advice	Osr anti rollbar D bush worn	
Advice	Brake pad wear light on dash	
Advice	Nsf tyre wearing low	





MOT #21	2020-01-11 15:44
MOT test number	169594903783
Result	🗙 Failed
FailNearside Front Suspension component ball joint dust cover no longer prevents the i(5.3.4 (b) (ii))	ngress of dirt
Advice Nsr shock damp	
Advice Osr anti rollbar D bush worn	
Advice Nsf tyre wearing low	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Os outer cv boot leaking	
Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no lor ingress of dirt (6.1.7 (g) (ii))	nger prevents the
Advice Outer sills not checked side skirts fitted	
Advice Osr brake pipe rusty	
Advice Nsr brake pipe rusty	
Advice Osf tyre wearing low	
Advice Both front anti roll bar D bushes worn	
Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no lon ingress of dirt (6.1.7 (g) (ii))	ger prevents the
Advice Brake pad wear light on dash	





MOT #20		2019-01-10 12:17
MOT test	number	704342013875
Result		✓ Passed
Advice	Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated	(5.3.4 (b) (i))
Advice	Nearside Non obligatory mirror damaged	
Minor	Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated	d (6.1.7 (g) (i))

МОТ #19	2019-01-09 16:54
MOT test number	941488484255
Result	🗙 Failed
Advice Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 ((b))
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorat	ed (6.1.7 (g) (i))
Fail Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents (5.3.4 (b) (ii))	the ingress of dirt
Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated	d (5.3.4 (b) (i))
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Minor Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))	
Advice Nearside Non obligatory mirror damaged	

MOT #18	2018-01-09 15:11
MOT test number	435988116256
Result	✓ Passed
Advice Offside Rear Shock absorber casing heavily corroded	



MOT #17	2018-01-02 16:02
MOT test number	411223137578
Result	🗙 Failed
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	
Advice Offside Rear Shock absorber casing heavily corroded	
Fail Nearside Front Seat belt anchorage prescribed area is excessively corroded INN	ER DOOR SILL (5.2.6)

MOT #16		2017-01-11 14:23
MOT test	number	904266352942
Result		✓ Passed
Advice	Nearside Front Brake hose slightly chafed (3.6.B.4d)	
Advice	Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)	
Advice	Front registration plate damaged slightly but unlikely to be misread	

MOT #15	2017-01-11 09:21
MOT test number	761063705706
Result	🗙 Failed
Advice Nearside Front Brake hose slightly chafed (3.6.B.4d)	
Advice Front registration plate damaged slightly but unlikely to be misread	
Fail Nearside Front Lower Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
Advice Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)	
FailNearside Front Front position lamp(s) not working (1.1.A.3b)	
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting movement REAR (2.4.G.2)	g in excessive

NG54FXR

report date: 2024-03-29



NG54FXR
report date: 2024-03-29

MOT #14		2016-02-01 12:55
MOT test	number	959499472035
Result		✓ Passed
Advice	Offside Front Brake hose slightly deteriorated (3.6.B.4d)	
Advice	Nearside Front Brake hose slightly chafed (3.6.B.4d)	

MOT #13	2016-01-28 13:28		
MOT test number	180188968171		
Result	🗙 Failed		
Fail Centre Exhaust has a major leak of exhaust gases (7.1.2)			
Advice Offside Front Brake hose slightly deteriorated (3.6.B.4d)			
Advice Nearside Front Brake hose slightly chafed (3.6.B.4d)			

MOT #12		2015-01-08 10:14
MOT test	number	457388705049
Result		✓ Passed
Notice	Rear discs worn slightly	
Notice	Near side front brake hose perished	
Notice	Near side front tyre worn low outer edge	
Notice	Front discs worn	
Notice	Movement in both front top suspension mounts	

MOT #11	2014-01-31 17:03
MOT test number	579181934029
Result	✓ Passed
Notice Some wear on discs	





MOT #10	2014-01-24 16:50
MOT test number	545944824007
Result	🗙 Failed
NoticeSome wear on discsFailOffside Side repeater has less than 50% of the light sources illuminating (1.4.A.2c)	
MOT #9	2012-12-12 11:24

MOT test	number 128757342337
Result	✓ Passed
Advice (2.5.C.1a)	Nearside Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

МОТ #8	2012-01-12 14:20
MOT test number	289022712009
Result	✓ Passed

MOT #7		2012-01-12 14:20
MOT test number		367082212014
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp aim too low (1.8)	

МОТ #6	2010-12-16 12:11
MOT test number	251930350354
Result	Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2010-01-09 13:10
MOT test number	430499400009
Result	✓ Passed





MOT #4	2009-12-31 14:16
MOT test number	533945469358
Result	🗙 Failed
Pass with rectification Offside Headlamp aim too high (1.8)	
Notice Spare wheel loose.	
Fail Emissions not tested (7.0)	
Fail Exhaust has a major leak of exhaust gases (7.1.2)	
Notice Udertray fitted.	

MOT #3	2008-11-06 11:36
MOT test number	940331818375
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2007-10-29 12:29
MOT test number	882742207365
Result	✓ Passed

MOT #1	2007-10-29 11:48
MOT test number	494392907339
Result	🗙 Failed
Fail Nearside Direction indicator not working (1.4.A.2c)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice N/s inner driveshaft boot split	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	X MOT Expired: 9 February 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	9 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEED ON
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE I
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
and the second sec	

And a second s	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2004-11-23
Last registration	2023-02-08
Complete history	See info



Registration #1	2004-11-23	18 mi
Registration #2	2007-10-29	40.773 mi
Registration #3	2007-10-29	40.773 mi
Registration #4	2008-11-06	48.453 mi
Registration #5	2009-12-31	55.413 mi
Registration #6	2010-01-09	55.473 mi
Registration #7	2010-12-16	63.091 mi
Registration #8	2012-01-12	71.838 mi
Registration #9	2012-12-12	81.703 mi
Registration #10	2014-01-24	91.842 mi
Registration #11	2014-01-31	91.893 mi
Registration #12	2015-01-08	100.642 mi
Registration #13	2016-01-28	108.429 mi
Registration #14	2016-02-01	108.499 mi
Registration #15		11.707 est
Registration #16		11.777 est
Registration #17		11.707 est
Registration #18		11.777 est
Registration #19		11.777 est
Registration #20		11.777 est
Registration #21		11.777 esi
Registration #22		11.777 est
Registration #23		10.317 est
Registration #23 Registration #24		11.777 es
		11.777 es 11.777 es 11.777 es
Registration #24		00,000 est 01,000 est 00,000 est 01,000 est

Registration #28

7000.00.00

-

11.777 mi

More info >





Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

Number of axles

CarCheck.co.uk

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1810 mm
Height	1730 mm
Length	4634 mm
Wheel base	2841 mm
Kerb weight	1928 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5

2