



UK

HK560MT

report date: 2024-03-29

General information

Make	NISSAN
Model	PRIMASTAR SE SWB 115DCI SHR P/V
Colour	Silver
Year of manufacture	-
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	290 Nm at 1.600 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	40.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-19
Pictures	2
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #23	2022-12-21 09:14
MOT test number	788525111934
Result	✓ Passed
Next expiry date	2023-12-22
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #22	2021-12-22 12:32
MOT test number	852961185843
Result	✓ Passed
Advice	Front Sub-frame pin or bush worn but not resulting in excessive movement all bushes worn (5.3.4 (a) (i))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))
Advice	Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))
Advice	Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #21**

2021-12-22 09:37

MOT test number

455116548016

Result

✗ Failed

Advice Front Sub-frame pin or bush worn but not resulting in excessive movement all bushes worn (5.3.4 (a) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #20

2020-12-18 11:54

MOT test number

815671622390

Result

✓ Passed

Advice Offside Front Play in steering rack inner joint(s)

Advice Offside Front upper Macpherson strut pin or bush worn but not resulting in excessive movement

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Front Play in steering rack inner joint(s)

Advice Nearside Front upper Macpherson strut pin or bush worn but not resulting in excessive movement

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #19**

2020-12-18 09:23

MOT test number

917243351281

Result**✗ Failed**

- Fail** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front upper Macpherson strut pin or bush worn but not resulting in excessive movement
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Play in steering rack inner joint(s)
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Headlamp lens seriously defective lens cloudy (4.1.1 (b) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Front upper Macpherson strut pin or bush worn but not resulting in excessive movement
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #18

2019-12-05 17:26

MOT test number

917023167927

Result**✓ Passed**

- Advice** Play in steering rack inner joint(s) both
- Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #17**

2019-12-02 16:42

MOT test number

578680652579

Result**✗ Failed**

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Obligatory mirror seriously damaged, affecting the rear view glass smashed (3.3 (b) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Play in steering rack inner joint(s) both

Fail Nearside Front Sub-frame pin or bush excessively worn (5.3.4 (a) (i))

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #16

2018-12-07 12:43

MOT test number

819693406192

Result**✓ Passed**

Advice Offside Front Macpherson strut has slight movement at the upper attachment

Advice Nearside Front Macpherson strut has slight movement at the upper attachment

Advice Nearside Front Sub-frame rubber bush deteriorated but not resulting in excessive movement, rearmost bush has slight play

**MOT #15**

2018-12-07 10:27

MOT test number

288733550739

Result**✗ Failed**

Advice Nearside Front Sub-frame rubber bush deteriorated but not resulting in excessive movement, rearmost bush has slight play

Advice Offside Front Macpherson strut has slight movement at the upper attachment

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Nearside Front Macpherson strut has slight movement at the upper attachment

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #14

2017-12-07 17:05

MOT test number

423708303808

Result**✓ Passed**

Advice Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice Nearside Front Play in steering rack inner joint(s)

Advice Nearside Front Suspension arm has slight play in a pin/bush wishbone rearmost bush has slight play (2.4.G.2)

Advice Engine management light lit on dash

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice Nearside Front Sub-frame rubber bush deteriorated but not resulting in excessive movement rearmost bush has play (2.4.G.2)

**MOT #13**

2017-12-07 09:23

MOT test number

813805674075

Result

✗ Failed

- Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Front abs wire mounting bracket broken and another mounting bracket missing. abs wire is not currently fouling any part of vehicle
- Advice** Nearside Front Suspension arm has slight play in a pin/bush wishbone rearmost bush has slight play (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Engine management light lit on dash
- Advice** Front front brake fluctuating, but not excessively (3.7.B.3)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Advice** Oily residue around nearside front shock absorber however vehicle is wet so unable to determine cause
- Advice** Nearside Front Sub-frame rubber bush deteriorated but not resulting in excessive movement rearmost bush has play (2.4.G.2)

MOT #12

2016-12-22 13:53

MOT test number

971199526245

Result

✓ Passed

MOT #11

2016-12-22 11:24

MOT test number

790366985447

Result

✗ Failed

- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Central Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Central Stop lamp not working (1.2.1b)

**MOT #10** 2015-12-23 15:03**MOT test number** 913682485228**Result** ✓ Passed**MOT #9** 2015-12-23 09:27**MOT test number** 938644149372**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #8** 2014-12-02 08:45**MOT test number** 886056334386**Result** ✓ Passed**MOT #7** 2014-12-02 08:45**MOT test number** 469106334497**Result** ✗ Failed**Pass with rectification** Centre Stop lamp not working (1.2.1b)**MOT #6** 2013-11-08 15:48**MOT test number** 168302213323**Result** ✓ Passed

**MOT #5** 2013-11-08 10:19**MOT test number** 308472113359**Result** ✗ Failed**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Centre Stop lamp not working (1.2.1b)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2012-11-09 12:16**MOT test number** 307694112375**Result** ✓ Passed**MOT #3** 2011-10-18 14:50**MOT test number** 236441691275**Result** ✓ Passed**Notice** All tyre tread depths 2mm**Notice** Front and rear brake pads heavily worn approx 3mm wear left**MOT #2** 2010-11-12 10:23**MOT test number** 951006010312**Result** ✓ Passed**MOT #1** 2010-01-13 08:50**MOT test number** 130103310097**Result** ✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-01-31
Last registration	2022-12-21
Complete history	See info



Registration #1	2007-01-31	7 mi
Registration #2	2010-01-13	47.776 mi
Registration #3	2010-11-12	65.875 mi
Registration #4	2011-10-18	74.213 mi
Registration #5	2012-11-09	83.026 mi
Registration #6	2013-11-08	90.019 mi
Registration #7	2013-11-08	90.019 mi
Registration #8	2014-12-02	97.932 mi
Registration #9	2015-12-23	105.670 mi
Registration #10	2015-12-23	105.670 mi
Registration #11	2016-12-22	111.327 mi
Registration #12	2016-12-22	111.327 mi
Registration #13	2017-12-21	117.997 mi
Registration #14	2017-12-21	117.997 mi
Registration #15	2018-12-20	124.667 mi
Registration #16	2018-12-20	124.667 mi
Registration #17	2019-12-19	131.337 mi
Registration #18	2019-12-19	131.337 mi
Registration #19	2020-12-18	138.007 mi
Registration #20	2020-12-18	138.007 mi
Registration #21	2021-12-17	144.677 mi
Registration #22	2021-12-17	144.677 mi
Registration #23	2022-12-21	151.347 mi
Registration #24	2022-12-21	151.347 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1904 mm
Wheel base	3098 mm
Kerb weight	1689 kg
Max. allowed weight	2935 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	046558