





report date: 2024-03-28

General information

Make	NISSAN
Model	PRIMASTAR ACCESS SWB DCI 100 P/V
Colour	Silver
Year of manufacture	2004
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	240 Nm at 2.000 rpm
Engine capacity	1.870 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	43.5 mpg
Consumption combined	38.2 mpg



CarCheck.co.uk page 1/21



report date: 2024-03-28

Internet history

Entry 1

Date 2021-11-03

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/21



report date: 2024-03-28

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2024-10-25
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	131
Total items failed	44

MOT #23	2023-10-25 08:47
MOT test number	305892676240
Result	✓ Passed
Next expiry date	2024-10-25

MOT #22		2022-10-26 10:21
MOT test	number	769196942337
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #21		2021-10-25 17:55
MOT test	number	249112712377
Result		✓ Passed
Advice	Nearside Rear SELL CORRODED	
Advice	Front Inner Track rod end ball joint has slight play BOTH SIDES (2.1.3 (b) (i))	

CarCheck.co.uk page 3/21



report date: 2024-03-28

MOT #20 2021-10-25 17:55 **MOT** test number 151482753118 Result × Failed Pass with rectification Front Position lamp not working (4.2.1 (a) (ii)) **Advice** Nearside Rear SELL CORRODED Pass with rectification Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) Advice Front Inner Track rod end ball joint has slight play BOTH SIDES (2.1.3 (b) (i)) Pass with rectification Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #19 2021-10-11 08:19 573276864484 **MOT test number** Result Failed Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i)) Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) Fail Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength step area (5.3.6 (a) (i)) Offside Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail **Advice** Play in steering rack inner joint(s)

MOT test number

Result

Advice Play in steering rack inner joint(s)

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner rear step area just out of prescribed area (5.3.6 (a) (i))

CarCheck.co.uk page 4/21



report date: 2024-03-28

MOT #17 2020-10-07 16:13 734978308667 **MOT test number** Result × Failed Fail Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b)) Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Fail Advice Play in steering rack inner joint(s) Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner rear step area just out of prescribed area (5.3.6 (a) (i))

MOT #16	2019-04-03 12:32
MOT test number	748087462293
Result	✓ Passed
Advice Play in steering rack inner joint(s)	

CarCheck.co.uk page 5/21



report date: 2024-03-28

MOT #15 2019-03-27 17:22

MOT test number 959253576160

Result **X** Failed Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **Advice** Play in steering rack inner joint(s) Fail Front Exhaust has a major leak of exhaust gases (6.1.2 (a)) Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Fail Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) Fail Offside Front Position lamp not working (4.2.1 (a)) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail Horn not working (7.7 (a) (ii)) Fail Nearside Headlamp insecure (4.1.1 (c)) Fail Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength subframe mount area (5.3.6 (a) (i)) Nearside Front Position lamp not working (4.2.1 (a)) Fail Fail Nearside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i)) Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 6/21



report date: 2024-03-28

MOT #14 2018-03-29 18:13

MOT test number 284708805185

Result ✓ Passed **Advice** Nearside Front Play in steering rack inner joint(s) Advice Front and rear suspension coil springs corroding Advice Dampness around steering rack gaiter nearside Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Advice Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e) Advice Offside Rear Upper Suspension spring mounting prescribed area is corroded but not considered excessive floor (2.4.A.3) Oil leak Advice Advice Offside Front Play in steering rack inner joint(s) Advice Front and rear tyres different sizes Advice Front jacking points corroding Advice Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e) **Advice** Nearside Rear Upper Suspension spring mounting prescribed area is corroded but not considered excessive floor (2.4.A.3)

CarCheck.co.uk page 7/21



report date: 2024-03-28

 MOT #13
 2018-03-29 12:53

 MOT test number
 504660481064

 Result
 X Failed

CarCheck.co.uk page 8/21

Fail Offside rear parking brake recording little or no effort (3.7.B.6a)
Advice Nearside rear brake fluctuating, but not excessively (3.7.B.3)
Advice Dampness around steering rack gaiter nearside
Advice Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice Nearside Front Play in steering rack inner joint(s)
Advice Offside Rear Upper Suspension spring mounting prescribed area is corroded but not considered excessive floor (2.4.A.3)
Fail Offside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice Nearside Rear rear brake fluctuating, but not excessively (3.7.B.3)
Advice Front and rear tyres different sizes
Advice Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice Front jacking points corroding
Fail Rear Brakes imbalanced across an axle (3.7.B.5b)
Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice Oil leak
Advice Nearside Rear Upper Suspension spring mounting prescribed area is corroded but not considered excessive floor (2.4.A.3)
Advice Rear Brake pad(s) wearing thin unable to see inner brake pads (3.5.1g)
Advice Offside Front Play in steering rack inner joint(s)
Fail Offside rear brake excessively fluctuating (3.7.B.3)
Advice Front and rear suspension coil springs corroding
Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)



MOT test number

NG54SYF

report date: 2024-03-28

422833911092

MOT #12 2017-02-27 16:29

Result
✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear Upper Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Play in steering rack inner joint(s)

Advice Nearside Front tyre . inner tyre wall cut

Advice Nearside Rear Brake hose has slight corrosion to ferrules front hose (3.6.B.4e)

Advice Front tyres 205/65/16c . rear tyres 195/65/16c. spare 195/65/16c

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Rear Upper Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Play in steering rack inner joint(s)

Advice Offside Front brake pads worn slightly low . offside brake pads worn a lot lower than nearside

front

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Spare wheel carrier corroded. securing bolts very corroded

Advice Offside Rear Brake hose has slight corrosion to ferrules front hose (3.6.B.4e)

Advice Offside Rear coil spring corroded (2.4.C.1b)

CarCheck.co.uk page 9/21



Advice

Nearside Front tyre . inner tyre wall cut

NG54SYF

report date: 2024-03-28

MOT #11 2017-02-27 11:43

MOT test number 947465269697

Result × Failed Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a) **Advice** Front tyres 205/65/16c . rear tyres 195/65/16c. spare 195/65/16c **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Offside Front brake pads worn slightly low . offside brake pads worn a lot lower than nearside front Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Rear Upper Coil spring mounting corroded but not seriously weakened (2.4.C.3c) Offside Rear Brake hose has slight corrosion to ferrules front hose (3.6.B.4e) Advice **Advice** Offside Front Play in steering rack inner joint(s) Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Advice Offside Rear coil spring corroded (2.4.C.1b) Advice Spare wheel carrier corroded. securing bolts very corroded Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Nearside Rear Upper Coil spring mounting corroded but not seriously weakened (2.4.C.3c) Nearside Rear Brake hose has slight corrosion to ferrules front hose (3.6.B.4e) Advice Advice Nearside Front Play in steering rack inner joint(s) Advice Nearside Rear coil spring corroded (2.4.C.1b)

CarCheck.co.uk page 10/21



report date: 2024-03-28

MOT #10 2016-03-02 15:46

 MOT test number
 760644299902

 Result
 ✓ Passed

Advice Slight front and rear brake imbalance on brake tester

Advice Offside Rear Brake hose has slight corrosion to ferrules front hose (3.6.B.4e)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened inner (3.5.1i)

Advice Nearside Rear Upper Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

Advice Steering rack inner coupling offside & nearside slight play

Advice Nearside Rear Brake hose has slight corrosion to ferrules front hose (3.6.B.4e)

Advice Offside Front tyre. outer wall perishing & cracks

Advice Front brake pads in poor condition

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner face outer

edge (3.5.1i)

Advice Offside Rear Upper Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

Advice Nearside Front outer wall perishing & cracks

CarCheck.co.uk page 11/21



report date: 2024-03-28

MOT #9 2016-03-01 12:35

MOT test number 906539621115

Result	×	Failed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear coil spring corroded (2.4.C.1b)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened inner (3.5.1i)	
Advice	Offside Rear Upper Coil spring mounting corroded but not seriously weakened (2.4.C.3c)	
Advice	Nearside Front outer wall perishing & cracks	
Advice	Offside Rear Brake hose has slight corrosion to ferrules front hose (3.6.B.4e)	
Fail Of	ffside Rear Rear reflector missing (1.5.1a)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear coil spring corroded (2.4.C.1b)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Rear Upper Coil spring mounting corroded but not seriously weakened (2.4.C.3c)	
Advice	Steering rack inner coupling offside & nearside slight play	
Advice edge (3.5.	Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner face oute 1i)	r
Advice	Nearside Rear Brake hose has slight corrosion to ferrules front hose (3.6.B.4e)	
Advice	Offside Front tyre. outer wall perishing & cracks	
Fail Ne	earside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Of	ffside Front front brake binding (3.7.B.1)	

CarCheck.co.uk page 12/21



report date: 2024-03-28

MOT #8 2015-03-05 09:16 836254165017 **MOT** test number Result ✓ Passed Notice Front and rear brake discs worn and corroded inner faces Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Notice Under-trays fitted obscuring some underside components Advice Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e) Notice Play in steering rack inner joint(s) Notice Parts of floor corroding Notice Front and rear tyres different sizes Advice Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e) Notice Engine covers fitted obscuring some components in the engine bay Advice Front Power steering pipe(s) or hose(s) slightly corroded (2.3.2) Notice Slight brake bind offside front Notice Front tyres cracking on tread and walls

MOT #7	2014-03-05 14:58
MOT test number	495284464086
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #6	2012-10-12 16:13
MOT test number	936716982209
Result	✓ Passed

CarCheck.co.uk page 13/21



report date: 2024-03-28





CarCheck.co.uk page 14/21



report date: 2024-03-28

MOT #3 2009-12-11 17:49
MOT test number 782325449365

Result × Failed

Notice Offside rear tyre wearing low and perishing

Fail Offside Stop lamp not working (1.2.1b)

Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

Fail Offside rear parking brake recording little or no effort (3.7.B.6a)

Notice Nearside front tyre wearing low

Notice All handbrake cables appear corroded

Fail Offside Headlamp aim too low and too far to the left. (1.8)

Fail Offside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)

Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice Offside handbrake cable casing fouling rear tyre

Fail Nearside Headlamp aim too low and too far to the left. (1.8)

MOT #2 2008-10-21 14:41

MOT test number 433225498228

Result

Passed

MOT #1 2007-12-04 16:10

MOT test number 740908537317

CarCheck.co.uk page 15/21



report date: 2024-03-28

Tax & MOT check



Tax status Valid until 1 February

Days left 278

MOT expiry date 25 October 2024

Full MOT history See MOT history

CarCheck.co.uk page 16/21



report date: 2024-03-28

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 17/21



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	UK AIS
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 18/21



report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 19/21



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-12-14
Last registration	2023-10-25
Complete history	See info



Registration #1	2004-12-14	24 mi
Registration #2	2007-12-04	38.274 mi
Registration #3	2008-10-21	48.088 mi
Registration #4	2009-12-11	54.374 mi
Registration #5	2009-12-17	54.376 mi
Registration #6	2011-10-05	54.954 mi
Registration #7	2012-10-12	55.472 mi
Registration #8	2014-03-05	56.388 mi
Registration #9	2015-03-05	61.121 mi
Registration #10	2016-03-01	65.683 mi
Registration #11	2016-03-02	65.683 mi
Registration #12	2017-02-27	70.269 mi
Registration #13	2017-02-27	70.269 mi
Registration #14		71.777 es
Registration #15		11.177 es
Registration #16		11.177 es
Registration #17		11.177 es
Registration #18		11.777 es
Registration #19		11.177 es
Registration #20		11.777 es
Registration #21		11.77 44
Registration #21 Registration #22		11.777 es
		11.777 es 11.777 es 11.777 es
Registration #22		11.777 es 11.777 es 11.777 es



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Additional information

Fuel tank capacity	90
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	225111

CarCheck.co.uk page 21/21