





General information

Make	JAGUAR
Model	X-TYPE SOVEREIGN
Colour	Grey
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	366 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg



Internet history	
Entry 1	
Date	2021-05-22
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #22	2022-07-05 13:53
MOT test number	655556245443
Result	✓ Passed
Next expiry date	2023-07-06
Advice Offside Rear Suspension arm pin or bush worn but not resulting in exarm (5.3.4 (a) (i))	cessive movement trailing
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in e arm (5.3.4 (a) (i))	excessive movement trailing
Advice Parking brake efficiency only just met. It would appear that the brakin adjustment or repair. (1.4.2 (a) (i))	ng system requires
Advice Brake fluid close to minimum mark suspect contamination (1.1.10 (d)) (ii))

MOT #21	2022-07-05 08:22
MOT test number	248522493711
Result	🗙 Failed
Fail Nearside Rear Brake cable insecure (1.1.15 (c))	
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive arm (5.3.4 (a) (i))	movement trailing
Advice Parking brake efficiency only just met. It would appear that the braking system adjustment or repair. (1.4.2 (a) (i))	ו requires
Advice Brake fluid close to minimum mark suspect contamination (1.1.10 (d) (ii))	
Fail Offside Rear Brake cable insecure (1.1.15 (c))	
Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive m arm (5.3.4 (a) (i))	ovement trailing
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #20		2021-07-07 11:20
MOT test	number	584796122198
Result		✓ Passed
Advice	Seat belt anchorage prescribed area repair covered in underseal (nearside und	ler sill)
Advice	Engine cover fitted obscuring some components in the engine bay	
Advice	Seat belt anchorage prescribed area repair covered in underseal (offside under	r sill)
Advice	Under trays fitted obscuring some underside components	



BN57AOG report date: 2024-03-28

MOT #1	19	2021-06-30 14:00
MOT te	st number	450305486108
Result		🗙 Failed
Fail	Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a	a) (ii))
Fail	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt	(5.3.4 (b) (ii))
Fail	Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Fail corrode	Nearside Seat belt anchorage prescribed area strength or continuity significantly readed to excess (7.1.1 (a) (i))	duced outer sill
Fail detachr	Nearside Front Lower Steering linkage ball joint worn to the extent there is a serious ment (2.1.3 (b) (ii))	s risk of
Fail	Nearside Rear Brake cable insecure handbrake cable (1.1.15 (c))	
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail inner si	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the dewall split to excess (5.2.3 (d) (i))	e ply or cords
Fail	Service brake excessively fluctuating all brakes front & rear fluctuating (1.2.1 (e))	
Fail	Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a)	(ii))
Fail	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail	Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a)	(ii))
Fail corrode	Offside Seat belt anchorage prescribed area strength or continuity significantly redued to excess (7.1.1 (a) (i))	iced outer sill
Fail	Offside Rear Brake cable insecure handbrake cable (1.1.15 (c))	
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	



BN57AOG report date: 2024-03-28

MOT #18		2021-01-14 13:51
MOT test nu	mber	702131916978
Result		✓ Passed
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Minor Ne	earside Front Suspension arm ball joint dust cover severely deteriorated (5.3	3.4 (b) (i))
Advice	learside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
	Offside Rear Suspension arm pin or bush worn but not resulting in excessive sh worn. (5.3.4 (a) (i))	movement Trailing
Advice F	ront Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice C	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	



MOT #17 2021-01-08 11:4
MOT test number 65782785687
Result X Faile
Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush worn. (5.3.4 (a) (i))
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Fail Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail Nearside Rear Shock absorbers damaged to the extent that it does not function (5.3.2 (b))
Fail Offside Rear Suspension arm pin or bush excessively worn Lower arm inner bush worn. (5.3.4 (a) (i))
Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Fail Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
Fail Offside Rear Shock absorbers damaged to the extent that it does not function (5.3.2 (b))
Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16		2020-01-07 13:33
MOT test	number	548129963500
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened Both fronts (1.1.	.14 (a) (ii))
Advice	Brake pedal wearing smooth (1.1.2 (c))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	



BN57AOG
report date: 2024-03-28

MOT #15	2020-01-06 13:19
MOT test number	712761397988
Result	🗙 Failed
Advice Brake disc worn, pitted or scored, but not seriously weakened Both fronts (1.1.1	L4 (a) (ii))
FailNearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Offside Rear Hydraulic brake calliper leaking and braking performance affected (1.	1.16 (b) (ii))
Advice Brake pedal wearing smooth (1.1.2 (c))	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #14		2019-01-11 09:52
MOT test	number	107495265351
Result		✓ Passed
Advice	Nearside Front Oil leak, but not excessive drive shaft oil seal (8.4.1 (a) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



BN57AOG report date: 2024-03-28

MOT #13	2019-01-07 15:36		
MOT test number	745333737079		
Result	🗙 Failed		
Advice Offside Rear Nail in tyre			
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))			
Advice Nearside Front Oil leak, but not excessive drive shaft oil seal (8.4.1 (a) (i))			
Fail Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))			
Fail Offside Front Tyre tread depth below requirements of 1.6mm 225/40/r18 (5.2.3 (e))	2))		
Advice Central Front Undertray not fully secure (8.1.1 (b) (i))			
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Fail Nearside Rear Axle swivel pins and bushes swivel pin and/or bush excessively wo	rn (5.1.2 (b) (i))		

MOT #12	2018-01-05 16:32
MOT test	number 569868673554
Result	✓ Passed
Advice	Oil leak
Advice (2.4.G.2)	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Advice (2.4.G.2)	Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement
Advice	Offside Rear tyre had excessive cuts to sidewall (but not deep enough to reach ply or cord)
Advice (2.4.G.2)	Offside Rear Inner Radius arm rubber bush deteriorated but not resulting in excessive movement
Advice	Offside Rear Outer Tie bar/rod has slight play in a pin/bush (2.4.G.2)
Advice (2.4.G.2)	Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
Advice (2.4.G.2)	Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement
Advice movement	Nearside Rear Inner Radius arm rubber bush deteriorated but not resulting in excessive t (2.4.G.2)





MOT #11	2017-01-09 15:58
MOT test number	935113679022
Result	✓ Passed
Advice Engine cover and undertray fitted	
MOT #10	2016-07-05 08:41
MOT test number	284550328991
Result	✓ Passed
MOT #9	2015-07-16 11:17
MOT test number	405887695169
Result	✓ Passed
MOT #8	2015-01-14 11:38
MOT test number	445994515073
Result	✓ Passed
Notice Both front tyres worn unevenly low on inner and outer edges	
Notice GB sticker on rear number plate not in correct position	
MOT #7	2015-01-14 08:49

MOT #7	2015-01-14 08:49
MOT test number	498164515047
Result	🗙 Failed
Notice GB sticker on rear number plate not in correct position	
Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)	
Fail Offside Front Suspension arm ball joint dust cover excessively deteriorated so prevents the ingress of dirt (2.4.G.2)	that it no longer
Notice Both front tyres worn unevenly low on inner and outer edges	
Fail Offside Outer Front constant velocity joint gaiter deteriorated to the extent the the ingress of dirt etc (2.5.C.1a)	at it no longer prevents
Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	



B	Ν	5	7/	40		G
	repo	ort d	date:	2024	4-03	3-28

MOT #6		2014-01-13 11:13
MOT test	number	757313014018
Result		✓ Passed
Notice	Items removed from driver's view prior to test	
Advice (2.4.G.2)	Offside Front Suspension arm ball joint dust cover deteriorated, but preve	nting the ingress of dirt
Notice	Fuel cap broken but still maintains a seal	

MOT #5		2013-01-16 09:33
MOT test	number	595826513019
Result		✓ Passed
Notice	Items removed from driver's view prior to test	
Notice	Light damage to offside front road wheel inner bead rim	
Notice	Fuel cap is broken but still maintains a seal	
Notice	Damage to nearside rear floor pan	

MOT #4	2013-01-16 09:33	
MOT test number	157226513048	
Result	🗙 Failed	
Notice Light damage to offside front road wheel inner bead rim		
Notice Fuel cap is broken but still maintains a seal		
Pass with rectification Offside Front Windscreen wiper blade insecure	(8.2.2)	
Notice Damage to nearside rear floor pan		
Notice Items removed from driver's view prior to test		
Pass with rectification Nearside Front Windscreen wiper blade insecur	re (8.2.2)	





MOT #3	2012-01-13 11:44
MOT test number	945003512074
Result	✓ Passed
MOT #2	2011-01-17 14:51
MOT test number	889927711082
Result	✓ Passed
Notice Covers over door sills	
Notice Under trays fitted	

	2010-10-15 09:25
number	332978380290
	✓ Passed
Rear Direction indicators slightly discoloured (1.4.A.2f)	
O/s/f tyre has cut in it	
Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Child seat fitted not allowing full inspection of adult belt	
	Rear Direction indicators slightly discoloured (1.4.A.2f) O/s/f tyre has cut in it Nearside Front Tyre worn close to the legal limit (4.1.E.1)





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-10-19
Last registration	2022-07-05
Complete history	See info



Registration #1	2007-10-19	23 mi
Registration #2	2010-10-15	56.459 mi
Registration #3	2011-01-17	58.605 mi
Registration #4	2012-01-13	66.374 mi
Registration #5	2013-01-16	73.906 mi
Registration #6	2014-01-13	88.791 mi
Registration #7	2015-01-14	96.813 mi
Registration #8	2015-01-14	96.813 mi
Registration #9	2015-07-16	99.663 mi
Registration #10	2016-07-05	106.467 mi
Registration #11	2017-01-09	110.603 mi
Registration #12	2018-01-05	115.775 mi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.777 esi
Registration #18		11.777 esi
Registration #19		11.777 esi
Registration #20		11.777 esi
Registration #21		11.777 esi
Registration #22		11.317 est
Registration #23		11.777 mi

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2035 kg
Additional information	
Additional information Fuel tank capacity	61 l
	61 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 4