



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT GT TDI DSG DPF 140
Colour	Black
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-09-11
Pictures	54
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-03-02
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	57
Total items failed	12

MOT #202023-03-03 08:47

MOT test number359772767636

Result✓ Passed

Next expiry date2024-03-02

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Front Upper Anti-roll bar linkage ball joint has slight play Lower (5.3.4 (a) (i))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Bothsides (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #19**

2023-02-25 12:00

**MOT test number**

236641911775

**Result****✗ Failed**

**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Offside Front Upper Anti-roll bar linkage ball joint has slight play Lower (5.3.4 (a) (i))

**DANGEROUS** Nearside Rear Brake pipe connection leaking on a hydraulic braking system (1.1.11 (b) (ii))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Bothsides (1.1.14 (a) (ii))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #18**

2022-02-03 15:11

**MOT test number**

520312899896

**Result****✓ Passed**

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

**MOT #17**

2021-02-26 10:13

**MOT test number**

584222706745

**Result****✓ Passed**

**MOT #16** 2021-02-24 12:16**MOT test number** 827272940403**Result** ✗ Failed**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #15** 2020-02-26 15:57**MOT test number** 474325025893**Result** ✓ Passed**MOT #14** 2019-02-16 12:43**MOT test number** 195919245229**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Outer Suspension arm pin or bush worn but not resulting in excessive movement spring hanger (5.3.4 (a) (i))**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2019-02-09 11:06

**MOT test number**

851240820839

**Result****✗ Failed**

- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))
- Advice** Nearside Rear Outer Suspension arm pin or bush worn but not resulting in excessive movement spring hanger (5.3.4 (a) (i))
- Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2018-02-14 16:21

**MOT test number**

593274362465

**Result****✓ Passed**

- Advice** Nearside Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
- Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #11**

2018-02-12 11:44

**MOT test number**

288651697897

**Result**

✗ Failed

**Fail** Nearside Side repeater not working (1.4.A.2c)**Advice** Nearside Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #10**

2017-02-14 13:56

**MOT test number**

522855728132

**Result**

✓ Passed

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear tyre worn on inner edge**Advice** Engine management light on**MOT #9**

2017-02-14 11:45

**MOT test number**

876013963719

**Result**

✗ Failed

**Advice** Nearside Rear tyre worn on inner edge**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Headlamp aim not tested (1.8.A.1c)**Advice** Engine management light on**Fail** Front Windscreen wiper does not clear the windscreen effectively split (8.2.2)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)

**MOT #8** 2016-02-04 11:46**MOT test number** 671327164153**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-02-04 10:50**MOT test number** 384041025379**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim too low (1.8)**MOT #6** 2015-02-17 14:16**MOT test number** 907418645095**Result** ✓ Passed**Advice** Nearside Lower Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #5** 2014-02-06 10:24**MOT test number** 959947434039**Result** ✓ Passed**MOT #4** 2012-09-10 15:03**MOT test number** 479544252259**Result** ✓ Passed



**MOT #3** 2012-09-07 11:02**MOT test number** 905631752284**Result** ✗ Failed**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Direction indicator damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #2** 2011-09-02 12:34**MOT test number** 296185841219**Result** ✓ Passed**MOT #1** 2011-09-02 12:34**MOT test number** 779535841272**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 February 2025

✗  
**MOT**  
  
Expired:  
2 March 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	2 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>LR58RXY</b>
Plate since	2019-06-29
Current registration	 <b>LR58RXY</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-19
Last registration	2023-03-03
Complete history	<a href="#">See info</a>



Registration #1	2008-09-19	22 mi
Registration #2	2011-09-02	29.134 mi
Registration #3	2012-09-07	36.906 mi
Registration #4	2012-09-10	36.983 mi
Registration #5	2014-02-06	46.078 mi
Registration #6	2015-02-17	53.488 mi
Registration #7	2016-02-04	60.414 mi
Registration #8	2016-02-04	60.414 mi
Registration #9	2017-02-14	67.884 mi
Registration #10	2017-02-14	67.888 mi
Registration #11	2018-02-12	72.681 mi
Registration #12	2019-03-20	75.277 mi
Registration #13	2019-03-20	75.277 mi
Registration #14	2019-03-20	75.277 mi
Registration #15	2019-03-20	75.277 mi
Registration #16	2019-03-20	75.277 mi
Registration #17	2019-03-20	75.277 mi
Registration #18	2019-03-20	75.277 mi
Registration #19	2019-03-20	75.277 mi
Registration #20	2019-03-20	75.277 mi
Registration #21	2019-03-20	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1486 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5



Number of seats	5
Engine number	BKD C39550