





General information

| Make | VOLKSWAGEN | |
|---------------------|--------------------------------|--|
| Model | TRANSPORTER T30 LWB P/V 174TDI | |
| Colour | Silver | |
| Year of manufacture | 2007 | |
| Top speed | 117 mph | |
| 0 - 60 mph | 12.0 seconds | |
| Gearbox | 6 speed Manual | |

Engine & fuel consumption

| Power | 172 BHP |
|-----------------|---------------------|
| Max. torque | 400 Nm at 2.000 rpm |
| Engine capacity | 2.460 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| | |







Internet history

Entry 1

Date

Pictures

2021-09-18

3

Listing price

View report



source: cargurus.co.uk





MOT history

| MOT expiry date | 2025-02-02 |
|--------------------|------------|
| MOT pass rate | 68 % |
| MOT passed | 15 |
| Failed MOT tests | 7 |
| Total advice items | 30 |
| Total items failed | 15 |

| MOT #22 | 2024-02-03 11:59 |
|------------------|------------------|
| MOT test number | 992928593972 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-02 |

| MOT #21 | 2024-02-02 09:04 |
|--|------------------|
| MOT test number | 906475151550 |
| Result | × Failed |
| Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) | |
| Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |
| Fail Windscreen washer not working (3.5 (a)) | |
| Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |

| МОТ #20 | 2023-06-20 15:46 |
|---|------------------|
| MOT test number | 815334318965 |
| Result | ✓ Passed |
| Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) | |





| MOT #19 | 2022-07-26 07:56 |
|-----------------|------------------|
| MOT test number | 210189678565 |
| Result | ✓ Passed |
| | |
| MOT #18 | 2021-09-29 14:20 |
| MOT test number | 867189881705 |
| Result | ✓ Passed |
| | |
| MOT #17 | 2021-09-29 14:20 |
| MOT test number | 807239016723 |

| Result | × Failed |
|-------------------------------------|--|
| Pass with rectification (i)) | Offside Front Inner Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) |
| Pass with rectification (i)) | Nearside Front Inner Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) |
| Pass with rectification | Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |

| MOT #16 | | 2020-12-22 16:11 |
|----------|--|------------------|
| MOT test | number | 537546491981 |
| Result | | ✓ Passed |
| Advice | Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) | |

| MOT #15 | 2020-12-22 11:16 | |
|--|------------------------|--|
| MOT test number | 369715242447 | |
| Result | × Failed | |
| Fail Nearside Front Lower Suspension arm pin or bush excessively worn front most | bush (5.3.4 (a) (i)) | |
| Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) | | |
| Fail (b) (ii))Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the | ingress of dirt (5.3.4 | |





| MOT #14 | 2019-11-15 14:15 |
|--|--|
| MOT test number | 404406337175 |
| Result | ✓ Passed |
| Advice Offside Front Anti-roll bar pin or bu | ush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice Nearside Front Anti-roll bar pin or (i)) | bush worn but not resulting in excessive movement (5.3.4 (a) |
| Minor Nearside Front Anti-roll bar linkage | ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |
| Advice Nearside Front Upper Macpherson (5.3.4 (a) (i)) | strut pin or bush worn but not resulting in excessive movement |
| MOT #13 | 2019-11-15 14:15 |

MOT test number 418097308941 Result × Failed Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a)) Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

| MOT #12 | | 2018-10-16 14:03 |
|----------|--|---------------------|
| MOT test | number | 162793719409 |
| Result | | ✓ Passed |
| Advice | Front Anti-roll bar pin or bush worn but not resulting in excessive movem | ent (5.3.4 (a) (i)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice | Offside Rear Shock absorbers light misting of oil or has limited damping e | effect (5.3.2 (b)) |





| MOT #11 | 2018-10-11 15:45 | |
|--|------------------------|--|
| MOT test number | 948586610638 | |
| Result | 🗙 Failed | |
| Advice Offside Rear Shock absorbers light misting of oil or has limited damping ef | fect (5.3.2 (b)) | |
| Fail Brake fluid contaminated (1.8 (a)) | | |
| Advice Front Anti-roll bar pin or bush worn but not resulting in excessive movement | ent (5.3.4 (a) (i)) | |
| Fail Offside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) | | |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | | |
| Fail Nearside Front Lower Suspension component ball joint dust cover no longer p dirt (5.3.4 (b) (ii)) | revents the ingress of | |

| MOT #10 | | 2017-11-15 11:37 |
|----------|---|------------------|
| MOT test | number | 595167363636 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Nail in tyre | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #9 | 2017-11-15 11:37 |
|---|------------------|
| MOT test number | 981512483418 |
| Result | 🗙 Failed |
| Advice Nearside Rear Nail in tyre | |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Pass with rectification Offside Rear Stop lamp not working (1.2.1b) | |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |





| MOT #8 | | 2016-11-10 09:54 |
|-------------------------|--|------------------|
| MOT test number | | 984272747453 |
| Result | | ✓ Passed |
| | | |
| MOT #7 | | 2016-11-10 09:54 |
| MOT test number | | 816982971139 |
| Result | | 🗙 Failed |
| Pass with rectification | Rear Registration plate lamp not working both (1.1.C.1d) | |

| MOT #6 | 2015-11-12 13:43 |
|-----------------|------------------|
| MOT test number | 257658110160 |
| Result | ✓ Passed |

| MOT #5 | | 2014-11-14 17:02 |
|----------|--|------------------|
| MOT test | number | 997438114365 |
| Result | | ✓ Passed |
| Advice | Rear registration plate deteriorated but not likely to be misread (6.3.1d) | |
| Notice | Under-trays fitted obscuring some underside components | |
| Advice | Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Notice | Power steering pump slightly noisey | |

| MOT #4 | | 2013-11-11 16:33 |
|----------|--|------------------|
| MOT test | number | 677105313371 |
| Result | | ✓ Passed |
| Notice | Ns mirror trim not 100% | |
| Notice | Under-trays fitted obscuring some underside components | |






| MOT #3 | 2012-11-05 07:38 |
|-----------------|------------------|
| MOT test number | 496020512366 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2011-04-27 09:57 |
| MOT test number | 219017411422 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2010-05-01 07:56 |
| MOT test number | 614661420156 |
| Result | ✓ Passed |





Tax & MOT check







Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E CAT ON |
| Date | * |
| Category | AMP |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******** | |
|--|-------------|
| | |
| | |
| ********** | |
| ANALY AND A ANALY ANY ANY ANY ANY ANY ANY ANY ANY ANY AN | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| | |
| Plate sites | |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 24 |
| First mileage registration | 2007-04-16 |
| Last registration | 2024-02-03 |
| Complete history | See info |



| Registration #1 | 2007-04-16 | 21 mi |
|------------------|------------|------------|
| Registration #2 | 2010-05-01 | 29.087 mi |
| Registration #3 | 2011-04-27 | 36.875 mi |
| Registration #4 | 2012-11-05 | 50.242 mi |
| Registration #5 | 2013-11-11 | 60.091 mi |
| Registration #6 | 2014-11-14 | 70.212 mi |
| Registration #7 | 2015-11-12 | 78.955 mi |
| Registration #8 | 2016-11-10 | 79.994 mi |
| Registration #9 | 2016-11-10 | 79.994 mi |
| Registration #10 | 2017-11-15 | 89.001 mi |
| Registration #11 | 2017-11-15 | 89.001 mi |
| Registration #12 | 2018-10-11 | 94.031 mi |
| Registration #13 | | 11.777 esi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 esi |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 esi |
| Registration #18 | | 11.777 es |
| Registration #19 | | 11.777 esi |
| Registration #20 | | 11.777 est |
| Registration #21 | | 11.777 esi |
| Registration #22 | | 11.777 est |
| Registration #23 | | 11.777 esi |
| | | |
| Registration #24 | | 11.777 ed |

More info \rightarrow





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| 50482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Dimensions & weight

| Width | 2175 mm |
|-------------|---------|
| Height | 1940 mm |
| Length | 4707 mm |
| Kerb weight | 1927 kg |

Additional information

| Fuel tank capacity | 80 l |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 3 |
| Engine number | BPC 032280 |