





report date: 2024-03-28

General information

Make	BMW
Model	X1 SDRIVE18D SE
Colour	Black
Year of manufacture	2016
Top speed	127 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	330 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history


Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-04
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	10
Total items failed	6

MOT #8	2023-10-05 09:42
MOT test number	677466609463
Result	✓ Passed
Next expiry date	2024-10-04
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Brake pad indicator illuminated	

2022-09-16 08:45
841416248512
✓ Passed


NO SUIT	Viassea
MOT #6	2022-09-02 13:50
MOT test number	700491219678
Result	× Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2021-09-09 14:34
MOT test number	841958720350
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28



MOT #3 2020-08-27 11:12 **MOT test number** 449800626663 Result **X** Failed Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) Fail Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) Front Windscreen washer not working (3.5 (a)) Fail Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #2	2019-10-03 07:48
MOT test number	611923356732
Result	✓ Passed
Advice Chips to windscreen	
Advice Damage to underside	

MOT #1	2019-10-02 14:29
MOT test number	873352666639
Result	≍ Failed
Advice Chips to windscreen	
Advice Damage to underside	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

LM66SYE

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this BMW had different number plates.

More info >

CarCheck.co.uk page 8/11



LM66SYE report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-10-24
Last registration	2023-10-05
Complete history	See info



Registration #1	2016-10-24	29 mi
Registration #2	2019-10-02	109.005 mi
Registration #3	2019-10-03	109.005 mi
Registration #4	2020-08-27	144.610 mi
Registration #5	2020-09-03	144.614 mi
Registration #6		11.777 es
Registration #7		9.70 es
Registration #8		11.777 es
Registration #9		0.00-44

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1821 mm
Height	1598 mm
Length	4439 mm
Wheel base	2670 mm
Kerb weight	1470 kg
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11,

Number of axles 2

Engine number 57639753