





report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER 4C HT DT 89
Colour	Red
Year of manufacture	1990
Gearbox	-MANUAL

Engine & fuel consumption

Engine capacity	2.495 cc
Fuel type	Diesel



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-09

Pictures 90

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

Advice

MOT expiry date	2022-06-28
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	51
Total items failed	14

MOT #21	2021-06-10 13:53
MOT test number	878206653083
Result	✓ Passed
Next expiry date	2022-06-28
Advice Steering linkage ball joint has slight play Drop arm ball joint (2.1.3 (b) (i))	

MOT #20	2020-06-29 12:40
MOT test number	946856758994
Result	√ Passed
MOT #19	2019-06-12 11:55
MOT test number	181210135538
Result	✓ Passed

Central Lower Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18	2019-06-12 11:55	
MOT test number	438659751592	
Result	≍ Failed	
Pass with rectification Offside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))		
Advice Central Lower Oil leak, but not excessive (8.4.1 (a) (i))		
Pass with rectification (4.2.3 (c))	Offside Rear Position lamp adversely affected by the operation of another lamp	

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT test number

Result

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Central Lower Oil leak, but not excessive mid (8.4.1 (a) (i))

 MOT #16
 2017-06-21 09:59

 MOT test number
 376920503737

 Result
 ✓ Passed

MOT #15

MOT test number

967009584169

Result

✓ Passed

MOT #14 2015-06-12 12:18

MOT test number 105903765194

Result \sqrt{Passed}

Advice Offside Rear Lower Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

Notice Rear number plate deteriorating

Advice Nearside Rear Lower Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

Notice Nearside front swivel seal starting to leak oil.

Offside outrigger/body mounting slightly corroded

Advice Nearside Front Upper Suspension component mounting prescribed area is corroded but not

considered excessive (2.4.A.3)

Notice

CarCheck.co.uk page 4/15



report date: 2024-03-28

✓ Passed

MOT #13 2015-06-10 15:21

MOT test number 268171765137

Result X Failed

Notice Nearside front swivel seal starting to leak oil.

Fail Offside Front Upper Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

Advice Nearside Rear Lower Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Notice Offside outrigger/body mounting slightly corroded

Notice Rear number plate deteriorating

Pass with rectification Nearside Headlamp aim too high (1.8)

Advice Nearside Front Upper Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Advice Offside Rear Lower Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

Notice Rear exhaust deteriorated

MOT #12 2014-05-19 11:54

MOT test number 297689834196

Notice Oil leak

Result

Advice Front Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Offside Steering box has a slight oil leak (2.2.D.2e)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 5/15



Fail

G553WAC

report date: 2024-03-28

MOT #11 2014-05-06 10:39 **MOT** test number 845816324122 Result × Failed **Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d) Fail Offside Rear fog lamp not working (1.3.2b) Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Exhaust has a minor leak of exhaust gases (7.1.2) Offside Rear position lamp(s) incorrect colour (1.1.A.3e) Fail **Advice** Offside Steering box has a slight oil leak (2.2.D.2e) **Fail** Nearside Front Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a) **Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d) Fail Windscreen washer provides insufficient washer liquid (8.2.3) **Notice** Oil leak Fail Offside Drag link end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c) **Advice** Front Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

MOT #10	2013-05-08 09:20
MOT test number	635558523150
Result	✓ Passed
Advice Rear registration plate faded but not likely to be misread (6.3.1d)	

Offside Stop lamp emits other than a steady red light (1.2.1e)

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #9 2012-05-04 10:24

MOT test number 927295422118

Result ✓ Passed

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Nearside Seat belt damaged but webbing not significantly weakened (5.2.2a)

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Offside Seat belt damaged but webbing not significantly weakened (5.2.2a)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2011-05-16 14:35

MOT test number 736656231166

Result ✓ Passed

MOT #7 2010-05-21 14:59

MOT test number 334381840189

Result ✓ Passed

MOT #6 2010-05-13 15:54

MOT test number 253463630400

Result × Failed

Fail Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)

Fail Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

MOT #5 2009-05-21 11:44

MOT test number 780001849182

Result ✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #4 2008-06-03 14:51 **MOT** test number 762875158111 Result ✓ Passed **Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2) **Advice** Nearside Rear Coil spring mounting corroded but not seriously weakened (2.4.C.3c) Offside Rear Shock absorber has a slightly worn bush (2.7.4) Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f) Advice Advice Offside Rear Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

2008-06-03 14:51 **MOT #3** 572985658102 **MOT test number** Result ★ Failed **Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2) Advice Nearside Rear Coil spring mounting corroded but not seriously weakened (2.4.C.3c) **Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4) Pass with rectification Rear Exhaust system not adequately supported (7.1.1) Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f) **Advice** Offside Rear Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

MOT #2	2007-04-14 11:42
MOT test number	622364507160
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 8/15



report date: 2024-03-28

MOT #1		2006-04-05 13:01
MOT test	number	863975496007
Result		✓ Passed
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 9/15



report date: 2024-03-28

Tax & MOT check





Tax status Expired at 8 October 2021

Days left 933 days too late

MOT expiry date 28 June 2022

Full MOT history See MOT history

CarCheck.co.uk page 10/15



report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to)

	More info >	
Plate changes		
See in this check if this LAND ROVER had different number plates.		
Number of plates		
Current registration	NK NK	
Plate since		
Current registration	OK SIE	
Plate since		
	More info >	

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	1990-01-03
Last registration	2021-06-10
Complete history	See info



Registration #1	1990-01-03	15 mi
Registration #2	2006-04-05	122.063 mi
Registration #3	2007-04-14	127.310 mi
Registration #4	2008-06-03	130.066 mi
Registration #5	2009-05-21	142.316 mi
Registration #6	2010-05-13	142.942 mi
Registration #7	2010-05-21	143.000 mi
Registration #8	2011-05-16	144.337 mi
Registration #9	2012-05-04	148.161 mi
Registration #10	2013-05-08	155.786 mi
Registration #11	2014-05-06	162.690 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 esi
Registration #16		11.777 es
Registration #17		91.777 esi
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

Additional information

Engine number 19J33974C

CarCheck.co.uk page 15/15