





General information

Make	MERCEDES
Model	SPRINTER 311 CDI LWB CC
Colour	White
Year of manufacture	2007
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.600 rpm
Engine capacity	2.148 сс
Cylinders	4
Fuel type	Diesel





Internet history			
Entry 1			
Date	2022-06-26	5	
Pictures	4		
Listing price	View repor	t	
FULL service history	Choose from 12, 24 or 36 MONTHS peace-of-mind warranty for this vehicle	Vehicle arriving soon $c_{L} v c$	Image: Second system Image: Second system
source: cargurus.co.uk			



MOT history

MOT expiry date	2025-04-21
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	17
Total items failed	23

MOT #21	2024-04-22 14:13
MOT test number	718044172576
Result	✓ Passed
Next expiry date	2025-04-21
Advice Front Play in steering rack inner joint(s) Both sides	
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))	
Advice Rear Tyre slightly damaged/cracking or perishing Both sides (5.2.3 (d) (ii))	





MOT #20 2024-04-17 09:34
MOT test number 519890350097
Result X Failed
Fail Rear Registration plate missing (0.1 (a))
Advice Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Fail Offside Rear Suspension component mounting prescribed area so inadequately repaired that control of the vehicle is likely to be adversely affected Chassis been cut (5.3.6 (a) (ii))
Fail Nearside Front Side repeater not working (4.4.1 (a) (ii))
Advice Front Play in steering rack inner joint(s) Both sides
Fail Front Outline marker lamp not working Both sides (4.2.1 (a) (ii))
Fail Front Headlamps matched pair are not the same colour (4.1.4 (d))
Advice Rear Tyre slightly damaged/cracking or perishing Both sides (5.2.3 (d) (ii))
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail Nearside Rear Suspension component mounting prescribed area so inadequately repaired that control of the vehicle is likely to be adversely affected Chassis been cut (5.3.6 (a) (ii))
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail Nearside Rear Outline marker lamp not working (4.2.1 (a) (ii))

MOT #19	2023-04-21 15:09	
MOT test number	825262043026	
Result	✓ Passed	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))		





MOT #18	2023-04-21 14:42	
MOT test number	513334086465	
Result	🗙 Failed	
Fail Rear Registration plate lamp inoperative in the case of a single lamp or all la	mps (4.7.1 (b) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))		
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))		

MOT #17		2022-04-07 14:14
MOT test	number	288978822967
Result		✓ Passed
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #16	2021-02-01 13:12
MOT test number	226336586519
Result	✓ Passed

MOT #15		2021-02-01 13:12
MOT test number		970194252366
Result		🗙 Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))	

MOT #14	2019-11-13 15:18
MOT test number	799701193530
Result	✓ Passed





MOT #3	13	2019-11-13 10:46
MOT te	st number	463597714804
Result		🗙 Failed
Fail	Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))	
Fail	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Fail	Front Registration plate inscription illegible (0.1 (b))	
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #12	2018-11-19 15:20
MOT test number	514907835103
Result	✓ Passed

MOT #:	11	2018-11-19 10:41
MOT te	st number	556048019688
Result		🗙 Failed
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail	Nearside Front Position lamp not working (4.2.1 (a))	
Fail	Central Outer All position lamps not working (4.2.1 (a))	
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail	Offside Front Position lamp not working (4.2.1 (a))	

MOT #10	2017-10-24 10:37
MOT test number	139190309702
Result	🗸 Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #9	2016-11-11 13:33
MOT test number	446944320802
Result	✓ Passed
Result	V T USSEU
MOT #8	2015-11-12 18:22
MOT test number	509826270315
Result	✓ Passed
MOT #7	2014-11-21 12:36
MOT test number	566275324343
Result	✓ Passed
МОТ #6	2013-11-18 10:53
MOT test number	105382723324
Result	✓ Passed
MOT #5	2013-11-18 10:53
MOT test number	145442723334
Result	🗙 Failed
Pass with rectification Offside Rear position lamp(s) not working (1.1.A.3b)	
MOT #4	2012-11-20 15:10
MOT test number	959145322369
Result	✓ Passed

MOT #3	2011-11-21 13:47
MOT test number	677285821349
Result	✓ Passed






MOT #2	2010-11-18 10:52
MOT test number	214412020372
Result	✓ Passed
MOT #1	2010-10-27 12:42
MOT test number	540550300367
Result	✓ Passed



Tax & MOT check







Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-10-01
Last registration	2024-04-22
Complete history	See info



Registration #1	2007-10-01	25 mi
Registration #2	2010-10-27	77.353 mi
Registration #3	2010-11-18	77.497 mi
Registration #4	2011-11-21	107.384 mi
Registration #5	2012-11-20	126.514 mi
Registration #6	2013-11-18	147.548 mi
Registration #7	2014-11-21	155.976 mi
Registration #8	2015-11-12	169.428 mi
Registration #9	2016-11-11	189.426 mi
Registration #10	2017-10-24	204.303 mi
Registration #11	2018-11-19	226.568 mi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.117 est
Registration #21		11.777 esi
Registration #22		11.117 est



Safety ratings

NCAP rating

Video

see crash video



1990 mm
2820 mm
6940 mm
4325 mm
2005 kg
3500 kg
75 I
Direct Injection
3
2
64698551333054