





report date: 2024-03-29

General information

Make	LAND ROVER
Model	DEFENDER
Colour	Red
Year of manufacture	2010
Gearbox	-

Engine & fuel consumption

Engine capacity	2.400 cc
Fuel type	Diesel



CarCheck.co.uk page 1/15



report date: 2024-03-29


Internet history

Entry 1


Date 2021-12-20


Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT history

MOT expiry date	2024-12-01
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	44
Total items failed	21

MOT #16		2023-11-30 17:42
MOT test	number	848940030729
Result		✓ Passed
Next exp	iry date	2024-12-01
Advice	Oil leak, but not excessive gearbox (8.4.1 (a) (i))	
Advice	Oil leak, but not excessive rear diff (8.4.1 (a) (i))	
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))	
Advice	Oil leak, but not excessive front diff (8.4.1 (a) (i))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Minor	Nearside Front Position lamp with a multiple light source up to 1/2 not functioni	ng (4.2.1 (a) (i))

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #15 2023-11-29 09:48

MOT test number 756248690706

Result X Failed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Oil leak, but not excessive gearbox (8.4.1 (a) (i))

Minor Nearside Front Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Oil leak, but not excessive rear diff (8.4.1 (a) (i))

Fail Central Obligatory mirror missing (3.3 (a))

Advice Oil leak, but not excessive engine (8.4.1 (a) (i))

Advice Oil leak, but not excessive front diff (8.4.1 (a) (i))

MOT #14 2022-11-29 09:45

MOT test number 941563354941

Result

Passed

Advice Steering lock not working (immobilizer fitted)

Advice Engine exhaust heat Shield loose

MOT #13 2021-12-02 15:24

MOT test number 563041422164

Result

Passed

Advice Brake pipe corroded, covered in grease or other material Downward pipe from master cylinder (1.1.11 (c))

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #12 2021-11-24 13:01 **MOT** test number 167327483775 Result × Failed Fail Nearside Headlamp aim too high (4.1.2 (a)) Fail Nearside Front Lower Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail Offside Headlamp aim too low (4.1.2 (a)) **Advice** Brake pipe corroded, covered in grease or other material Downward pipe from master cylinder (1.1.11 (c)) Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #11		2020-03-18 11:55
MOT test	number	562371589903
Result		✓ Passed
Advice	Steering linkage ball joint has slight play pitman arm (2.1.3 (b) (i))	
Advice	Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Oil leak, but not excessive gearbox (8.4.1 (a) (i))	
Advice	Fluid leak, but not excessive rear diff (8.4.1 (a) (i))	
Advice	Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Fluid leak, but not excessive front diff (8.4.1 (a) (i))	

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #10 2020-03-13 09:36 **MOT** test number 914600230119 Result × Failed **Advice** Fluid leak, but not excessive rear diff (8.4.1 (a) (i)) **Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c)) Nearside Front Seat belt not functioning as intended (7.1.2 (c)) Fail Offside Rear Suspension component pin or bush excessively worn front trailing arm bush (5.3.4 (a) (i)) Fail Fluid leak, but not excessive front diff (8.4.1 (a) (i)) **Advice** Steering linkage ball joint has slight play pitman arm (2.1.3 (b) (i)) **Advice** Fail Front Registration plate inscription illegible (0.1 (b)) **Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c)) Fail Nearside Rear Suspension component pin or bush excessively worn front trailing arm bush (5.3.4 (a) (i)) **Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))

 MOT #9
 2019-03-25 11:45

 MOT test number
 762065260079

 Result
 ✓ Passed

MOT #8 2019-03-23 12:31
MOT test number 839706389984

Result × Failed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Rear Brake pipe excessively corroded chalked (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #7 2018-01-02 12:21

MOT test number 265563171336

Result ✓ Passed

MOT #6 2017-01-20 17:14

MOT test number 884983102890

Result ✓ Passed

MOT #5 2016-01-18 12:04

MOT test number 383084697145

Result ✓ Passed

MOT #4 2015-01-23 15:57

MOT test number 637403225046

Result ✓ Passed

Notice Front wipers do not park automaticly

Advice Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

Notice Slight corrosion on rear coil spring

Notice Front reg plate damaged

Advice Parking brake lever has little reserve travel (3.1.6b)

Notice Oil leak on rear diff

Advice Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

CarCheck.co.uk page 7/15



Fail

Offside Rear Stop lamp not working (1.2.1b)

PN10NBF

report date: 2024-03-29

MOT #3 2014-12-18 12:40 128872054397 **MOT** test number Result × Failed Fail Offside Front Headlamp aim too high (1.8) Notice Slight corrosion on n/s/r coil spring Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a) Fail Nearside Front position lamp(s) not working (1.1.A.3b) **Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d) **Notice** Oil leak on rear diff Fail Nearside Rear Stop lamp not working (1.2.1b) Fail Nearside Front Headlamp aim too high (1.8) **Notice** Nail in nearside front tyre Fail Offside Front brake caliper leaking (3.6.A.1) Fail Nearside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a) **Notice** Front wiper blades do not park automatically Fail Offside Front position lamp(s) not working (1.1.A.3b) **Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #2	2014-05-24 13:25
MOT test number	166434644149
Result	✓ Passed
MOT #1	2013-06-08 09:56
MOT test number	746749453184
Result	✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-29

Tax & MOT check



Days left 15

MOT expiry date 1 December 2024

Full MOT history See MOT history

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download to	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	NIE NIE
Plate since	
Current registration	UK ZIN
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-08
Last registration	2023-11-30
Complete history	See info



Registration #1	2010-06-08	6 mi
Registration #2	2013-06-08	34.648 mi
Registration #3	2014-05-24	54.869 mi
Registration #4	2014-12-18	66.911 mi
Registration #5	2015-01-23	68.021 mi
Registration #6	2016-01-18	85.979 mi
Registration #7	2017-01-20	98.130 mi
Registration #8	2018-01-02	106.645 mi
Registration #9	2019-03-23	107.615 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 mg

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

Additional information

Number of seats	2

Engine number ELD00080611101618

CarCheck.co.uk page 15/15