



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	ML ML 350
Colour	Black
Year of manufacture	2004
Top speed	128 mph
0 - 60 mph	8.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	245 BHP
Max. torque	350 Nm at 3.500 rpm
Engine capacity	3.724 cc
Cylinders	6
Fuel type	Petrol
Consumption city	14.6 mpg
Consumption extra urban	25.7 mpg
Consumption combined	20.0 mpg
CO2 emission	305 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-08-28
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-10-18
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	82
Total items failed	64

**MOT #23**

2021-11-09 13:48

MOT test number

125815615006

Result**✗ Failed**

- Fail** Central Seat belt not functioning as intended middle row (7.1.2 (c))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Fail** Offside Rear Passenger's seat insecure rear row (6.2.6 (a) (ii))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Front All direction indicators incorrect colour (4.4.3 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Passenger's seat insecure rear row (6.2.6 (a) (ii))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm bold inner edge (5.2.3 (e))
- Minor** Offside Front Tyre obviously under inflated (5.2.3 (l))
- Advice** Covered in under seal lower part of vehicle
- Fail** Power steering pipe/hose leaking 2 pipes at top of rack (2.1.5 (a))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #22**

2021-09-20 11:35

MOT test number

698374138247

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Power steering pipe/hose has slight seepage at rack**Advice** Under Seal coated**MOT #21**

2021-09-15 15:07

MOT test number

911586599586

Result

✗ Failed

Advice Power steering pipe/hose has slight seepage at rack**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Under Seal coated**MOT #20**

2020-10-19 17:56

MOT test number

324676122520

Result

✓ Passed

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Power steering pipe/hose has slight seepage at rack (2.1.5 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #19** 2019-10-17 19:27**MOT test number** 544218509538**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #18** 2017-08-17 16:53**MOT test number** 774411425685**Result** ✓ Passed**MOT #17** 2016-07-28 14:00**MOT test number** 668447656138**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Brake pipe slightly corroded on top of chassis in engine bay (3.6.B.2c)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Brake pipe slightly corroded both front to rear (3.6.B.2c)



MOT #16	2016-07-11 15:51
MOT test number	444913223864
Result	✗ Failed
Fail	Offside Front Brake pipe excessively corroded on top of c hassis (3.6.B.2c)
Fail	Nearside Front Brake pipe excessively corroded (3.6.B.2c)
Fail	Nearside Brake pipe excessively corroded both front to rear (3.6.B.2c)
Fail	Offside Front Front wheel bearing has excessive play (2.5.A.3c)
Fail	Offside Headlamp aim too low (1.8)
Fail	Offside Front Brake pipe excessively corroded (3.6.B.2c)
Fail	Horn not working (1.6.2a)
Fail	Nearside Headlamp aim too low (1.8)

MOT #15	2015-03-26 12:27
MOT test number	658925785036
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)



MOT #14	2015-03-23 15:59
MOT test number	256072085081
Result	✗ Failed
Fail	Offside Front Brake pipe excessively corroded (3.6.B.2c)
Fail	Nearside Front Brake pipe excessively corroded (3.6.B.2c)
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
Fail	Offside Front Brake pipe excessively corroded (3.6.B.2c)
Fail	Nearside Front Brake pipe excessively corroded (3.6.B.2c)
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #13**

2015-02-26 12:55

MOT test number

846397855034

Result**✗ Failed**

- Fail** Offside Front front brake excessively fluctuating (3.7.B.3)
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Advice** Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)
- Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)
- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)
- Fail** Offside Rear Anti-roll bar linkage fractured (2.4.G.1)
- Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)
- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #12

2014-03-07 12:37

MOT test number

626786164099

Result**✓ Passed**

- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #11** 2014-03-04 17:38**MOT test number** 219133064052**Result** ✗ Failed

- Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Centre Rear Brake pipe excessively corroded (3.6.B.2c)
- Fail** Power steering inoperative (2.3.3a)
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Brake pipe excessively corroded (3.6.B.2c)

MOT #10 2013-03-29 14:39**MOT test number** 405778383054**Result** ✓ Passed**MOT #9** 2013-03-27 11:54**MOT test number** 387076383007**Result** ✗ Failed

- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Rear coil spring fractured (2.4.C.1a)



MOT #8	2012-01-20 14:06
MOT test number	286030522051
Result	✓ Passed
Advice	Brake pipe slightly corroded (3.6.B.2c)
Advice	Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #7	2010-12-15 11:54
MOT test number	712859640383
Result	✓ Passed
Advice	Rear rear brake grabbing slightly (3.7.A.5b)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



MOT #6

2010-01-07 09:50

MOT test number

172387200459

Result		✓ Passed
Notice	VEHICLE IS FITTED WITH A REAR TOW BAR	
Advice	Offside Rear Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Outer Rear brake disc slightly pitted (3.5.1h)	
Notice	VEHICLE TESTED IN COLD AND ICEY CONDITIONS	
Advice	Nearside Rear Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Outer Rear brake disc slightly pitted (3.5.1h)	
Advice	Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)	
Advice	Nearside Front Direction indicator slightly discoloured (1.4.A.2f)	



MOT #5 2010-01-07 09:32

MOT test number 783277900072

Result ✗ Failed

Advice Nearside Rear Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice VEHICLE TESTED IN COLD AND ICEY CONDITIONS

Fail Centre Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Notice VEHICLE IS FITTED WITH A REAR TOW BAR

Fail Offside Front Headlamp aim too high (1.8)

Advice Nearside Outer Rear brake disc slightly pitted (3.5.1h)

Advice Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)

Fail Offside Front Lower Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)

Advice Offside Rear Anti-roll bar linkage corroded but not seriously weakened (2.4.G.1)

Notice WINDSCREEN WASHERS WHERE NOT WORKING AT THE START OF THE TEST..BUT ARE WORKING NOW????

Fail Nearside Front Headlamp aim too high (1.8)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Child seat fitted not allowing full inspection of adult belt

Fail Offside Front Direction indicator incorrect colour (1.4.A.2f)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Outer Rear brake disc slightly pitted (3.5.1h)



MOT #42008-12-02 15:14

MOT test number480167938444

Result

✓ Passed

- Notice

Advise slight corrossion on exhaust
- Advice

Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice

Advise childseat fitted nearside rear
- Notice

Advise sidesteps fitted
- Advice

Offside Front Direction indicator slightly discoloured (1.4.A.2f)

**MOT #3**

2008-12-01 09:53

MOT test number

611106638338

Result**✗ Failed**

- Fail** Parking brake: efficiency below requirements (3.7.C.1b)
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Notice** Advise childseat fitted nearside rear
- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Fail** Offside Rear Registration plate lamp not working (1.1.5c)
- Notice** Advise sidesteps fitted
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front Headlamp aim too low (1.8)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Notice** Advise slight corrosion on exhaust
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Front Headlamp aim too low (1.8)
- Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)



MOT #2	2007-11-26 16:11
MOT test number	583370737300
Result	✓ Passed
MOT #1	2007-02-20 10:31
MOT test number	161711057483
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
14 August 2021

X

MOT

Expired:
18 October 2022

Tax status	Expired at 14 August 2021
Days left	988 days too late
MOT expiry date	18 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-01-06
Last registration	2021-11-09
Complete history	See info



Registration #1	2004-01-06	15 mi
Registration #2	2007-02-20	20.792 mi
Registration #3	2007-11-26	25.763 mi
Registration #4	2008-12-01	41.701 mi
Registration #5	2008-12-02	41.701 mi
Registration #6	2010-01-07	48.906 mi
Registration #7	2010-01-07	48.906 mi
Registration #8	2010-12-15	53.439 mi
Registration #9	2012-01-20	59.958 mi
Registration #10	2013-03-27	65.536 mi
Registration #11	2013-03-29	65.536 mi
Registration #12	2014-03-04	70.719 mi
Registration #13	2014-03-07	70.719 mi
Registration #14	2014-03-07	70.719 mi
Registration #15	2014-03-07	70.719 mi
Registration #16	2014-03-07	70.719 mi
Registration #17	2014-03-07	70.719 mi
Registration #18	2014-03-07	70.719 mi
Registration #19	2014-03-07	70.719 mi
Registration #20	2014-03-07	70.719 mi
Registration #21	2014-03-07	70.719 mi
Registration #22	2014-03-07	70.719 mi
Registration #23	2014-03-07	70.719 mi
Registration #24	2014-03-07	70.719 mi
Registration #25	2014-03-07	70.719 mi



Dimensions & weight

Width	2190 mm
Height	1820 mm
Length	4710 mm
Wheel base	2820 mm
Kerb weight	2185 kg

Additional information

Fuel tank capacity	83 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	11297031689056