





General information

Make	MERCEDES
Model	SPRINTER 311 CDI LWB P/V
Colour	White
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.600 rpm
Engine capacity	2.148 сс
Cylinders	4
Fuel type	Diesel





MOT history

MOT expiry date	2021-01-25
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	15
Total items failed	3

MOT #10		2019-07-26 11:41
MOT test	number	190962642120
Result		✓ Passed
Next expi	ry date	2021-01-25
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Play in steering rack inner joint(s)	

MOT #9

MOT test number

2018-07-21 08:42

786874601382

Result

✓ Passed

MOT #8	2017-05-30 14:11
MOT test number	272398173228
Result	✓ Passed
Advice Offside Front slight play in suspension shock absorber / strut	
Advice Offside Front Play in steering rack inner joint(s)	
Advice Nearside Front Play in steering rack inner joint(s)	





MOT #7	2017-05-26 09:12
MOT test number	783098302781
Result	🗙 Failed
Fail Nearside rear brake recording little or no effort (3.7.B.5a)	
Advice Offside Front Play in steering rack inner joint(s)	
Advice Offside Front slight play in suspension shock absorber / strut	
FailParking brake: efficiency below requirements (3.7.B.7)	
Advice Nearside Front Play in steering rack inner joint(s)	

МОТ #6	2016-05-16 12:49
MOT test number	831858511383
Result	✓ Passed
Advice Offside Front Macpherson strut has slight play in the sliding bush or gland absorber (2.5.B.1b)	d suspension strut / shock
Advice Nearside Rear Anti-roll bar linkage has slight play in a pin/bush link arm /	rod (2.4.G.2)
Advice Offside Front Lower slight play detected at steering rack inner joint/s	

MOT #5	2015-05-29 10:44
MOT test number	509269145180
Result	✓ Passed
MOT #4	2014-05-16 11:41
MOT test number	559736434127
Result	✓ Passed

Notice Play in steering rack inner joint(s)





MOT #3	2014-05-16 11:41
MOT test number	196696734159
Result	🗙 Failed
Pass with rectificationOffside Headlamp aim too high (1.8)NoticePlay in steering rack inner joint(s)	
MOT #2	2013-05-28 17:07

MOT test number	897128743157
Result	✓ Passed
Advice Offside Steering pivot point has slight play (2.2.B.1g)	
MOT #1	2012-05-24 14:58

	2012-03-24 14.30
MOT test number	978745942144
Result	✓ Passed



EX55EED report date: 2024-03-28

Tax & MOT check

X Untaxed	Х MOT
Tax expired: 7 August 2020	Expired: 25 January 2021
Tax status	Expired at 7 August 2020
Days left	1361 days too late
MOT expiry date	25 January 2021
Full MOT history	See MOT history





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Category	ANPLE .
Туре	We have a state of the state of
.) P =	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
See in this check in this MERCEDES had uncreate number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Current registration	
Current registration Plate since	





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2009-06-11
Last registration	2019-07-26
Complete history	See info



Registration #1	2009-06-11	23 mi
Registration #2	2012-05-24	52.013 mi
Registration #3	2013-05-28	65.575 mi
Registration #4	2014-05-16	94.782 mi
Registration #5	2015-05-29	105.383 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1960 mm
Height	3050 mm
Length	6940 mm
Kerb weight	2280 kg
Max. allowed weight	3500 kg
Additional information	
Additional information Fuel tank capacity	75 l
	75 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5