





report date: 2024-03-28

### General information

Make	LAND ROVER
Model	DEFENDER HT TDI 95
Colour	Green
Year of manufacture	1997
Gearbox	-MANUAL

## Engine & fuel consumption

Engine capacity	2.495 cc
Fuel type	Diesel



CarCheck.co.uk page 1/15



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-08-29

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history		
MOT expiry date	2	025-01-21
MOT pass rate		71 %
MOT passed	1	7
Failed MOT tests	7	
Total advice items	4	9
Total items failed	1	4
MOT #24		2024-01-22 11:58
MOT test number		308614049294
Result		<b>✓</b> Passed
Next expiry date		2025-01-21
MOT #23		2023-02-24 09:23
MOT test number		101244460655
Result		✓ Passed
MOT #22		2022-02-17 13:00
MOT test number		472212631705
Result		✓ Passed
MOT #21		2021-07-14 14:23
MOT test number		475713333585
Result		<b>✓</b> Passed
MOT #20		2021-07-14 14:23
MOT test number		447410116066
Result		<b>≍</b> Failed
Pass with rectification	Rear fog lamp not working (4.5.1 (a)	(ii))

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #19

MOT test number

244940566723

Result

Advice Power steering pipe/hose has slight seepage at reservoir (2.1.5 (a))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #18** 2019-05-20 09:11 **MOT** test number 307700054217 Result **X** Failed Offside Windscreen wiper blade defective wiper poor (3.4 (b) (i)) Minor Fuel hose leaking on engine (6.1.3 (b) (i)) **MAJOR** Advice Power steering pipe/hose has slight seepage at reservoir (2.1.5 (a)) **MAJOR** Registration plate lamp missing in the case of a single lamp or all lamps number plate not located within lamp perimeter (4.7.1 (b) (ii)) Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i)) Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **MAJOR** 

MOT #17	2018-02-21 16:46
MOT test number	802563804105
Result	✓ Passed
Advice Brake pipe slightly corroded front an Advice Nearside Front wheel bearing has sl	

CarCheck.co.uk page 4/15



report date: 2024-03-28

**MOT #16** 2018-02-20 09:04

MOT test number 418734383443

**Result** X Failed

**Advice** Steering system lightly rubbing centre guide bracket on front axle rubbing partially on track rod (2.2.D.2a)

Fail Nearside Stop lamp not working (1.2.1b)

**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)

**Fail** Central Rear Upper Tie bar/rod ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt on axle (2.4.G.2)

**Fail** Front registration plate deteriorated (6.3.1d)

**Fail** Exhaust has a major leak of exhaust gases centre section (7.1.2)

**Advice** Brake pipe slightly corroded front and rear (3.6.B.2c)

MOT #15 2017-02-21 11:23

MOT test number 549028265085

Result \( \sqrt{Passed} \)

**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)

**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**Advice** Offside Front coil spring corroded (2.4.C.1b)

**Advice** Oil leak

**Advice** Nearside Front coil spring corroded (2.4.C.1b)

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #14 2016-02-26 15:09 391359507893 **MOT** test number Result ✓ Passed **Advice** Windscreen wipers poor Nearside Front coil spring corroded (2.4.C.1b) Advice Advice Exhaust corroded Advice Front registration plate deteriorated but not likely to be misread (6.3.1d) Offside Front coil spring corroded (2.4.C.1b) Advice **Advice** Oil leak

MOT #13

MOT test number

Result

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Notice Oil leak

MOT #12

MOT test number

Result

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Notice Oil leak

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT test number
906366354046

Result
Notice Oil leak
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #10** 2013-03-18 09:21 **MOT** test number 599097973002 Result ✓ Passed **Advice** Rear Upper Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4) **Advice** Notice Oil leak Advice Front registration plate deteriorated but not likely to be misread (6.3.1d) **Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

MOT test number

359766612050

Result

Notice Oil leak

Advice Offside Rear Shock absorber has a slightly reduced damping effect (2.7.5)

Notice All Front Steering Dust Covers Detiorated

Advice Nearside Rear Shock absorber has a slightly reduced damping effect (2.7.5)

 MOT #8
 2011-01-18 09:07

 MOT test number
 226548711046

 Result
 ✓ Passed

CarCheck.co.uk page 7/15



Result

**P2690EW** 

report date: 2024-03-28

**X** Failed

MOT #7 2011-01-17 10:42

**MOT test number** 285297611010

Result X Failed

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #6 2010-01-14 09:21

**MOT test number** 143414810404

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Headlamp aim too low (1.8)

**Notice** O/s/r & n/s/r shock top bushes slight wear

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Pass with rectification** Offside Stop lamp not working (1.2.1b)

**Pass with rectification** Offside Headlamp aim too low (1.8)

MOT #5 2010-01-14 09:21

MOT test number 124234010405

**Result** 
✓ Passed

**Notice** O/s/r & n/s/r shock top bushes slight wear

MOT #4 2009-01-20 10:05

**MOT test number** 334640629005

Result Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Oil leak

**Notice** All tyres poor condition/perishing and losing shape

**Advice** Front Exhaust has part of the system slightly deteriorated (7.1.1a)

CarCheck.co.uk page 8/15



report date: 2024-03-28

MOT #3 2009-01-19 10:25 **MOT test number** 320219519055 Result ★ Failed Fail Offside Front Seat belt has a cut which has significantly weakened the webbing (5.2.2a) Front Exhaust has part of the system slightly deteriorated (7.1.1a) **Advice** Fail Nearside Stop lamp not working (1.2.1b) Notice Oil leak **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Notice All tyres poor condition/perishing and losing shape

MOT #2	2008-02-14 15:02
MOT test number	320415448001
Result	<b>✓</b> Passed
MOT #1	2006-09-28 08:56
MOT test number	232021776257
Result	<b>✓</b> Passed

CarCheck.co.uk page 9/15



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	21 January 2025
Full MOT history	See MOT history

CarCheck.co.uk page 10/15



report date: 2024-03-28

### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

Owner	hictory
OWITEI	HIISLULY

C Wile Prince of	
For how long did the current and previous owner(s) have this LAND ROVER? How many on ROVER have? Check it in the premium report and see all owner registrations. Download to	
manage of the same	
***************************************	
	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-28

### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	1997-06-26
Last registration	2024-01-22
Complete history	See info



Registration #1	1997-06-26	8 mi
Registration #2	2006-09-28	26.117 mi
Registration #3	2008-02-14	29.032 mi
Registration #4	2009-01-19	32.454 mi
Registration #5	2009-01-20	32.454 mi
Registration #6	2010-01-14	33.765 mi
Registration #7	2011-01-17	35.045 mi
Registration #8	2011-01-18	35.045 mi
Registration #9	2012-01-16	36.218 mi
Registration #10	2013-03-18	37.622 mi
Registration #11	2014-02-25	38.525 mi
Registration #12	2015-02-23	38.805 mi
Registration #13		11.777 es
Registration #14		77,777 46
Registration #15		71.777 es
Registration #16		77,777 46
Registration #17		71.777 66
Registration #18		77,777 46
Registration #19		71.777 66
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		71.777 es
Registration #23		11.777 66

More info >



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Adult	85%
Children	85%
Pedestrian	71%
Safety systems	79%
Overall rating	81%
Video	see crash video



## Additional information

Number of axles	2
Engine number	23L20493A

CarCheck.co.uk page 15/15