





General information

Make	MERCEDES-BENZ
Model	SPRINTER 313 CDI
Colour	White
Year of manufacture	2010
Top speed	94 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP	0 < 101 A
Max. torque	305 Nm at 1.200 rpm	101 - 120 B
Engine capacity	2.143 сс	121 - 140 E
Cylinders	4	141 - 165 F G
Fuel type	Diesel	166 - 185 H
Consumption city	26.9 mpg	186 - 225 J
Consumption extra urban	38.7 mpg	225+ L
Consumption combined	33.6 mpg	



MOT history

MOT expiry date	2021-06-02
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	27
Total items failed	19

MOT #12	2020-06-03 08:41
MOT test number	912242100793
Result	✓ Passed
Next expiry date	2021-06-02

MOT #11		2019-03-23 07:09
MOT test	number	931701950212
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	



SV10UCG
report date: 2024-03-29

MOT #10		2018-05-02 17:15
MOT test	number	148193001805
Result		✓ Passed
Advice	Exhaust modified	
Advice	Slight oil leak	
Advice	All component under body slightly rusty	
Advice	Zero emission	
Advice	Parking reading low both front wheel bearings has slight play	
Advice	Under body slightly rusty all brake pipes slightly corroded	

МОТ #9	2018-05-01 07:50
MOT test number	306935685313
Result	🗙 Failed
Advice Slight oil leak	
Advice All component under body slightly rusty	
Pass with rectificationWindscreen washer provides insufficient washer liquid (8.2.3)	
Fail Offside Headlamp not working on dipped beam (1.7.5a)	
Advice Parking reading low both front wheel bearings has slight play	
Advice Under body slightly rusty all brake pipes slightly corroded	
Fail Exhaust has a major leak of exhaust gases (7.1.2)	
Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT #8	2017-02-16 08:31
MOT test number	956183127277
Result	✓ Passed
Advice All brake pipes slightly corroded	



MOT #7	2017-02-10 16:21
MOT test number	139647416544
Result	🗙 Failed
Fail Nearside Rear Rear reflector more than 50% obscured (1.5.1b)	
Fail Service brake: efficiency below requirements (3.7.B.7)	
Advice All brake pipes slightly corroded	
Fail Rear parking brake recording little or no effort (3.7.B.6a)	
Fail Offside Front front brake binding (3.7.B.1)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	
Fail Offside Front Front position lamp(s) not working (1.1.A.3b)	

MOT #6	2016-02-23 14:54
MOT test number	666136378329
Result	✓ Passed

MOT #5	2016-02-22 14:37
MOT test number	319115460545
Result	🗙 Failed
Fail Registration plate lamp not working (1.1.C.1d)	
Advice Both frt brake discs badly corroded	
Fail Nearside Front Steering arm has relative movement at its fixings (2.2.B.1h)	
Fail Front Brakes imbalanced across an axle (3.7.B.5b)	
Fail Exhaust system not adequately supported (7.1.1)	

SV10UCG

report date: 2024-03-29



S	V	1	0	U	С	G
I	repo	rt c	late	: 20	24-0	3-29

MOT #4		2015-03-27 09:05
MOT test	number	929286085056
Result		✓ Passed
Notice	High level brake light inop	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakene	d (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weaker	ned (3.5.1i)
MOT #3		2015-03-18 11:35
MOT test	number	969237375007
Result		🗙 Failed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakene	d (3.5.1i)
Fail N	learside Front Headlamp aim too low (1.8)	

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

Notice High level brake light inop

Fail Nearside Front Body has a sharp edge caused by damage (6.1.C.1)

Offside Rear rear parking brake recording little or no effort (3.7.B.6a) Fail

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #2	2014-03-13 12:13
MOT test number	399672374037
Result	✓ Passed
MOT #1	2013-03-12 10:46

MOT test number	639021373015
Result	✓ Passed

Fail





Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	A PLANE
Туре	
Damage 2	AMPLE
	A A A A A A A A A A A A A A A A A A A
Date	1. E
Category	ant
Туре	

Extra MERCEDES-BENZ salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

2000000	

And a second sec	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-03-19
Last registration	2020-06-03
Complete history	<u>See info</u>



Registration #1	2010-03-19	13 mi
Registration #2	2013-03-12	49.917 mi
Registration #3	2014-03-13	64.784 mi
Registration #4	2015-03-18	82.486 mi
Registration #5	2015-03-27	82.496 mi
Registration #6	2016-02-22	98.859 mi
Registration #7	2016-02-23	98.861 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 mi
Registration #13		11.117 mi

More info \rightarrow





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
50566	
\$0567	
S0569	

Dimensions & weight

Width	1993 mm
Height	2350 mm
Length	5870 mm
Wheel base	3665 mm
Kerb weight	1842 kg
Max. allowed weight	3500 kg
Additional information	

Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	65195530183776