





General information

Make	HYUNDAI
Model	MATRIX GSI
Colour	Blue
Year of manufacture	2005
Top speed	103 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	102 BHP
Max. torque	141 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.9 mpg
Consumption extra urban	31.0 mpg
Consumption combined	26.9 mpg
CO2 emission	198 g/km
CO2 label	J







Internet history

Entry	1
Date	


Pictures

2022-05-21

17

Listing price

View report



source: cargurus.co.uk



KD050EG report date: 2024-03-29

MOT history

MOT expiry date	2022-11-05
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	21
Total items failed	11

MOT #23	2021-11-02 16:25
MOT test number	256800427611
Result	✓ Passed
Next expiry date	2022-11-05

MOT #22	2020-11-06 15:00
MOT test number	863906955595
Result	✓ Passed

MOT #21	2020-11-05 14:20
MOT test number	963693503820
Result	🗙 Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #20	2019-05-09 13:38
MOT test number	219393035953
Result	✓ Passed





MOT #19		2019-04-16 11:33
MOT test	number	926073466212
Result		✓ Passed
Advice	Power steering belt cracking	
Minor (6.1.7 (g)	Offside Front Outer Drive shaft joint constant velocity boot severely deteriora (i))	ated deeply cracked
Advice	BOTH n/s and o/s front lower arm rear bushes split	
Advice	Power steering pipe/hose has slight seepage high pressure hose (2.1.5 (a))	
Minor (6.1.7 (g)	Nearside Front Outer Drive shaft joint constant velocity boot severely deterio (i))	orated deeply cracked

MOT #18	2018-04-17 15:21
MOT test number	299177152867
Result	✓ Passed

MOT #:	17	2018-04-17 10:10
MOT te	st number	183795812741
Result		🗙 Failed
Fail	Nearside Rear Brake pipe excessively corroded (3.6.B.2c)	
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT #16		2017-04-05 12:35
MOT test	number	108624029394
Result		Passed
Advice	Offside Headlamp deteriorated but light output not reduced (1.7.5a)	
Advice	Nearside Headlamp deteriorated but light output not reduced (1.7.5a)	





MOT #15		2017-04-05 09:53
MOT test	number	721179683750
Result		🗙 Failed
Advice	Offside Headlamp deteriorated but light output not reduced (1.7.5a)	
Advice	Nearside Headlamp deteriorated but light output not reduced (1.7.5a)	
Fail O	ffside Front position lamp(s) not working (1.1.A.3b)	

MOT #14	2016-04-19 12:40
MOT test number	314409904763
Result	✓ Passed
Advice Nearside steering rack gaitor oily	

MOT #13	2016-04-19 10:21
MOT test number	539329948420
Result	🗙 Failed
FailSupplementary Restraint System warning lamp indicates a fault (5.4.2)AdviceNearside steering rack gaitor oily	

MOT #12		2015-04-22 11:05
MOT test i	number	929802015114
Result		✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Notice	Both fron tyres worn on inner edge	



KD050EG
report date: 2024-03-29

MOT #11	2014-05-16 11:05
MOT test number	295346034477
Result	✓ Passed
Notice Both outer cv boots perished	
Notice Both front lower arm rear bushes slightly perished	
MOT #10	2014-05-15 10:23
MOT test number 229835	

		229039031101
Result		🗙 Failed
Notice	Both outer cv boots perished	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Both front lower arm rear bushes slightly perished	
Fail N	learside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)	

МОТ #9	2013-05-16 12:33
MOT test number	687536033144
Result	✓ Passed

MOT #8		2013-05-16 12:33
MOT test number		405436133160
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too high and too far to the right. (1.8)	

MOT #7	2012-05-10 13:12
MOT test number	296241832153
Result	✓ Passed



KD050EG
report date: 2024-03-29

MOT #6		2012-05-10 11:27
MOT test number		718321232113
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too high (1.8)	
Fail Nearside Headlamp	insecure (1.7.3)	

MOT #5	2011-05-11 10:57
MOT test number	385461931152
Result	✓ Passed

MOT #4		2011-05-11 10:57
MOT test number		128581731149
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
Pass with rectification	Offside Headlamp aim too high (1.8)	

MOT #3		2010-05-10 12:16
MOT test	number	451380130131
Result		✓ Passed
Notice	Air con belt cracked	
Notice	Front brake pads becoming low	
Notice	Damp with oil around n/s/f power steering rack gaitor	

MOT #2	2009-04-30 11:59
MOT test number	631390529123
Result	✓ Passed





MOT #1	2008-05-15 10:23
MOT test number	190266638124
Result	✓ Passed



KD050EG report date: 2024-03-29

Tax & MOT check

X Untaxed Tax expired: 1 February 2023	X MOT Expired: 5 November 2022
Tax status	Expired at 1 February 2023
Days left	453 days too late
MOT expiry date	5 November 2022
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	······································
Category	AMP
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	1000-20-20
Current registration	
Plate since	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



KD050EG report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-05-19
Last registration	2021-11-02
Complete history	See info



Registration #2 20		14 mi 27.594 mi
-		27.594 mi
Pogistration #2		
	009-04-30	33.712 mi
Registration #4 20	010-05-10	39.138 mi
Registration #5 20	011-05-11	43.562 mi
Registration #6 20	012-05-10	46.973 mi
Registration #7 20	012-05-10	46.973 mi
Registration #820	013-05-16	50.120 mi
Registration #9 20	014-05-15	54.424 mi
Registration #1020	014-05-16	54.424 mi
Registration #11 20	015-04-22	58.822 mi
Registration #12 20	016-04-19	63.391 mi
Registration #13		11.777 mi
Registration #14		11.317 mi
Registration #15		11.777 mi
Registration #16		11.317 mi
Registration #17		11.717 mi
Registration #18		11.317 mi
Registration #19		11.777 mi
Registration #20		11.317 mi
Registration #21		11.777 mi
Registration #22		11.117 mi
Registration #23		11.777 mi
Registration #18		

More info >





Car features

S0225	Air conditionin
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1740 mm
Height	1625 mm
Length	4025 mm
Wheel base	2600 mm
Kerb weight	1349 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4ED5097564