



report date: 2024-03-28

General information

Make	FIAT
Model	500 LOUNGE
Colour	Grey
Year of manufacture	2017
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	110 g/km
CO2 label	B





Internet history

Entry 2

Date	2022-02-06
Pictures	26
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-04
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	6
Total items failed	3

MOT #7 2024-03-05 15:25

MOT test number 757526114488

Result ✓ Passed

Next expiry date 2025-03-04

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rearward bush debonding (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rearward bush debonding (5.3.4 (a) (i))

Advice Offside Rear Integral body structure is deformed but structural rigidity is not significantly reduced quarter going into the door shut (6.1.1 (a) (i))

MOT #6 2024-02-28 14:34

MOT test number 883365970021

Result ✗ Failed

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure outside sidewall (5.2.3 (d) (ii))

Advice Offside Rear Integral body structure is deformed but structural rigidity is not significantly reduced quarter going into the door shut (6.1.1 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rearward bush debonding (5.3.4 (a) (i))

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure outer sidewall (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rearward bush debonding (5.3.4 (a) (i))

MOT #5 2023-03-02 11:57

MOT test number 410722339580

Result

✓ Passed



MOT #4	2022-03-04 07:53
MOT test number	882076428296
Result	✓ Passed
MOT #3	2021-08-05 11:59
MOT test number	738903443164
Result	✓ Passed
MOT #2	2021-08-05 08:06
MOT test number	692030259549
Result	✗ Failed
<div><div>Fail</div>Offside Rear Direction indicator not working (4.4.1 (a) (ii))</div>	
MOT #1	2020-09-26 14:25
MOT test number	814597523217
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
4 March 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	4 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-28
Current registration	*****
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-09-30
Last registration	2024-03-05
Complete history	See info



Registration #1	2017-09-30	20 mi
Registration #2	2020-09-26	15.624 mi
Registration #3	2020-09-26	15.624 mi
Registration #4	2021-08-05	15.646 mi
Registration #5	2021-08-05	15.646 mi
Registration #6	2021-08-05	15.646 mi
Registration #7	2021-08-05	15.646 mi
Registration #8	2021-08-05	15.646 mi
Registration #9	2021-08-05	15.646 mi
Registration #10	2021-08-05	15.646 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	66%
Children	49%
Pedestrian	53%
Safety systems	27%
Overall rating	52%
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1345 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2

Engine number	2181262
---------------	---------