



MJ07CBX

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 69BHP SDI VAN
Colour	White
Year of manufacture	2007
Top speed	88 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	140 Nm at 2.200 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-16
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-19
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	39
Total items failed	14

MOT #20 2023-10-20 17:33

MOT test number 178391854868

Result ✓ Passed

Next expiry date 2024-10-19

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))

MOT #19 2022-09-05 09:56

MOT test number 389646112068

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18 2021-10-07 06:50

MOT test number 489172190711

Result ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #17

2020-08-07 15:11

MOT test number

163760635490

Result

✓ Passed

- Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #16**

2020-08-06 12:10

MOT test number

103843555440

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Fail** Offside Windscreen wiper not working (3.4 (a))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Windscreen wiper not working (3.4 (a))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15

2019-01-08 10:34

MOT test number

109207106567

Result**✓ Passed**

- Advice** High level brake light cover missing but still shows red light

MOT #14

2019-01-07 15:45

MOT test number

110476634020

Result**✗ Failed**

- Advice** High level brake light cover missing but still shows red light
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #13** 2017-12-07 13:37**MOT test number** 730857581327**Result** ✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush (2.4.G.2)

MOT #12 2017-12-06 13:06**MOT test number** 757691403909**Result** ✗ Failed

Fail Nearside Front Lower Suspension arm has excessive play in a pin/bush Rear bush (2.4.G.2)

Fail Nearside Rear Stop lamp emits other than a steady red light (1.2.1e)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush (2.4.G.2)

MOT #11 2017-04-03 13:46**MOT test number** 791690645009**Result** ✓ Passed**MOT #10** 2015-10-26 10:55**MOT test number** 913493845839**Result** ✓ Passed**MOT #9** 2015-10-26 10:55**MOT test number** 214828303229**Result** ✗ Failed

Pass with rectification Nearside Stop lamp not working (1.2.1b)

Pass with rectification Nearside Front Direction indicator not working (1.4.A.2c)

Pass with rectification Offside Stop lamp not working (1.2.1b)

**MOT #8** 2015-03-31 11:06**MOT test number** 269550295081**Result** ✓ Passed**MOT #7** 2015-03-31 11:06**MOT test number** 327830495025**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #6** 2014-01-28 13:04**MOT test number** 768528524009**Result** ✓ Passed**MOT #5** 2014-01-27 09:35**MOT test number** 188817424456**Result** ✗ Failed**Fail** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #4** 2013-01-15 09:34**MOT test number** 655575513004**Result** ✓ Passed

**MOT #3** 2012-01-17 16:42**MOT test number** 315057212042**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Both rear tyres slightly perrished condition

MOT #2 2011-01-18 16:46**MOT test number** 156638711437**Result** ✓ Passed

- Notice** Both front brake disks slightly worn
- Notice** Both rear brake disks slightly worn

MOT #1 2010-04-19 14:04**MOT test number** 994409000179**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
19 October 2024

Tax status		Valid until 1 March
Days left		305
MOT expiry date		19 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-04-17
Last registration	2023-10-20
Complete history	See info



Registration #1	2007-04-17	24 mi
Registration #2	2010-04-19	28.025 mi
Registration #3	2011-01-18	32.807 mi
Registration #4	2012-01-17	46.883 mi
Registration #5	2013-01-15	60.293 mi
Registration #6	2014-01-27	71.684 mi
Registration #7	2014-01-28	71.684 mi
Registration #8	2015-03-31	83.889 mi
Registration #9	2015-10-26	94.043 mi
Registration #10	2015-10-26	94.043 mi
Registration #11	2017-04-03	104.235 mi
Registration #12	2019-05-20	115.277 mi
Registration #13	2019-05-20	115.277 mi
Registration #14	2019-05-20	115.277 mi
Registration #15	2019-05-20	115.277 mi
Registration #16	2019-05-20	115.277 mi
Registration #17	2019-05-20	115.277 mi
Registration #18	2019-05-20	115.277 mi
Registration #19	2019-05-20	115.277 mi
Registration #20	2019-05-20	115.277 mi
Registration #21	2019-05-20	115.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Length	4405 mm

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	BST 065437