



General information

Make	SUZUKI
Model	SX4 AERIO
Colour	Black
Year of manufacture	2010
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	145 Nm at 4.400 rpm
Engine capacity	1.590 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-12
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-01
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	18
Total items failed	6

MOT #14	2023-10-02 09:25
MOT test number	899874393354
Result	✓ Passed
Next expiry date	2024-10-01
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13	2022-09-17 09:38
MOT test number	764536062995
Result	✓ Passed
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12** 2021-09-28 16:44**MOT test number** 804060220646**Result** ✓ Passed**MOT #11** 2020-07-31 15:40**MOT test number** 564494460022**Result** ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10 2020-07-30 13:00**MOT test number** 876971643313**Result** ✗ Failed

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #9 2019-07-23 11:52**MOT test number** 893663741681**Result** ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8** 2019-07-23 11:52**MOT test number** 884899277219**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2018-07-26 15:51**MOT test number** 598975158029**Result** ✓ Passed**Advice** Offside Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #6** 2017-07-21 09:03**MOT test number** 522770993673**Result** ✓ Passed**MOT #5** 2017-07-21 09:03**MOT test number** 622414793192**Result** ✗ Failed**Pass with rectification** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**MOT #4** 2016-08-08 14:57**MOT test number** 121871528526**Result** ✓ Passed**MOT #3** 2015-09-18 11:00**MOT test number** 292714123313**Result** ✓ Passed



MOT #2	2014-09-23 11:14
MOT test number	629996264287
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2013-09-25 10:32
MOT test number	338598463272
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
1 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	1 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	YH60NKM
Plate since	2019-09-29
Current registration	YH60NKM
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-30
Last registration	2023-10-02
Complete history	See info



Registration #1	2010-09-30	6 mi
Registration #2	2013-09-25	19.170 mi
Registration #3	2014-09-23	25.453 mi
Registration #4	2015-09-18	31.950 mi
Registration #5	2016-08-08	36.948 mi
Registration #6	2017-07-21	38.818 mi
Registration #7	2017-07-21	38.818 mi
Registration #8	2018-07-26	39.941 mi
Registration #9	2019-05-29	40.277 mi
Registration #10	2019-05-29	40.277 mi
Registration #11	2019-05-29	40.277 mi
Registration #12	2019-05-29	40.277 mi
Registration #13	2019-05-29	40.277 mi
Registration #14	2019-05-29	40.277 mi
Registration #15	2019-05-29	40.277 mi
Registration #16	2023-10-02	40.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1565 mm
Length	4120 mm
Wheel base	2500 mm
Kerb weight	1156 kg
Max. allowed weight	1650 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1512412