





report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE
Colour	White
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-11


Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



CA64TDV report date: 2024-03-29

MOT history

MOT expiry date	2025-04-04
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	25
Total items failed	10

MOT #11	2024-04-05 11:08
MOT test number	942569816600
Result	✓ Passed
Next expiry date	2025-04-04

MOT #10		2023-07-13 10:36
MOT test	number	743815279242
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Exhaust mounting defective (6.1.2 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #9 2023-07-10 14:05 668375727548 **MOT** test number Result **★** Failed Fail Windscreen washer not working (3.5 (a)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b)) Fail Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii)) Fail Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) **Advice** Rear Exhaust mounting defective (6.1.2 (a))

MOT #8	2022-07-11 15:22
MOT test number	824924331363
Result	✓ Passed
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #7	2021-07-14 14:40
MOT test number	491969732987
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6 2020-10-13 08:50 **MOT** test number 691743959144 Result ✓ Passed **Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i)) Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice **Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

 MOT #5
 2019-11-11 10:28

 MOT test number
 497696464771

 Result
 ✓ Passed

MOT #4 2019-10-25 16:11
MOT test number 175932782611

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #3 2019-01-28 13:16

MOT test number 727781601294

Result
✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2		2018-01-24 14:16
MOT test	number	348495383977
Result		✓ Passed
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Nearside Rear Nail in tyre	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Front Track rod end ball joint has slight play (2.2.B.1f)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #1		2018-01-24 14:16
MOT test	number	647913188029
Result		× Failed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Nearside Rear Nail in tyre	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Pass wit	th rectification Front Headlamp aim too low (1.8)	
Advice	Nearside Front Track rod end ball joint has slight play (2.2.B.1f)	

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check





Tax status	Expired at 24 March 2024
Days left	37 days too late
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 10/13



CA64TDV report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-01-28
Last registration	2024-04-05
Complete history	See info



Registration #1	2015-01-28	18 mi
Registration #2	2018-01-24	22.190 mi
Registration #3	2018-01-24	22.190 mi
Registration #4	2019-01-28	30.496 mi
Registration #5	2019-10-25	35.201 mi
Registration #6	2019-11-11	35.216 mi
Registration #7	2020-10-13	40.800 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		70.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM0107961

CarCheck.co.uk page 13/13