



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 EXCLUSIVE HDI
Colour	Silver
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-07-11
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-02
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	32
Total items failed	15

MOT #21	2023-06-15 08:31
MOT test number	828084140072
Result	✓ Passed
Next expiry date	2024-07-02

MOT #20	2022-06-17 13:06
MOT test number	426501900304
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
Advice	High level stop light not working
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #19**

2022-06-13 10:44

MOT test number

918047275036

Result**✗ Failed****Advice** Nearside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** High level stop light not working**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Play in steering rack inner joint(s)**Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #18**

2021-06-22 15:52

MOT test number

679732443083

Result**✓ Passed****Advice** High level stop lamp in not working**Advice** Offside Play in steering rack inner joint(s)

**MOT #17**

2021-06-14 09:59

MOT test number

814295320848

Result**✗ Failed**

- Advice** Reverse lamps & high level stop lamp not working
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both inner faces (1.1.14 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #16

2020-06-17 08:07

MOT test number

260508944066

Result**✓ Passed**

- Advice** Offside Front Steering linkage ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Steering linkage ball joint has slight play (2.1.3 (b) (i))

MOT #15

2019-07-03 12:15

MOT test number

489840936441

Result**✓ Passed**

- Advice** Nearside rear tyre wearing thin edges of tread
- Advice** Play in steering rack inner joint(s) offside and nearside
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front tyres worn outer edges and perished edges

**MOT #14** 2019-06-26 07:35**MOT test number** 125830684010**Result** ✗ Failed**Advice** Play in steering rack inner joint(s) offside and nearside**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside rear tyre wearing thin edges of tread**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Front tyres worn outer edges and perished edges**MOT #13** 2018-06-25 08:53**MOT test number** 607235513439**Result** ✓ Passed**MOT #12** 2017-06-05 14:06**MOT test number** 386924758945**Result** ✓ Passed**Advice** 1/ screw in o/s rear tyre**MOT #11** 2016-07-01 08:11**MOT test number** 953509125230**Result** ✓ Passed**MOT #10** 2015-05-28 11:52**MOT test number** 495608945107**Result** ✓ Passed

**MOT #9** 2014-07-01 12:48**MOT test number** 906522084107**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #8** 2014-07-01 12:48**MOT test number** 248502984154**Result** ✗ Failed**Pass with rectification** Centre Stop lamp not working (1.2.1b)**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Notice** Under-trays fitted obscuring some underside components**MOT #7** 2013-07-17 10:36**MOT test number** 608828093165**Result** ✓ Passed**MOT #6** 2012-07-02 09:52**MOT test number** 688124582183**Result** ✓ Passed**MOT #5** 2011-07-04 11:29**MOT test number** 589135281163**Result** ✓ Passed**MOT #4** 2010-07-08 10:26**MOT test number** 600139380183**Result** ✓ Passed



MOT #3	2009-07-14 17:31
MOT test number	541855899132
Result	✓ Passed

MOT #2	2009-07-14 17:31
MOT test number	464995199189
Result	✗ Failed
<div>Pass with rectification</div> Nearside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)	
<div>Pass with rectification</div> Nearside Stop lamp not working (1.2.1b)	

MOT #1	2008-07-16 15:38
MOT test number	384878398165
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
2 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-07-31
Last registration	2023-06-15
Complete history	See info



Registration #1	2005-07-31	9 mi
Registration #2	2008-07-16	19.996 mi
Registration #3	2009-07-14	25.493 mi
Registration #4	2010-07-08	28.734 mi
Registration #5	2011-07-04	32.226 mi
Registration #6	2012-07-02	33.914 mi
Registration #7	2013-07-17	35.485 mi
Registration #8	2014-07-01	37.047 mi
Registration #9	2015-05-28	38.008 mi
Registration #10	2016-07-01	38.998 mi
Registration #11	2017-06-05	51.355 mi
Registration #12	2018-06-05	51.355 mi
Registration #13	2019-06-05	51.355 mi
Registration #14	2020-06-05	51.355 mi
Registration #15	2021-06-05	51.355 mi
Registration #16	2022-06-05	51.355 mi
Registration #17	2023-06-15	51.355 mi
Registration #18	2023-06-15	51.355 mi
Registration #19	2023-06-15	51.355 mi
Registration #20	2023-06-15	51.355 mi
Registration #21	2023-06-15	51.355 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1475 mm
Length	4745 mm
Wheel base	2750 mm
Kerb weight	1498 kg
Max. allowed weight	2018 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYTJ4134024