



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Black
Year of manufacture	2013
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-11-08
Pictures	47
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-18
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	23
Total items failed	2

MOT #10	2023-10-19 15:09
MOT test number	487248295922
Result	✓ Passed
Next expiry date	2024-10-18
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #9	2022-10-19 15:08
MOT test number	780518595877
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Nail in tyre
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2022-10-19 08:21**MOT test number** 721971306086**Result** ✗ Failed**Advice** Offside Front Nail in tyre**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #7** 2021-09-17 08:00**MOT test number** 548450413462**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Anti-roll bar linkage corroded but not seriously weakened both (5.3.3 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2020-09-18 15:52**MOT test number** 213346152719**Result** ✓ Passed**Advice** Tyre slightly damaged/cracking or perishing Both rear (5.2.3 (d) (ii))**MOT #5** 2019-04-23 16:13**MOT test number** 243515001405**Result** ✓ Passed**Advice** Tyre slightly damaged/cracking or perishing Both rear 235/65/17 (5.2.3 (d) (ii))

**MOT #4** 2018-04-14 09:19**MOT test number** 164675156614**Result** ✓ Passed**Advice** Oil leak around sump area and rear of engine**MOT #3** 2017-04-22 08:20**MOT test number** 808839767925**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Oil leak**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2017-04-22 08:20**MOT test number** 475601309072**Result** ✗ Failed**Advice** Oil leak**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2016-04-23 09:58**MOT test number** 303781470373**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
18 October 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	18 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>AV13GDA</b>
Plate since	2019-06-29
Current registration	<b>AV13GDA</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-04-30
Last registration	2023-10-19
Complete history	<a href="#">See info</a>



Registration #1	2013-04-30	21 mi
Registration #2	2016-04-23	27.493 mi
Registration #3	2017-04-22	39.026 mi
Registration #4	2017-04-22	39.026 mi
Registration #5	2018-04-14	48.489 mi
Registration #6	2019-04-23	58.858 mi
Registration #7	2019-04-23	58.858 mi
Registration #8	2019-04-23	58.858 mi
Registration #9	2019-04-23	58.858 mi
Registration #10	2019-04-23	58.858 mi
Registration #11	2019-04-23	58.858 mi
Registration #12	2019-04-23	58.858 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 263998K LNQ