



report date: 2024-03-29

General information

Make	VOLVO
Model	S40
Colour	Black
Year of manufacture	2008
Gearbox	-

Engine & fuel consumption

Engine capacity	1.798 cc
Fuel type	Petrol
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-20
Pictures	21
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-23
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	12
Total items failed	8

MOT #16	2023-10-24 14:51
MOT test number	502222129500
Result	✓ Passed
Next expiry date	2024-10-23

MOT #15	2023-10-19 14:05
MOT test number	592397239898
Result	✗ Failed

- Fail** Offside Front Headlamp light intensity severely reduced (4.1.4 (a))
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement wishbone back round bush (5.3.4 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps x2 (4.7.1 (b) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt bottom ball joint (5.3.4 (b) (ii))

**MOT #14** 2022-10-04 15:15**MOT test number** 127471147819**Result** ✓ Passed

- Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge (5.2.3 (e))
- Advice** Rear Inner Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))
- Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge (5.2.3 (e))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))

MOT #13 2021-10-20 12:58**MOT test number** 961841549784**Result** ✓ Passed**MOT #12** 2020-10-20 09:19**MOT test number** 716103402659**Result** ✓ Passed**MOT #11** 2019-06-04 08:38**MOT test number** 837236352210**Result** ✓ Passed

- Advice** Tyre worn close to legal limit/worn on edge Both front & nearside rear (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10 2018-05-14 08:08**MOT test number** 179654191955**Result** ✓ Passed

**MOT #9** 2018-05-12 09:02**MOT test number** 386922202387**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Registration plate lamp not working offside and nearside (1.1.C.1d)**MOT #8** 2017-05-06 10:38**MOT test number** 924250338729**Result** ✓ Passed**MOT #7** 2016-05-25 12:22**MOT test number** 998786910719**Result** ✓ Passed**MOT #6** 2015-06-02 14:29**MOT test number** 418273655119**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-06-02 14:29**MOT test number** 819673455125**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #4** 2014-03-04 16:25**MOT test number** 965653164034**Result** ✓ Passed



MOT #3	2013-02-25 12:29
MOT test number	449766853048
Result	✓ Passed

MOT #2	2012-02-28 11:09
MOT test number	426979452066
Result	✓ Passed
<div>Advice Front Brake pad(s) wearing thin (3.5.1g)</div>	

MOT #1	2011-03-10 12:03
MOT test number	335049861072
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
23 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	23 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YY08FJP
Plate since	2019-03-29
Current registration	YY08FJP
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-04-21
Last registration	2023-10-24
Complete history	See info



Registration #1	2008-04-21	24 mi
Registration #2	2011-03-10	31.012 mi
Registration #3	2012-02-28	34.566 mi
Registration #4	2013-02-25	40.758 mi
Registration #5	2014-03-04	47.713 mi
Registration #6	2015-06-02	65.917 mi
Registration #7	2016-05-25	76.636 mi
Registration #8	2017-05-06	87.552 mi
Registration #9	2018-05-12	100.196 mi
Registration #10	2019-05-20	111.377 mi
Registration #11	2020-05-20	121.377 mi
Registration #12	2021-05-20	131.377 mi
Registration #13	2022-05-20	141.377 mi
Registration #14	2023-05-20	151.377 mi
Registration #15	2024-05-20	161.377 mi
Registration #16	2025-05-20	171.377 mi
Registration #17	2026-05-20	181.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats	4
Engine number	143891