



report date: 2024-03-29

General information

Make	FIAT
Model	500C 500C BY GUCCI
Colour	Red
Year of manufacture	2013
Top speed	107 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	92 g/km
CO2 label	A





Internet history

Entry 2



Date	2022-08-11
Pictures	26
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-02-09
Pictures	4
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2024-08-30
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	26
Total items failed	4

MOT #11 2023-08-09 09:50

MOT test number 746793985824

Result ✓ Passed

Next expiry date 2024-08-30

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #10 2022-08-31 11:04

MOT test number 632021308456

Result ✓ Passed

MOT #9 2022-08-26 08:19

MOT test number 506050609881

Result ✗ Failed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))



MOT #8	2021-08-17 10:42
MOT test number	861483472717
Result	✓ Passed
Advice	Rear Coil spring corroded Both (5.3.1 (b) (i))
Advice	Offside Rear Noise from brake drum when wheel spun
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Both shock absorbers heavily corroded
Minor	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Front Coil spring corroded Both (5.3.1 (b) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #7**

2021-08-17 09:01

**MOT test number**

291019282587

**Result****✗ Failed**

**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))

**Advice** Front Both shock absorbers heavily corroded

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Front Coil spring corroded Both (5.3.1 (b) (i))

**Advice** Auxiliary belt cracked and has chunks missing

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Rear Noise from brake drum when wheel spun

**MOT #6**

2020-09-22 16:37

**MOT test number**

542987572050

**Result****✓ Passed**

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on edges (5.2.3 (e))

**MOT #5** 2020-09-21 10:20**MOT test number** 240933900134**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on edges (5.2.3 (e))**MOT #4** 2019-06-24 14:45**MOT test number** 223694619981**Result** ✓ Passed**MOT #3** 2018-05-16 12:48**MOT test number** 194685715893**Result** ✓ Passed**MOT #2** 2017-05-30 14:18**MOT test number** 891712060660**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit wearing on inner edge (4.1.E.1)**MOT #1** 2016-06-01 08:03**MOT test number** 350259093011**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
30 August 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	30 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation


<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	KX13NKH
Plate since	2019-03-29
Current registration	KX13NKH
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-05-31
Last registration	2023-08-09
Complete history	<a href="#">See info</a>



Registration #1	2013-05-31	10 mi
Registration #2	2016-06-01	28.493 mi
Registration #3	2017-05-30	36.964 mi
Registration #4	2018-05-16	45.562 mi
Registration #5	2019-06-24	54.757 mi
Registration #6	2020-09-21	64.883 mi
Registration #7	2020-09-22	64.885 mi
Registration #8	2020-09-22	64.885 mi
Registration #9	2020-09-22	64.885 mi
Registration #10	2020-09-22	64.885 mi
Registration #11	2020-09-22	64.885 mi
Registration #12	2020-09-22	64.885 mi
Registration #13	2020-09-22	64.885 mi
Registration #14	2020-09-22	64.885 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	970 kg
Max. allowed weight	1385 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	0084251