





General information

| Make | PEUGEOT |
|---------------------|---------|
| Model | 206 |
| Colour | Blue |
| Year of manufacture | 2002 |
| Gearbox | - |

Engine & fuel consumption

| Engine capacity | 1.587 cc |
|-----------------|----------|
| Fuel type | Petrol |
| CO2 emission | 166 g/km |
| CO2 label | Н |







Internet history

| Entry 3 | |
|---------------|-------------|
| Date | 2021-09-09 |
| Pictures | 18 |
| Listing price | View report |



source: autotrader.co.uk

Date

Pictures

Listing price

2021-08-11 18

View report



source: autotrader.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-07-09 |
| Pictures | 18 |
| Listing price | View report |









source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-06-21 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 16 |
| Failed MOT tests | 4 |
| Total advice items | 18 |
| Total items failed | 8 |

| MOT #20 | 2023-06-22 08:12 |
|------------------|------------------|
| MOT test number | 192422074726 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-21 |

| MOT #19 | 2022-08-30 11:03 |
|---|------------------|
| MOT test number | 366116186963 |
| Result | ✓ Passed |
| Advice Offside Front Coil spring corroded (5.3.1 (b) (i)) | |

| MOT #18 | 2022-08-30 11:03 | |
|---|--|--|
| MOT test number | 118891032764 | |
| Result | × Failed | |
| Pass with rectification (ii)) | Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) | |
| Advice Offside Front Coil spring corroded (5.3.1 (b) (i)) | | |
| Pass with rectification | Offside Front Position lamp not working (4.2.1 (a) (ii)) | |

| MOT #17 | 2021-07-09 16:27 |
|-----------------|------------------|
| MOT test number | 653005841736 |
| Result | ✓ Passed |





| MOT #16 | 2018-09-04 16:27 |
|---------------------------------|---|
| MOT test number | 586986930020 |
| Result | ✓ Passed |
| | |
| MOT #15 | 2018-09-04 16:27 |
| MOT test number | 767485600502 |
| Result | × Failed |
| Pass with rectification | Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) |
| | |
| MOT #14 | 2017-12-21 09:29 |
| MOT test number | 570597499906 |
| Result | ✓ Passed |
| | |
| MOT #13 | 2017-12-21 08:54 |
| MOT test number | 436062857869 |
| Result | × Failed |
| Fail Offside Stop lamp n | ot working (1.2.1b) |

| MOT #12 | | 2016-12-06 12:55 |
|--|---------------------------|------------------|
| MOT test | number | 250126753753 |
| Result | | ✓ Passed |
| Advice Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i) | | |
| Advice | Sun visor needs attention | |



| RL02FNW |
|-------------------------|
| report date: 2024-03-29 |

| MOT #11 | 2016-12-06 09:10 |
|---|------------------|
| MOT test number | 631168910144 |
| Result | × Failed |
| Fail Nearside Side repeater incorrect colour (1.4.A.2f) | |
| Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so the prevents the ingress of dirt (2.4.G.2) | hat it no longer |
| Advice Sun visor needs attention | |
| FailNearside Headlamp not working on dipped beam (1.7.5a) | |
| Fail Exhaust has a major leak of exhaust gases second joint (7.1.2) | |
| Advice Front brake disc worn, pitted or scored, but not seriously weakened inner face (3. | 5.1i) |

| MOT #10 | 2015-12-10 14:30 | |
|--|--------------------|--|
| MOT test number | 716970517247 | |
| Result | ✓ Passed | |
| Advice Offside Outer Front constant velocity joint gaiter damaged, but preventing the (2.5.C.1a) | ne ingress of dirt | |
| Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | | |
| Advice Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2) | | |
| Advice Front Exhaust has a minor leak of exhaust gases (7.1.2) | | |

| MOT #9 | | 2014-12-16 12:04 |
|----------|--|------------------|
| MOT test | number | 469640654479 |
| Result | | ✓ Passed |
| Advice | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |
| Notice | Os checkstrap needs attention | |





| MOT #8 | | 2013-12-31 08:59 |
|----------|--|------------------|
| MOT test | number | 877505063322 |
| Result | | ✓ Passed |
| Notice | Screen scratched | |
| Advice | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |
| Notice | Os check strap needs attention | |
| | | |

| MOT #7 | | 2012-09-11 12:51 |
|---------|--|------------------|
| MOT tes | t number | 915845152231 |
| Result | | ✓ Passed |
| Notice | Screen scratched | |
| Advice | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |

| МОТ #6 | 2011-08-25 16:36 |
|-----------------|------------------|
| MOT test number | 186877731259 |
| Result | ✓ Passed |

| MOT #5 | 2010-08-27 11:31 |
|-----------------|------------------|
| MOT test number | 330899730220 |
| Result | ✓ Passed |

| МОТ #4 | 2009-08-27 10:15 |
|-----------------|------------------|
| MOT test number | 294239539233 |
| Result | ✓ Passed |

| MOT #3 | 2008-08-27 12:20 |
|-----------------|------------------|
| MOT test number | 802960048258 |
| Result | ✓ Passed |



| RLO | 2 F | N | W |
|------------|------------|------|--------|
| report | date: | 2024 | -03-29 |

| MOT #2 | 2007-08-02 14:15 |
|---|------------------|
| MOT test number | 804464917223 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2006-06-29 11:28 |
| MOT test number | 794490586178 |
| Result | ✓ Passed |
| Advice Front Tyre worn close to the legal limit (4.1.E.1) | |



Tax & MOT check

| ✓ Taxed | ✓ MOT Expires: |
|--------------------------|-----------------------------------|
| 1 May 2025 Tax status | 21 June 2024 Valid until 1 May |
| Days left | 366 |
| MOT expiry date | 21 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | н |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---|
| Date | |
| Category | 4. DEM PE |
| Туре | |
| Damage 2 | Annet |
| Date | No. Contraction of the second |
| Category | AMP |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ********** | |
| ******** | |
| ******* | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 24 |
| First mileage registration | 2002-07-10 |
| Last registration | 2023-06-22 |
| Complete history | See info |



| Registration #1 | 2002-07-10 | 18 mi |
|--|-------------|---|
| Registration #2 | 2006-06-29 | 13.028 mi |
| Registration #3 | 2007-08-02 | 23.361 mi |
| Registration #4 | 2008-08-27 | 26.340 mi |
| Registration #5 | 2009-08-27 | 29.799 mi |
| Registration #6 | 2010-08-27 | 33.381 mi |
| Registration #7 | 2011-08-25 | 35.196 mi |
| Registration #8 | 2012-09-11 | 38.420 mi |
| Registration #9 | 2013-12-31 | 41.008 mi |
| Registration #10 | 2014-12-16 | 43.331 mi |
| Registration #11 | 2015-12-10 | 44.844 mi |
| Registration #12 | 2016-12-06 | 46.551 mi |
| | | |
| Registration #13 | 10003-03-02 | 11.777 esi |
| | | 11.277 est |
| Registration #13 | | 11.377 esi 11.377 esi 11.377 esi |
| Registration #13 Registration #14 | | 01,707 esi 01,707 esi 01,707 esi 01,707 esi |
| Registration #13 Registration #14 Registration #15 | | 01.000 est 01.000 est 01.000 est 01.000 est 01.000 est |
| Registration #13 Registration #14 Registration #15 Registration #16 | | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |
| Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 | | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |
| Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 | | 10.000 est 1.000 est |
| Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 | | 10.000 est 1.000 est |
| Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 | | 10.000 est 10.000 |
| Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 | | 10.000 est 10.000 |
| Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 | | 10.000 est 10.000 |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| 50501 | |
| \$0566 | |
| \$0567 | |
| 50569 | |

Safety ratings

NCAP rating

Video

see crash video



Additional information

Engine number

NOT KNOWN