



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | VOLVO          |
| Model               | C70 D3 SE LUX  |
| Colour              | Red            |
| Year of manufacture | 2011           |
| Top speed           | 130 mph        |
| 0 - 60 mph          | 10.2 seconds   |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 148 BHP             |
| Max. torque             | 350 Nm at 1.500 rpm |
| Engine capacity         | 1.984 cc            |
| Cylinders               | 5                   |
| Fuel type               | Diesel              |
| Consumption city        | 35.8 mpg            |
| Consumption extra urban | 61.4 mpg            |
| Consumption combined    | 47.9 mpg            |
| CO2 emission            | 154 g/km            |
| CO2 label               | G                   |








Internet history

Entry 2


|               |                             |
|---------------|-----------------------------|
| Date          | 2022-03-13                  |
| Pictures      | 12                          |
| Listing price | <a href="#">View report</a> |



source: cargurus.co.uk

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-07                  |
| Pictures      | 18                          |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-04-12 |
| MOT pass rate      | 79 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 3          |
| Total advice items | 20         |
| Total items failed | 5          |

|                  |  |
|------------------|--|
| MOT #14          | 2024-04-10 13:55   |
| MOT test number  | 647746063692   |
| Result           | ✓ Passed   |
| Next expiry date | 2025-04-12   |
| Advice           | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                                      |
| Advice           | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))              |
| Advice           | Offside Power steering component has slight seepage from a component steering rack gaitor area (2.1.5 (a)) |
| Advice           | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                                     |
| Advice           | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))               |

**MOT #13**

2024-04-08 15:55

**MOT test number**

952155280902

**Result****✗ Failed**

- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Wipers not tested due to inoperative washers
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Power steering component has slight seepage from a component steering rack gaitor area (2.1.5 (a))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #12**

2023-04-11 11:55

**MOT test number**

798474721078

**Result****✓ Passed**

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11**

2022-04-13 12:48

**MOT test number**

453862937212

**Result****✓ Passed**

**MOT #10** 2021-07-14 09:50**MOT test number** 462715418406**Result** ✓ Passed**MOT #9** 2020-07-27 12:21**MOT test number** 442611713777**Result** ✓ Passed**MOT #8** 2019-06-27 15:17**MOT test number** 595969145209**Result** ✓ Passed**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #7** 2019-06-26 15:29**MOT test number** 123586770047**Result** ✗ Failed**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #6** 2018-06-28 15:23**MOT test number** 787868622941**Result** ✓ Passed**MOT #5** 2017-07-12 14:26**MOT test number** 272947664544**Result** ✓ Passed

**MOT #4** 2017-07-12 14:26**MOT test number** 397659900079**Result** ✗ Failed**Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)**MOT #3** 2016-07-20 12:46**MOT test number** 105440571799**Result** ✓ Passed**MOT #2** 2015-07-22 16:05**MOT test number** 836543105252**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2014-07-23 11:04**MOT test number** 246974404206**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
12 April 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 September         |
| <b>Days left</b>        | 125                             |
| <b>MOT expiry date</b>  | 12 April 2025                   |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | G          |
| <b>Single payment (12 months)</b>              | £ 240,00,- |
| <b>Single six month payment</b>                | £ 132,00,- |
| <b>Total payable by 12 monthly instalments</b> | £ 252,00,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-28    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-28    |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 17                       |
| First mileage registration | 2011-07-29               |
| Last registration          | 2024-04-10               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2011-07-29 | 20 mi     |
| Registration #2  | 2014-07-23 | 24.104 mi |
| Registration #3  | 2015-07-22 | 31.031 mi |
| Registration #4  | 2016-07-20 | 38.841 mi |
| Registration #5  | 2017-07-12 | 44.588 mi |
| Registration #6  | 2017-07-12 | 44.588 mi |
| Registration #7  | 2018-06-28 | 47.078 mi |
| Registration #8  | 2019-06-26 | 52.946 mi |
| Registration #9  | 2019-06-27 | 52.946 mi |
| Registration #10 | 2019-06-27 | 52.946 mi |
| Registration #11 | 2019-06-27 | 52.946 mi |
| Registration #12 | 2019-06-27 | 52.946 mi |
| Registration #13 | 2019-06-27 | 52.946 mi |
| Registration #14 | 2019-06-27 | 52.946 mi |
| Registration #15 | 2019-06-27 | 52.946 mi |
| Registration #16 | 2019-06-27 | 52.946 mi |
| Registration #17 | 2019-06-27 | 52.946 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1847 mm |
| Height              | 1400 mm |
| Length              | 4615 mm |
| Wheel base          | 2640 mm |
| Kerb weight         | 1773 kg |
| Max. allowed weight | 2130 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 60 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 2                |
| Number of seats    | 4                |

|               |         |
|---------------|---------|
| Engine number | 1030577 |
|---------------|---------|