






report date: 2024-03-28

### General information

Make	BMW
Model	316 316I COMP
Colour	Green
Year of manufacture	1998
Top speed	114 mph
0 - 60 mph	12.7 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	101 BHP
Max. torque	150 Nm at 3.900 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg



CarCheck.co.uk page 1/15




# Internet history

#### Entry 1

Date 2021-12-08

Pictures 35

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2025-01-02
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	25
Total items failed	10

MOT #25	2024-01-03 13:26
MOT test number	540235826625
Result	✓ Passed
Next expiry date	2025-01-02
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #24		2022-11-26 11:59
MOT test	number	499842265649
Result		✓ Passed
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	N/s rear parking brake effort slightly low	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Front fog lamps missing	

CarCheck.co.uk page 3/15



MOT #23 2022-11-26 11:59

MOT test number 569758338831

**Result** X Failed

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Pass with rectification** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Advice N/s rear parking brake effort slightly low

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Front fog lamps missing

MOT #22 2021-12-13 08:32

MOT test number 909813199784

**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin both side (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

Minor Nearside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #21 2021-01-11 10:11

**MOT test number** 972922976085

Result \( \sqrt{Passed} \)

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20** 2019-07-31 15:10

**MOT test number** 178369860222

**Result** ✓ Passed

CarCheck.co.uk page 4/15



Fail

R926JNV

report date: 2024-03-28

MOT #19

MOT test number

Result

Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #18** 2018-07-20 15:23 **MOT** test number 516670990917 Result ✓ Passed **MOT #17** 2018-07-19 13:48 **MOT** test number 330528916568 Result × Failed Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #16

MOT test number

Result

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Rear Brake pipe slightly corroded (3.6.B.2c)

Front Registration plate inscription illegible (0.1 (b))

MOT #15

MOT test number

Result

Advice Rear Brake pipe slightly corroded o/s and n/s. (3.6.B.2c)

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

CarCheck.co.uk page 5/15



R926JNV

report date: 2024-03-28

2013-08-16 12:17

2013-08-14 16:37

MOT #14

MOT test number

Result

Advice Rear registration plate faded but not likely to be misread (6.3.1d)

MOT test number
923149053882

Result

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Advice Rear registration plate faded but not likely to be misread (6.3.1d)

 MOT #12
 2014-08-18 09:24

 MOT test number
 268150534291

 Result
 ✓ Passed

MOT test number 876648523232

Result Passed

MOT test number 129436423280

Result X Failed

**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

Notice Hand brake travel quite high

MOT #11

**MOT #10** 

CarCheck.co.uk page 6/15



MOT #9	2012-08-20 08:54
MOT test number	648083432202
Result	<b>✓</b> Passed
MOT #8	2011-08-18 13:56
MOT test number	848340731202
Result	<b>✓</b> Passed
MOT #7	2010-08-23 12:31
MOT test number	653895130266
Result	<b>✓</b> Passed
MOT #6	2009-08-27 12:23
MOT test number	603739139272
Result	✓ Passed
MOT #5	2009-08-25 08:22
MOT test number	921007139248
Result	<b>X</b> Failed
Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT #4	2008-08-22 06:39
MOT test number	344495338267
Result	✓ Passed

CarCheck.co.uk page 7/15



MOT #3	2008-08-21 10:03
MOT test number	481294938228
Result	<b>X</b> Failed
Fail Nearside Rear Stop lamp not working (1.2.1b)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #2	2007-08-16 08:48
MOT test number	623948927262
Result	✓ Passed
MOT #1	2006-08-21 09:29
MOT test number	433833436289
Result	<b>✓</b> Passed


CarCheck.co.uk page 8/15



See MOT history

#### Tax & MOT check

**Full MOT history** 



CarCheck.co.uk page 9/15



R926JNV

report date: 2024-03-28

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



### Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report \( \frac{1}{2} \)	
THE STATE OF THE S	
********	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



# Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	1998-05-08
Last registration	2024-01-03
Complete history	See info



Registration #1	1998-05-08	10 mi
Registration #2	2006-08-21	20.468 mi
Registration #3	2007-08-16	24.191 mi
Registration #4	2008-08-21	28.083 mi
Registration #5	2008-08-22	28.083 mi
Registration #6	2009-08-25	31.145 mi
Registration #7	2009-08-27	31.145 mi
Registration #8	2010-08-23	32.868 mi
Registration #9	2011-08-18	34.414 mi
Registration #10	2012-08-20	36.525 mi
Registration #11	2013-08-14	38.928 mi
Registration #12	2013-08-16	38.928 mi
Registration #13	2014-08-18	41.710 mi
Registration #14	2015-08-17	43.502 mi
Registration #15		11.777 es
Registration #16		11.117 es
Registration #17		11.777 es
Registration #18		11.117 es
Registration #19		11.777 es
Registration #20		11.117 es
Registration #21		11.777 es
Registration #22		11.117 es
Registration #23		11.777 es
Registration #24		11.117 es
Registration #25		11.777 es
Registration #26		11.777 es
CarCheck.co.uk		page 14/15

More info >



### Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1698 mm
Height	1393 mm
Length	4210 mm
Kerb weight	1175 kg

### Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	05778969

CarCheck.co.uk page 15/15