



Mercedes-Benz




report date: 2024-03-28

General information

| | |
|---------------------|---|
| Make | MERCEDES-BENZ |
| Model | SLK SLK250 CDI BLUEEFFICIENCY AMG SPORT |
| Colour | White |
| Year of manufacture | 2014 |
| Top speed | 151 mph |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 150 kW / 204 HP / 204 BHP |
| Max. torque | 500 Nm at 1.600 rpm |
| Engine capacity | 2.143 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 45.6 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 132 g/km |
| CO2 label | E |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-08 |
| Pictures | 21 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-22 |
| MOT pass rate | 78 % |
| MOT passed | 7 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 1 |

| | |
|------------------|------------------|
| MOT #9 | 2023-06-30 11:09 |
| MOT test number | 705006184614 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-22 |

| | |
|-----------------|------------------|
| MOT #8 | 2022-07-14 11:47 |
| MOT test number | 304995450874 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #7 | 2021-07-23 08:07 |
| MOT test number | 897250125357 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #6 | 2021-07-20 17:07 |
| MOT test number | 504771957465 |
| Result | ✗ Failed |
| MAJOR | Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) |
| Advice | Rear Inner Brake disc worn, pitted or scored, but not seriously weakened both rear inner faces (1.1.14 (a) (ii)) |
| MAJOR | Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

**MOT #5** 2021-04-16 10:17**MOT test number** 579813668407**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Front (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Wheel bearing has slight play Both (5.1.3 (a) (i))**MOT #4** 2020-03-16 17:45**MOT test number** 174056976573**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both discs worn / stepped / lipped (1.1.14 (a) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge both on limit (5.2.3 (e))**Advice** Front Inner Brake pad(s) wearing thin sunk into worn discs. unable to access/estimate (1.1.13 (a) (ii))**MOT #3** 2019-02-20 12:58**MOT test number** 194920002249**Result** ✓ Passed**Advice** Tyre size now correct on each axle**Advice** Oil leak, but not excessive engine oil on plastic under trays (8.4.1 (a) (i))**MOT #2** 2018-02-28 16:07**MOT test number** 147515819713**Result** ✓ Passed**Advice** Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)



| | |
|-----------------|---|
| MOT #1 | 2018-02-27 10:13 |
| MOT test number | 424224160522 |
| Result | ✗ Failed |
| Advice | Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1) |
| Fail | Offside Front Inner Tyre has ply or cords exposed (4.1.D.1b) |
| Advice | Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a) |



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
22 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 94 |
| MOT expiry date | 22 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------|
| Owner | From |
| Owner | From |
| Owner | From |
| Owner | From |
| Owner | From |
| Owner | From |
| Owner | From |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

| | |
|----------------------|--------------|
| Number of plates | 1 |
| Current registration | XXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2014-09-30 |
| Last registration | 2023-06-30 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-09-30 | 14 mi |
| Registration #2 | 2018-02-27 | 31.639 mi |
| Registration #3 | 2018-02-28 | 31.665 mi |
| Registration #4 | 2019-02-20 | 38.202 mi |
| Registration #5 | 2020-03-16 | 44.987 mi |
| Registration #6 | 2021-04-16 | 47.075 mi |
| Registration #7 | 2022-06-20 | 55.277 mi |
| Registration #8 | 2022-06-20 | 55.277 mi |
| Registration #9 | 2022-06-20 | 55.277 mi |
| Registration #10 | 2022-06-20 | 55.277 mi |
| Registration #11 | 2023-06-30 | 55.277 mi |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1301 mm |
| Length | 4134 mm |
| Wheel base | 2430 mm |
| Kerb weight | 1590 kg |
| Max. allowed weight | 1905 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats | 2 |
| Number of axles | 2 |
| Engine number | 65198032265025 |