



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD I-VTEC EX
Colour	Blue
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	192 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-08-28
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-02
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	12
Total items failed	4

## MOT #15 2023-06-03 15:23

MOT test number 264193013197

Result ✓ Passed

Next expiry date 2024-06-02

- Advice** Outer Tyre slightly damaged/cracking or perishing all 4 (5.2.3 (d) (ii))
- Advice** Front Shock absorbers has light misting of oil both (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear light damaged but not showing white light

## MOT #14 2022-05-31 17:34

MOT test number 805147609206

Result ✓ Passed

- Advice** Rear Outer Tyre has a cut but not deep enough to reach the ply or cords both sides (5.2.3 (d) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #13** 2022-05-31 17:34**MOT test number** 699251181758**Result** ✗ Failed**Advice** Rear Outer Tyre has a cut but not deep enough to reach the ply or cords both sides (5.2.3 (d) (i))**Pass with rectification** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #12** 2020-12-12 09:54**MOT test number** 649658197663**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**MOT #11** 2019-12-20 13:38**MOT test number** 892365845886**Result** ✓ Passed**MOT #10** 2018-12-10 15:47**MOT test number** 448159387500**Result** ✓ Passed**MOT #9** 2017-12-06 13:01**MOT test number** 275487805855**Result** ✓ Passed

**MOT #8** 2017-12-06 13:01**MOT test number** 654290662079**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #7** 2016-12-07 12:04**MOT test number** 879794993825**Result** ✓ Passed**MOT #6** 2016-12-07 12:04**MOT test number** 635303498052**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**MOT #5** 2016-01-05 17:54**MOT test number** 772674851636**Result** ✓ Passed**MOT #4** 2016-01-05 17:54**MOT test number** 108518661938**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2015-03-17 09:27**MOT test number** 847896375056**Result** ✓ Passed**Notice** Both rear tyres have slight surface cracks



MOT #2	2014-04-04 16:34
MOT test number	147904494031
Result	✓ Passed

MOT #1	2013-09-13 15:28
MOT test number	685156253218
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
2 June 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	217
<b>MOT expiry date</b>	2 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-15
Last registration	2023-06-03
Complete history	<a href="#">See info</a>



Registration #1	2010-09-15	14 mi
Registration #2	2013-09-13	21.403 mi
Registration #3	2014-04-04	23.560 mi
Registration #4	2015-03-17	32.149 mi
Registration #5	2016-01-05	38.392 mi
Registration #6	2016-01-05	38.392 mi
Registration #7	2016-12-07	42.768 mi
Registration #8	2016-12-07	42.768 mi
Registration #9	2017-12-06	47.161 mi
Registration #10	2019-06-20	55.377 mi
Registration #11	2019-06-20	55.377 mi
Registration #12	2019-06-20	55.377 mi
Registration #13	2019-06-20	55.377 mi
Registration #14	2019-06-20	55.377 mi
Registration #15	2019-06-20	55.377 mi
Registration #16	2019-06-20	55.377 mi
Registration #17	2019-06-20	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4726 mm
Wheel base	2705 mm
Kerb weight	1414 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	R20A33100699