



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX TSI
Colour	Black
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	200 Nm at 1.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg



**MOT history****MOT #14** 2020-03-12 08:34**MOT test number** 646159827648**Result** ✓ Passed**Next expiry date** 2021-03-19**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))**MOT #13** 2019-03-18 09:29**MOT test number** 424695406945**Result** ✓ Passed**MOT #12** 2018-03-20 08:38**MOT test number** 109924325005**Result** ✓ Passed**MOT #11** 2018-03-19 17:05**MOT test number** 776668287362**Result** ✗ Failed**Fail** Nearside Ball joint has excessive play (2.2.B.1f)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #10** 2017-03-07 15:00**MOT test number** 767240982524**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2017-03-07 15:00**MOT test number** 566899280524**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #8** 2016-02-24 14:02**MOT test number** 391239957314**Result** ✓ Passed**MOT #7** 2015-01-16 16:02**MOT test number** 498896815019**Result** ✓ Passed**Notice** Nearside rear seat slightly loose

**MOT #6** 2015-01-16 11:52**MOT test number** 498256815073**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Nearside rear seat slightly loose**MOT #5** 2014-01-06 10:33**MOT test number** 138976104416**Result** ✓ Passed**MOT #4** 2013-03-05 14:17**MOT test number** 679264263090**Result** ✓ Passed**MOT #3** 2013-01-24 15:49**MOT test number** 275454223071**Result** ✗ Failed**Fail** Nearside Front Side repeater insecure (1.4.A.2b)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #2	2012-02-03 16:28
MOT test number	138114732040
Result	✓ Passed
<div>NoticeOil leak</div>	

MOT #1	2011-03-26 09:50
MOT test number	738835181011
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SL08SOH
Plate since	2019-06-29
Current registration	 SL08SOH
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-03-28
Last registration	2020-03-12
Complete history	See info



Registration #1	2008-03-28	28 mi
Registration #2	2011-03-26	21.095 mi
Registration #3	2012-02-03	27.832 mi
Registration #4	2013-01-24	35.084 mi
Registration #5	2013-03-05	33.216 mi
Registration #6	2014-01-06	32.262 mi
Registration #7	2015-01-16	47.512 mi
Registration #8	2015-01-16	47.518 mi
Registration #9	2015-01-16	47.518 mi
Registration #10	2015-01-16	47.518 mi
Registration #11	2015-01-16	47.518 mi
Registration #12	2015-01-16	47.518 mi
Registration #13	2015-01-16	47.518 mi
Registration #14	2015-01-16	47.518 mi
Registration #15	2015-01-16	47.518 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles

2

Engine number

CAX 016127