



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VAUXHALL |
| Model | ZAFIRA SRI NAV |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 122 mph |
| 0 - 60 mph | 10.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 138 BHP |
| Max. torque | 200 Nm at 1.850 rpm |
| Engine capacity | 1.364 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 33.2 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 41.5 mpg |
| CO2 emission | 156 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-05 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-26 |
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 5 |
| Total items failed | 5 |

| | |
|------------------|------------------|
| MOT #6 | 2024-02-27 12:35 |
| MOT test number | 871450946831 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-26 |

| | |
|-----------------|--|
| MOT #5 | 2024-02-27 08:52 |
| MOT test number | 789895889773 |
| Result | ✗ Failed |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Fail | Nearside Front Windscreen wiper does not clear the windscreen effectively flat blades (3.4 (b) (ii)) |
| Fail | Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |

| | |
|-----------------|--|
| MOT #4 | 2023-02-20 13:12 |
| MOT test number | 438063869003 |
| Result | ✓ Passed |
| Advice | Offside Front Macpherson strut mounting damaged but not seriously weakened slight play in top mount. (5.3.3 (b) (i)) |
| Minor | Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) |

**MOT #3** 2022-02-24 15:42**MOT test number** 131850083876**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #2** 2022-02-24 11:43**MOT test number** 635220461968**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #1** 2021-02-15 16:35**MOT test number** 264430266526**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
26 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 277 |
| MOT expiry date | 26 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | I |
| First licence fee (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  VAUXH |
| Plate since | 2024-03-29 |
| Current registration |  VAUXH |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 8 |
| First mileage registration | 2018-05-30 |
| Last registration | 2024-02-27 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-05-30 | 17 mi |
| Registration #2 | 2019-05-29 | 25.277 mi |
| Registration #3 | 2021-02-15 | 27.627 mi |
| Registration #4 | 2022-02-24 | 39.557 mi |
| Registration #5 | 2023-05-29 | 39.557 mi |
| Registration #6 | 2023-05-29 | 39.557 mi |
| Registration #7 | 2023-05-29 | 39.557 mi |
| Registration #8 | 2024-02-27 | 39.557 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2099 mm |
| Height | 1685 mm |
| Length | 4658 mm |
| Wheel base | 2760 mm |
| Kerb weight | 1538 kg |
| Max. allowed weight | 2310 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 58 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Engine number | B14NET -19TA0727LUJ |