



report date: 2024-03-28

General information

Make	MAZDA
Model	5 TS2
Colour	Grey
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	193 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2

Date	2022-06-25
Pictures	14
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-11-28
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	55
Total items failed	14

MOT #16	2023-11-16 11:45
MOT test number	810083674586
Result	✓ Passed
Next expiry date	2024-11-28

MOT #15	2022-11-29 16:51
MOT test number	450516667189
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #14**

2022-11-28 12:48

MOT test number

330101700496

Result**✗ Failed**

- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #13

2022-01-17 13:37

MOT test number

758985625810

Result**✓ Passed**

- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #12**

2022-01-15 12:30

MOT test number

434525056031

Result

✗ Failed

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #11

2021-01-20 11:46

MOT test number

640498119385

Result

✓ Passed

- Advice** Slight play in front joints
- Advice** Brake pad(s) wearing thin Front and rear (1.1.13 (a) (ii))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Front and rear (1.1.14 (a) (ii))

MOT #10

2021-01-19 19:03

MOT test number

482470973635

Result

✗ Failed

- Advice** Brake pad(s) wearing thin Front and rear (1.1.13 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Slight play in front joints
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Front and rear (1.1.14 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #9** 2018-11-30 10:28**MOT test number** 121199416299**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt two in rear**Advice** Rear boot seats folded down at time of test preventing full inspection of rear seat belts**MOT #8** 2018-11-22 11:07**MOT test number** 170817559528**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt two in rear**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear boot seats folded down at time of test preventing full inspection of rear seat belts**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Front Position lamp not working (4.2.1 (a))**MOT #7** 2017-11-25 10:34**MOT test number** 631932069777**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2016-11-25 12:53**MOT test number** 974680785462**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #5** 2015-11-10 16:30**MOT test number** 493648975582**Result** ✓ Passed**Advice** Engine covers**Advice** Rear seats missing at time of test**Advice** Under trays**MOT #4** 2014-11-13 12:50**MOT test number** 236687814335**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Notice** N/S/R AND O/S/R TYRES inner tread low and feathering**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #3** 2014-11-06 08:32**MOT test number** 468650814444**Result** ✗ Failed

- Advice** Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Nearside Rear rear brake recording little or no effort (3.7.B.5a)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Plastic trims fitted to both outer sills.

MOT #2 2014-11-05 14:07**MOT test number** 509339704310**Result** ✗ Failed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** N/S/R AND O/S/R TYRES inner tread low and feathering
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)



MOT #1	2013-11-20 09:38
MOT test number	639724423381
Result	✓ Passed
Notice	Plastic trims fitted to both outer sils.
Notice	O/s/f. wiper blade split.
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Vehicle's internal headlight adjuster altered to recheck lights



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
28 November 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-11-27
Last registration	2023-11-16
Complete history	See info



Registration #1	2010-11-27	29 mi
Registration #2	2013-11-20	23.409 mi
Registration #3	2014-11-05	30.442 mi
Registration #4	2014-11-06	30.455 mi
Registration #5	2014-11-13	30.587 mi
Registration #6	2015-11-10	38.454 mi
Registration #7	2016-11-25	51.339 mi
Registration #8	2017-11-25	67.471 mi
Registration #9	2018-11-22	85.535 mi
Registration #10	2018-11-30	85.842 mi
Registration #11	2019-11-20	95.377 mi
Registration #12	2019-11-20	95.377 mi
Registration #13	2019-11-20	95.377 mi
Registration #14	2019-11-20	95.377 mi
Registration #15	2019-11-20	95.377 mi
Registration #16	2019-11-20	95.377 mi
Registration #17	2019-11-20	95.377 mi
Registration #18	2019-11-20	95.377 mi
Registration #19	2019-11-20	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1435 kg
Max. allowed weight	1955 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 20316606