





report date: 2024-03-28

General information

Make	ТОУОТА
Model	AVENSIS D-CAT TR
Colour	Blue
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date 2021-08-30

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



	_			
MO	1	hic	to	r\/
				ıv.
				. ,

Advice

MOT expiry date	2024-09-17
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	44
Total items failed	8

MOT #18	2023-09-07 12:05
MOT test number	663103328345
Result	✓ Passed
Next expiry date	2024-09-17

MOT #17	2022-09-10 09:44
MOT test number	592902451269
Result	✓ Passed

MOT #16	2021-09-17 15:41
MOT test	number 812193099671
Result	✓ Passed
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 3/15



× Failed

MOT #15 2021-09-17 10:44

MOT test number 552495891178

Result

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #14 2020-09-18 13:45

MOT test number 515963631948

Result \(\sqrt{Passed} \)

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (Worn & Lipped) (1.1.14 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (Worn & Lipped) (1.1.14 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

CarCheck.co.uk page 4/15



MOT #13 2020-09-15 15:18

MOT test number 988712829321

Result X Failed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (Worn & Lipped) (1.1.14 (a) (ii))

Fail Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (Holed & leaking) (5.3.4 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (replacement advised) (5.2.3 (e))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (Void of tread on the inner portion of the tyre. Borderline pass. Replacement recommended) (5.2.3 (e))

Advice Nearside Rear Nail in tyre (seven nails in tyre)

Advice Front Brake pad(s) wearing thin (Very low Borderline pass. Replacement recommended) (1.1.13 (a) (ii))

Fail Offside Side repeater not working (4.4.1 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (Worn & Lipped) (1.1.14 (a) (ii))

Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (Holed & Leaking) (5.3.4 (b) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (Void of tread on the inner portion of the tyre. Borderline pass. Replacement recommended) (5.2.3 (e))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Nail in tyre

Advice Offside Front Tyre worn close to legal limit/worn on edge (Void of tread on the inner portion of the tyre. Borderline pass.Replacement recommended) (5.2.3 (e))

MOT #12 2019-04-09 15:02

MOT test number 431721376349

Advice Advise Engine bay covers & Under trays fitted obscuring some testable components.

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 5/15



MOT #11 2018-03-14 12:29

MOT test number 933133471985

Result ✓ Passed

Advice Nearside Front Brake pad(s) wearing thin Borderline pass) (Replacement recommended (3.5.1g)

Advice Rear Inner Brake pad(s) wearing thin Advise Rear brake pads look to be wearing thin But are not clearly visible during test) (Replacement advised (3.5.1g)

Advice Offside Front Brake pad(s) wearing thin Borderline pass) (Replacement recvommended (3.5.1g)

Advice Front brake disc worn, pitted or scored, but not seriously weakened Advised Both Front brake discs are heavily worn & lipped,possibly below manufacturers recommended minimum wear limits) (
Replacement Advised (3.5.1i)

Advice Advise Engine bay covers & under trays fitted obscuring some testable components

MOT #10 2017-03-27 08:21

MOT test number 542060187711

Result \rightarrow Passed

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Advise Engine bay covers & under trays fitted obscuring some testable components

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #9 2016-09-23 15:02

MOT test number 793395050302

Result / Passed

MOT #8 2016-04-22 14:20

MOT test number 322987008416

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/15



MOT #7 2015-04-24 16:12

MOT test number 208504115404

Result
✓ Passed

MOT #6 2015-04-24 16:12

MOT test number 767074515196

Result X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #5 2014-05-01 16:56

MOT test number 179101124125

Notice Nsr tyre has been run flat light damage to outer wall visable

MOT #4 2014-03-04 13:02

MOT test number 416273264030

Result

Passed

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT #3 2013-02-19 16:39

MOT test number 355020753004

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 7/15



MOT #2 2013-02-15 15:01

MOT test number 198296143483

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #1 2012-02-21 09:34

MOT test number 496222152065

Notice N/s/r tyre wearing on edges and tread depth getting low

Notice O/s/f tyre wearing on inner edge and tread depth getting low

Notice N/s/f tyre wearing on inner edge and tread depth close to legal limit (Advise attention)

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	17 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-18
Last registration	2023-09-07
Complete history	See info



Registration #1	2009-09-18	19 mi
Registration #2	2012-02-21	30.967 mi
Registration #3	2013-02-15	39.887 mi
Registration #4	2013-02-19	39.887 mi
Registration #5	2014-03-04	46.463 mi
Registration #6	2014-05-01	47.648 mi
Registration #7	2015-04-24	51.275 mi
Registration #8	2016-04-22	53.860 mi
Registration #9	2016-09-23	55.006 mi
Registration #10	2017-03-27	62.513 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		0.77 44
Registration #19		11.777 es

More info >

CarCheck.co.uk page 14/15



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1480 mm
Length	4765 mm
Wheel base	2700 mm
Kerb weight	1650 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 15/15

Number of axles 2

Engine number 2AH5477471